

Damage Report for THOR 5th ED2634


12/30/19

THOR 5th

Strain Relief zip tie loosened up and the T1 Accelerometers cables were pulled tight.



Right Clavicle Bolt tore through the Shoulder Cover.



Right lower IRTRACC must be further examined.



Impact marks on Right Arm.




Multiple cuts and tears on Abdomen Flesh.



Broken Grounding Strap which connects the Pelvis to the Thorax.




T8 Accels seem to have been pulled.




Damage on Lower Left IRTRACC.




Damage done all along the Posterior Inferior edge of the shoulder covers.




Cuts to the Flesh on the Right Lower Arm.



Tear on the Left Upper Medial Arm.



In the Left Upper ITRACC, the cable for the Y-pot was pinched in between the Spine and the Spine-Shoulder Coupler Assembly. This was not like this Pre-test.



Upper Left ITRACC Z-pot was destroyed.



Rubber washer on Upper Scapula had damage.



Thank you,

Mike Godfrey DML