


Damage Report for LODC 3 & THOR 5th ED2634

12/17/19

LODC

This is the Spine adjustment. Looks like the metal is bowed out from metal to metal impact. This is the nut that holds the spines in place.



Posterior neck tear seemed to be bigger.



Left shoulder became free from Chest.




THOR 5th

Strain Relief zip tie loosened up and the T1 Accelerometers cables were pulled tight.



Right Clavicle Bolt tore through the Shoulder Cover.



Right lower IRTRACC has to be further examined.




Impact marks on Right Arm.




Multiple cuts and tears on Abdomen Flesh.



Broken Grounding Strap which connects the Pelvis to the Thorax.




T8 Accels seem to have been pulled.



Damage on Lower Left ITRACC.



Damage done all along the Posterior Inferior edge of the shoulder covers.



I will add to this document as I assess these two dummies closer.

Thank you,

Mike Godfrey DML