

REPORT NUMBER: TWG-CAL07-03


NEW CAR ASSESSMENT PROGRAM (NCAP)
SIDE AIRBAG OUT-OF-POSITION INJURY TESTING

2007 HONDA ELEMENT
FOUR DOOR MULTIPURPOSE VEHICLE

NHTSA NUMBER: M75306TWG2

CALSPAN CORPORATION TEST NUMBER: 8642-TWG-25

CALSPAN CORPORATION
TRANSPORTATION SCIENCES CENTER
P.O. BOX 400
BUFFALO, NEW YORK 14225



May 15, 2007

FINAL REPORT

U. S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
Rulemaking
Office of Crashworthiness Standards
Mail Code: NVS-111
400 Seventh Street, SW, Room No. 5313
Washington, DC 20590

This Final Test Report was prepared for the U.S. Department of Transportation, National Highway Traffic Safety Administration, under Contract No. DTNH22-03-D-22005. This document is disseminated under the sponsorship of the U.S. Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

Prepared By:

Patrick G. MacDiarmid, Jr., Project Engineer

Approved By:

Michael J. Kilgallon, Program Manager
Transportation Sciences Center

Approval Date:

FINAL REPORT ACCEPTANCE BY:

Accepted By:

Acceptance Date:

TECHNICAL REPORT STANDARD TITLE PAGE							
1. Report No. TWG-CAL07-03		2. Government Accession No.		3. Recipient's Catalog No.			
4. Title and Subtitle Final Report NHTSA No.: M75306TWG2				5. Report Date May 15, 2007			
				6. Performing Organization Code CAL			
7. Author(s) Patrick G. MacDiarmid, Jr., Project Engineer David J. Travale, Program Manager				8. Performing Organization Report No. 8642-TWG-25			
9. Performing Organization Name and Address Calspan Corporation Transportation Sciences Center P.O. Box 400 Buffalo, New York 14225				10. Work Unit No.			
				11. Contract or Grant No. DTNH22-03-D-22005			
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration Office of Crashworthiness Standards Mail Code: NVS-111 400 Seventh SW, Room 5313 Washington, D.C. 20590				13. Type of Report and Period Covered Final Report, June 8, 2006			
				14. Sponsoring Agency Code NVS-111			
15. Supplementary Notes							
16. Abstract This side impact out-of-position test was performed in conjunction with a New Car Assessment Program (NCAP). This test was conducted at the Calspan Corporation Crash Test Facility in Buffalo, New York, on May 15, 2007.							
Injury Summary							
HIC15	HIC36	Clip (g's)	Chest Displacement (mm)	NIJ NTF	NIJ NTE	NIJ NCF	NIJ NCE
32.5	33.0	5.4	-0.3	0.12	0.25	0.10	0.25
17. Key Words New Car Assessment Program (NCAP) Side Airbag Out-of-Position				18. Distribution Statement Copies of this report are available from: National Highway Traffic Safety Administration Technical Reference Division Room 5111 (NAD-52) 400 Seventh St., S.W. Washington, D.C. 20590 Telephone No. (202) 366-4946 ATTN: Robert Hornicle			
19. Security Classification of Report UNCLASSIFIED		20. Security Classification of Page UNCLASSIFIED		21. No. of Pages 30		22. Price	

TABLE OF CONTENTS

<u>Section</u>		<u>Page No.</u>
1	PURPOSE AND SUMMARY OF TEST	1-1
2	DATA SHEETS	2-1
	Data Sheet 1 – Test Summary	2-1
	Data Sheet 2 – Vehicle Parameter Data	2-2
	Data Sheet 3 – Dummy Positioning in Vehicle	2-3
	Data Sheet 4 – Dummy Injury Criteria Values	2-4
A	PHOTOGRAPHS	A-1
B	CHILD DUMMY RESPONSE DATA TRACES	B-1
C	TEST EQUIPMENT LIST AND CALIBRATION INFORMATION	C-1

TABLE OF PHOTOGRAPHS

<u>Figure</u>	<u>Photograph Title</u>	<u>Page</u>
Figure A- 1	PRE-TEST VEHICLE LEFT SIDE VIEW	A- 3
Figure A- 2	POST-TEST VEHICLE LEFT SIDE VIEW	A- 3
Figure A- 3	VEHICLE CERTIFICATION PLACARD	A- 4
Figure A- 4	VEHICLE TIRE PLACARD	A- 4
Figure A- 5	PRE-TEST DUMMY FRONTAL VIEW	A- 5
Figure A- 6	POST-TEST DUMMY FRONTAL VIEW	A- 5
Figure A- 7	PRE-TEST LEFT SIDE OF DUMMY VIEW	A- 6
Figure A- 8	POST-TEST LEFT SIDE OF DUMMY VIEW	A- 6
Figure A- 9	PRE-TEST RIGHT SIDE OF DUMMY VIEW	A- 7
Figure A- 10	POST-TEST RIGHT SIDE OF DUMMY VIEW	A- 7

TABLE OF DATA PLOTS

PLOT	PLOT NAME[UNITS, CHANNEL FILTER CLASS]	PAGE
1	P2 Head x [g, CFC_1000]	B-3
2	P2 Head y [g, CFC_1000]	B-3
3	P2 Head z [g, CFC_1000]	B-3
4	P2 Head Resultant [g, CFC_1000]	B-3
5	P2 Upper Neck Fx [N, CFC_1000]	B-4
6	P2 Upper Neck Fy [N, CFC_1000]	B-4
7	P2 Upper Neck Fz [N, CFC_1000]	B-4
8	P2 Upper Neck F Resultant [N, CFC_1000]	B-4
9	P2 Upper Neck Mx [N-m, CFC_600]	B-5
10	P2 Upper Neck My [N-m, CFC_600]	B-5
11	P2 Upper Neck Mz [N-m, CFC_600]	B-5
12	P2 Upper Neck M Resultant [N-m, CFC_600]	B-5
13	P2 Chest x [g, CFC_180]	B-6
14	P2 Chest y [g, CFC_180]	B-6
15	P2 Chest z [g, CFC_180]	B-6
16	P2 Chest Resultant [g, CFC_180]	B-6
17	P2 Chest Compression [mm, CFC_600]	B-7
18	P2 Upper Sternum Ax [g, CFC_180]	B-7
19	P2 Lower Sternum Ax [g, CFC_180]	B-7
20	P2 Pelvic x [g, CFC_1000]	B-8
21	P2 Pelvic y [g, CFC_1000]	B-8
22	P2 Pelvic z [g, CFC_1000]	B-8
23	P2 Pelvic Resultant [g, CFC_1000]	B-8
24	P2 Left Femur Fz [N, CFC_600]	B-9
25	P2 Right Femur Fz [N, CFC_600]	B-9

SECTION 1

PURPOSE AND SUMMARY OF TEST M75306TWG2

1.1 PURPOSE

The purpose of this test was to obtain data in a static out-of-position side impact. These data constitute part of the general consumer information collected by the New Car Assessment Program (NCAP) sponsored by the National Highway Traffic Safety Administration (NHTSA) under contract No. DTNH22-03-D-22005.

1.2 SUMMARY

The effects of a side rail mounted curtain airbag deployment in a 2007 Honda Element with an out-of-position six-year-old child were evaluated. The test was performed by Calspan Corporation on May 15, 2007. Pre-and post-test photographs of the vehicle and dummy can be found in Appendix A.

One high-speed digital camera was used to document the side airbag deployment event. The camera was placed perpendicular to the right-front seat centerline as capture the deployment event. The recorded image rate is 1000 frames per second.

One part 572, Hybrid III six-year-old child anthropomorphic test device (ATD) was placed in the right front seat situated in the inboard facing position according to dummy placement instructions specified in the Recommended Procedures for Evaluating Occupant Injury Risk from Deploying Side Airbags as prepared by the Side Airbag Out-of-Position Injury Technical Working Group (TWG).

The child dummy was instrumented with head, chest, upper and lower sternum and pelvic triaxial accelerometers. In addition an upper six axial neck force and moment load cell sensors and left and right femur load cell sensors was utilized.

Twenty channels of data were recorded using an on-board data acquisition system. Appendix A contains photographs. Appendix B contains dummy response data traces. Appendix C contains the Instrumentation Data Channel assignments.

The Hybrid III six-year-old child dummy's visible contact points were as follows: The side curtain airbag to the top of the head.

The six-year old child dummy was placed with its arms hanging at its sides on the foam block facing inboard with its legs extended. The seat track was adjusted to 240 mm rearward of full forward to minimize the vertical distance between the dummy's head and the roof-rail module and to maximize the cushion to head interaction. While keeping the head in neutral orientation, the dummy's pelvis was moved outboard until the dummy's back contacted the door trim panel armrest and the center of gravity of the head was centered in the deployment trajectory of the airbag. The dummy was then moved to maintain the vertical plane through the centerline of the dummy's shoulder bolts parallel to the vehicle centerline. The dummy's arms were then bent at the elbow until the fingers contacted the booster seat. This orientation complies with section 3.3.5.1 of the TWG Recommended Procedures for Evaluating Occupant Injury Risk from Deploying Side Airbags as defined by Lund, et al and the Technical Working Group First Revision dated July, 2003.

SECTION 2

DATA SHEET NO. 1

TEST SUMMARY

TEST CONFIGURATION INFORMATION:

	TEST DATA	DESCRIPTION
Seating Position:	P2	Right Front Seating Position
Test:	3.3.5.1*	Inboard facing Hybrid-III six-year-old child dummy on booster block
Airbag:	Side Rail	Side curtain airbag.
Booster Block	300mm x 450 mm x 75 mm	Block consisted of HD36 foam with a density of 44.8 g/L
ATD Type/Serial No.:	P572N/186	Hybrid III six-year-old child dummy

*- Procedure as defined by Lund, et al and the Technical Working Group dated July, 2003

<u>Number of Data Channels</u>	20	
<u>Number of Cameras:</u>	0	<u>Real Time</u>
	1	<u>High Speed Digital</u>
	0	<u>High Speed Film</u>

VISIBLE DUMMY CONTACT POINTS

Head Contact:	The back (occipital) of the head by the side curtain.
Upper Torso Contact:	None
Lower Torso Contact:	None
Left Knee Contact:	None
Right Knee Contact:	None

DATA SHEET NO. 2
VEHICLE PARAMETER DATA

Test Vehicle:	2007 Honda Element‡	NHTSA No.	M75306TWG2
Test Program:	NCAP Side Impact	Test Date:	May 15, 2006

TEST VEHICLE INFORMATION AND VEHICLE OPTIONS

Make	Honda of America MFG.	Driver Front Airbag	Yes
Model	Element	Driver Side Curtain Airbag	Yes
Body Style	MPV	Driver Side Torso Airbag	Yes
NHTSA No.	M75306	Driver Pretensioners	Yes
VIN	5J6YH28747L001440‡	Driver Load Limiters	Yes
Color	RED	Driver Power Seats	No
Engine Disp.(L)	2.4	Rear Pass. Side Curtain Airbag	Yes
Engine Cylinders	4	Rear Pass. Side Torso Airbag	No
Engine Placement	Lateral	Rear Pass. Pretensioners	No
Transmission Type	Automatic	Rear Pass. Load Limiters	No
Transmission Speeds	5	Rear Pass. Power Seats	NA
Final Drive	4 Wheel	Tilt Wheel	Yes
Air Conditioning	Yes	Anti-lock Brakes	Yes
Power Steering	Yes	Traction Control	Yes/No
Power Brakes	Yes	Power Windows	Yes
Delivery Date	9/28/06	Power Door Locks	Yes
Odometer Reading (km)	18	Automatic Door Locks (ADL)	No
Dealer	LIA HONDA	Owner's Manual Details Instructions on Disabling ADLs	NA

DATA FROM CERTIFICATION LABEL

Manufactured By	Honda of America MFG.	GVWR (kg)	2020
Date of Manufacture	09/06	GAWR Front (kg)	1045
		GAWR Rear (kg)	1000

VEHICLE CAPACITY DATA

Measured Parameter	Front	Rear	Third	Total
Type of Seats	Bucket	Bucket/Bench/Split Bench		
Number Of Occupants	2	2		4
Capacity Wt. (VCW) (kg)				308
Cargo Wt. (RCLW) (kg)				35.8

‡ This vehicle had previously been tested in an NCAP side impact on October 24, 2006.

DATA SHEET NO. 3

CHILD DUMMY POSITIONING IN VEHICLE

NHTSA No. M75306TWG2

Measurement		Value
Total Fore/Aft Travel (mm)		240
Test Distance Rearward of Full-Forward (mm)		140
Total Fore/Aft Travel (Detents)		25
Placed in Position #		14
Seat Back Angle	SA (°)	17°
Airbag Module Width	AMW (mm)	-
Airbag Width	ABW (mm)	-
Airbag Module Length	AML (mm)	-
Airbag Length	ABL (mm)	-
Top of Airbag Module to Head/Neck Junction	AN (mm)	-
Head CG to Door Panel/Window	HD (mm)	146
Head to Seat Back Centerline	HSC (mm)	275
Head to B-Pillar (cg)	HB (mm)	80
Head to Roof, Z (top of the head)	HZ (mm)	264
Head to Header	HHH (mm)	-
Chest to Dash	CD (mm)	653
Chest to Seatback	CS (mm)	247
Right Arm to Seat Back Centerline	RACL (mm)	-
Right Arm to Seat Back Centerline	RACL (°)	-
Left Arm to Seat Back Centerline	LACL (mm)	-
Left Arm to Seat Back Centerline	LACL (°)	-
Right Arm to Door Panel	RA (mm)	0
Left Arm to Door Panel	LA (mm)	0
Knee to Knee	KK (mm)	165
Toe to Toe	TT (mm)	80
Right Knee to Seat Cushion Centerline	KSCR (mm)	-
Left Knee to Seat Cushion Centerline	KSCL (mm)	-
Right Toe to Seat Cushion Centerline	TSCR (mm)	-
Left Toe to Seat Cushion Centerline	TSCL (mm)	-
Nose to Dash	ND (mm)	-
Nose to Seatback	NS (mm)	-
Nose to Header	NR (mm)	-
Foam Block Depth	(mm)	300
Foam Block Width	(mm)	450
Foam Block Thickness	(mm)	75
HD36 foam density	(g/L)	44.8

DATA SHEET 4

CHILD DUMMY INJURY CRITERIA VALUES

NHTSA No. M75306TWG2

		MAXIMUM VALUE			
		Position #2			
DESCRIPTION	Unit	Maximum	Time (ms)	Minimum	Time (ms)
Head X	g	26.6	19.0	-4.6	43.3
Head Y	g	6.1	21.9	-20.8	13.8
Head Z	g	10.8	21.4	-7.7	17.8
Head Resultant	g	29.4	13.8	0.0	-19.2
Upper Neck Fx	N	6.5	11.5	-309.7	32.4
Upper Neck Fy	N	118.3	16.8	-51.7	25.6
Upper Neck Fz	N	253.2	22.0	-445.6	17.4
Upper Neck F Resultant	N	486.5	17.3	0.1	-11.8
Upper Neck Mx	N-m	6.0	25.8	-4.5	38.4
Upper Neck My	N-m	8.1	52.2	-10.4	21.6
Upper Neck Mz	N-m	3.8	35.8	-1.7	17.8
Upper Neck M Resultant	N-m	10.7	21.6	0.0	1.7
Chest X	g	6.4	22.0	-1.4	196.7
Chest Y	g	1.7	26.3	-2.6	19.9
Chest Z	g	4.1	17.6	-2.7	21.6
Chest Resultant	g	7.0	21.8	0.0	-10.6
Chest Displacement	mm	1.0	115.3	-0.3	26.3
Upper Sternum Ax	g	7.6	23.5	-2.2	51.5
Lower Sternum Ax	g	6.4	25.8	-2.6	19.7
Pelvic X	g	1.9	63.1	-7.9	47.7
Pelvic Y	g	3.0	47.6	-1.1	10.7
Pelvic Z	g	4.7	18.5	-5.7	21.9
Pelvic Resultant	g	9.3	47.7	0.0	-7.6
Left Femur	N	53.6	50.1	-72.2	199.9
Right Femur	N	30.2	23.2	-52.6	192.8

DATA SHEET 4

CHILD DUMMY INJURY CRITERIA VALUES (CONTINUED)

NHTSA No. M75306TWG2

	HEAD INJURY CRITERIA (HIC)							
	HIC15				HIC36			
	HIC	t ₁ (msec)	t ₂ (msec)	Average Acceleration t ₁ to t ₂	HIC	t ₁ (msec)	t ₂ (msec)	Average Acceleration t ₁ to t ₂
Position #2 – Right Front	32.5	12.9	27.9	21.4	33.0	12.7	29.5	20.6

	CLIP SUMMARY*			
	CLIP (g's)	t ₁ (msec)	t ₂ (msec)	CSI
Position #2 – Right Front	5.4	20.7	23.7	1.5

* The maximum chest resultant acceleration is defined as the maximum acceleration which exceeds 0.003 seconds in duration.

Position 2 Neck Injury Summary (HIII 6 year old – Out of Position)

Nij V10	Nij	Time (ms)	Z Force (N)	X Force (N)	Y Moment (N-m)
Ntf	0.12	55.3	70.9	-68.3	8.9
Nte	0.25	22.0	248.7	-247.7	-6.0
Ncf	0.10	49.9	-31.5	-77.0	8.6
Nce	0.25	18.7	-350.4	-181.3	-4.5

Peak Tension (CFC1000) 253.2 N

Peak Compression (CFC1000) -445.6 N

Critical Values

Nij Intercepts				Peak Limits	
Tension (CVt)	2880 N	Extension (mCVe)	37 N-m	Tension	1890 N
Compression (CVc)	2880 N	Flexion (mCVf)	93 N-m	Compression	-1820 N

Condyle Offset -0.01778

APPENDIX A

PHOTOGRAPHS

TABLE OF PHOTOGRAPHS

<u>Figure</u>	<u>Photograph Title</u>	<u>Page</u>
Figure A- 1	PRE-TEST VEHICLE LEFT SIDE VIEW	A- 3
Figure A- 2	POST-TEST VEHICLE LEFT SIDE VIEW	A- 3
Figure A- 3	VEHICLE CERTIFICATION PLACARD	A- 4
Figure A- 4	VEHICLE TIRE PLACARD	A- 4
Figure A- 5	PRE-TEST DUMMY FRONTAL VIEW	A- 5
Figure A- 6	POST-TEST DUMMY FRONTAL VIEW	A- 5
Figure A- 7	PRE-TEST LEFT SIDE OF DUMMY VIEW	A- 6
Figure A- 8	POST-TEST LEFT SIDE OF DUMMY VIEW	A- 6
Figure A- 9	PRE-TEST RIGHT SIDE OF DUMMY VIEW	A- 7
Figure A- 10	POST-TEST RIGHT SIDE OF DUMMY VIEW	A- 7



Figure A-1: Pre-Test Vehicle Left Side View



Figure A-2: Post-Test Vehicle Left Side View



Figure A-3: Vehicle Certification Placard



Figure A-4: Vehicle Tire Placard



Figure A-5: Pre-Test Dummy Frontal View



Figure A-6: Post-Test Dummy Frontal View




Figure A-7: Pre-Test Left Side of Dummy View



Figure A-8: Post-Test Left Side of Dummy View



Figure A-9: Pre-Test Right Side of Dummy View



Figure A-10: Post-Test Right Side of Dummy View





APPENDIX B

CHILD DUMMY RESPONSE DATA TRACES





TABLE OF DATA PLOTS

PLOT	PLOT NAME[UNITS, CHANNEL FILTER CLASS]	PAGE
1	P2 Head x [g, CFC_1000]	B-3
2	P2 Head y [g, CFC_1000]	B-3
3	P2 Head z [g, CFC_1000]	B-3
4	P2 Head Resultant [g, CFC_1000]	B-3
5	P2 Upper Neck Fx [N, CFC_1000]	B-4
6	P2 Upper Neck Fy [N, CFC_1000]	B-4
7	P2 Upper Neck Fz [N, CFC_1000]	B-4
8	P2 Upper Neck F Resultant [N, CFC_1000]	B-4
9	P2 Upper Neck Mx [N-m, CFC_600]	B-5
10	P2 Upper Neck My [N-m, CFC_600]	B-5
11	P2 Upper Neck Mz [N-m, CFC_600]	B-5
12	P2 Upper Neck M Resultant [N-m, CFC_600]	B-5
13	P2 Chest x [g, CFC_180]	B-6
14	P2 Chest y [g, CFC_180]	B-6
15	P2 Chest z [g, CFC_180]	B-6
16	P2 Chest Resultant [g, CFC_180]	B-6
17	P2 Chest Compression [mm, CFC_600]	B-7
18	P2 Upper Sternum Ax [g, CFC_180]	B-7
19	P2 Lower Sternum Ax [g, CFC_180]	B-7
20	P2 Pelvic x [g, CFC_1000]	B-8
21	P2 Pelvic y [g, CFC_1000]	B-8
22	P2 Pelvic z [g, CFC_1000]	B-8
23	P2 Pelvic Resultant [g, CFC_1000]	B-8
24	P2 Left Femur Fz [N, CFC_600]	B-9
25	P2 Right Femur Fz [N, CFC_600]	B-9





2007 TWG Test 3 2007 Honda Element M75306TWG2 - May 15, 2007







2007 TWG Test 3 2007 Honda Element M75306TWG2 - May 15, 2007






2007 TWG Test 3 2007 Honda Element M75306TWG2 - May 15, 2007







2007 TWG Test 3 2007 Honda Element M75306TWG2 - May 15, 2007



2007 TWG Test 3 2007 Honda Element
M75306TWG2 - May 15, 2007





2007 TWG Test 3 2007 Honda Element M75306TWG2 - May 15, 2007



2007 TWG Test 3 2007 Honda Element

M75306TWG2 - May 15, 2007



APPENDIX C

TEST EQUIPMENT LIST AND CALIBRATION INFORMATION

TEST EQUIPMENT LIST AND CALIBRATION INFORMATION

P572N INSTRUMENTATION

	POSITION #2 (RIGHT FRONT) SERIAL NO.: 186		
	SERIAL NUMBER	MANUFACTURER	CALIBRATION DATE
HEAD AX	AC-04J04I20-Z23	ENTRAN	3/13/2007
HEAD AY	AC-04J04I01-R12	ENTRAN	3/13/2007
HEAD AZ	AC-02I02I16-A08	ENTRAN	3/13/2007
UPPER NECK FX	LC-175Fx	DENTON	5/2/2007
UPPER NECK FY	LC-175Fy	DENTON	5/2/2007
UPPER NECK FZ	LC-175Fz	DENTON	5/2/2007
UPPER NECK MX	LC-175Mx	DENTON	5/2/2007
UPPER NECK MY	LC-175My	DENTON	5/2/2007
UPPER NECK MZ	LC-175Mz	DENTON	5/2/2007
CHEST AX	AC-04J04I08-F25	ENTRAN	3/13/2007
CHEST AY	AC-03E03E20-N05	ENTRAN	3/13/2007
CHEST AZ	AC-03E03D30-N08	ENTRAN	3/13/2007
CHEST DISPLACEMENT X	DS-186	SERVO	5/10/2006
UPPER STERNUM AX	AC-02A16-A26	ENTRAN	3/13/2007
LOWER STERNUM AX	AC-99H12-F24	ENTRAN	3/13/2007
PELVIS AX	AC-04J04I01-R06	ENTRAN	3/13/2007
PELVIS AY	AC-03E03D30-N03	ENTRAN	3/13/2007
PELVIS AZ	AC-03D03D16-F04	ENTRAN	3/13/2007
LEFT FEMUR FZ	LC-247	DENTON	5/18/2006
RIGHT FEMUR FZ	LC-248	DENTON	5/16/2006