

Manufactured in 13JUN07

Model # 3901698 L1

Figure D2-1: Position 3 CRS Label

This Space Intentionally Left Blank



Figure D2-2: Pre-Test Frontal View of Position 3 CRS



Figure D2-3: Post-Test Frontal View of Position 3 CRS



Figure D2-4: Pre-Test Rear View of Position 3 CRS



Figure D2-5: Post-Test Rear View of Position 3 CRS



Figure D2-6: Pre-Test Left Side View of Position 3 CRS



Figure D2-7: Post-Test Left Side View of Position 3 CRS



Figure D2-8: Pre-Test Right Side View of Position 3 CRS



Figure D2-9: Post-Test Right Side View of Position 3 CRS



Figure D2-10: Pre-Test Position 3 Front View (Head and Seat Belt Position)



Figure D2-11: Post-Test Position 3 Front View (Head and Seat Belt Position)



Figure D2-12: Pre-Test Position 3 Front View (Seat Belt Position)



Figure D2-13: Post-Test Position 3 Front View (Seat Belt Position)



Figure D2-14: Pre-Test Position 3 Right Side View



Figure D2-15: Post-Test Position 3 Right Side View



Figure D2-16: Pre-Test Position 3 Right Side View (Through Window)



Figure D2-17: Post-Test Position 3 Right Side View (Through Window)

