


REPORT NUMBER: SINCAP-MGA-2018-003

**NEW CAR ASSESSMENT PROGRAM (NCAP)
Moving Deformable Barrier Side Impact Test**

**HONDA MFG. OF ALABAMA, LLC
2018 Honda Odyssey EX Minivan
NHTSA No.: O20185302**

**MGA RESEARCH CORPORATION
5000 Warren Road
Burlington, WI 53105**



Test Date: August 10, 2017

Final Report Date: September 15, 2017


FINAL REPORT

**U.S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
Office of Crashworthiness Standards
Mail Code: NRM-110
1200 New Jersey Ave, SE
Room W43-410
Washington, DC 20590**

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof.

If trade or manufacturers' names or products are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Prepared by: 
Ben Fischer, Project Engineer

Approved by: 
Bob Schnorenberg, Project Engineer

Approval Date: September 15, 2017

FINAL REPORT ACCEPTANCE BY OCWS:

Division Chief, New Car Assessment Program
NHTSA, Office of Crashworthiness Standards

Date: _____

COTR, New Car Assessment Program
NHTSA, Office of Crashworthiness Standards

Date: _____

Technical Report Documentation Page

1. Report No. SINCAP-MGA-2018-003	2. Government Accession No.	3. Recipient's Catalog No.																													
4. Title and Subtitle Final Report of New Car Assessment Program Side Impact MDB Testing of 2018 Honda Odyssey EX Minivan, NHTSA No.: O20185302		5. Report Date September 15, 2017																													
		6. Performing Organization Code MGA																													
7. Author(s) Ben Fischer, Project Engineer		8. Performing Organization Report No. SINCAP-MGA-2018-003																													
9. Performing Organization Name and Address MGA Research Corporation 5000 Warren Road Burlington, WI 53105		10. Work Unit No.																													
		11. Contract or Grant No. DTNH22-14-D-00353																													
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration Office of Crashworthiness Standards (NRM-110) 1200 New Jersey Ave, SE, Room W43-410 Washington, D.C. 20590		13. Type of Report and Period Covered: Final Test Report August 10, 2017 to September 15, 2017																													
		14. Sponsoring Agency Code NRM-110																													
15. Supplementary Notes																															
16. Abstract A 55/28 km/h 90° Moving Deformable Barrier NCAP Side Impact Test was conducted on the 2018 Honda Odyssey EX Minivan in accordance with the specifications of the Office of Crashworthiness Standards NCAP Side Laboratory Test Procedure for the generation of consumer information on vehicle side crash protection. The test was conducted at MGA Research Corporation in Burlington, Wisconsin on August 10, 2017. The impact velocity of the Moving Deformable Barrier (MDB) was 62.59 km/h, and the ambient temperature at the struck (driver's) side of the target vehicle at the time of impact was 21.8°C. The target vehicle post-test maximum crush was 198 mm at level 3. The test vehicle's performance was as follows:																															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="4" style="text-align: center;">Driver ATD (ES-2re)</th> </tr> <tr> <th style="text-align: left;">Measurement Description</th> <th style="text-align: center;">Units</th> <th style="text-align: center;">Threshold</th> <th style="text-align: center;">Result</th> </tr> </thead> <tbody> <tr> <td>Head Injury Criteria (HIC₃₆)</td> <td style="text-align: center;">N/A</td> <td style="text-align: center;">1000</td> <td style="text-align: center;">66</td> </tr> <tr> <td>Maximum Thorax Rib Deflection</td> <td style="text-align: center;">mm</td> <td style="text-align: center;">44</td> <td style="text-align: center;">13</td> </tr> <tr> <td>Total Abdominal Force</td> <td style="text-align: center;">N</td> <td style="text-align: center;">2500</td> <td style="text-align: center;">367</td> </tr> <tr> <td>Pubic Symphysis Force</td> <td style="text-align: center;">N</td> <td style="text-align: center;">6000</td> <td style="text-align: center;">1429</td> </tr> <tr> <td>Resultant Lower Spine Acceleration</td> <td style="text-align: center;">Gs</td> <td style="text-align: center;">82*</td> <td style="text-align: center;">16</td> </tr> </tbody> </table>				Driver ATD (ES-2re)				Measurement Description	Units	Threshold	Result	Head Injury Criteria (HIC ₃₆)	N/A	1000	66	Maximum Thorax Rib Deflection	mm	44	13	Total Abdominal Force	N	2500	367	Pubic Symphysis Force	N	6000	1429	Resultant Lower Spine Acceleration	Gs	82*	16
Driver ATD (ES-2re)																															
Measurement Description	Units	Threshold	Result																												
Head Injury Criteria (HIC ₃₆)	N/A	1000	66																												
Maximum Thorax Rib Deflection	mm	44	13																												
Total Abdominal Force	N	2500	367																												
Pubic Symphysis Force	N	6000	1429																												
Resultant Lower Spine Acceleration	Gs	82*	16																												
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="4" style="text-align: center;">Passenger ATD (SID-IIs)</th> </tr> <tr> <th style="text-align: left;">Measurement Description</th> <th style="text-align: center;">Units</th> <th style="text-align: center;">Threshold</th> <th style="text-align: center;">Result</th> </tr> </thead> <tbody> <tr> <td>Head Injury Criteria (HIC₃₆)</td> <td style="text-align: center;">N/A</td> <td style="text-align: center;">1000</td> <td style="text-align: center;">125</td> </tr> <tr> <td>Resultant Lower Spine Acceleration</td> <td style="text-align: center;">Gs</td> <td style="text-align: center;">82</td> <td style="text-align: center;">70</td> </tr> <tr> <td>Total Pelvic Force (sum of acetabular and iliac forces)</td> <td style="text-align: center;">N</td> <td style="text-align: center;">5525</td> <td style="text-align: center;">3155</td> </tr> <tr> <td>Maximum Thoracic Rib Deflection</td> <td style="text-align: center;">mm</td> <td style="text-align: center;">38*</td> <td style="text-align: center;">30</td> </tr> <tr> <td>Maximum Abdomen Rib Deflection</td> <td style="text-align: center;">mm</td> <td style="text-align: center;">45*</td> <td style="text-align: center;">18</td> </tr> </tbody> </table>				Passenger ATD (SID-IIs)				Measurement Description	Units	Threshold	Result	Head Injury Criteria (HIC ₃₆)	N/A	1000	125	Resultant Lower Spine Acceleration	Gs	82	70	Total Pelvic Force (sum of acetabular and iliac forces)	N	5525	3155	Maximum Thoracic Rib Deflection	mm	38*	30	Maximum Abdomen Rib Deflection	mm	45*	18
Passenger ATD (SID-IIs)																															
Measurement Description	Units	Threshold	Result																												
Head Injury Criteria (HIC ₃₆)	N/A	1000	125																												
Resultant Lower Spine Acceleration	Gs	82	70																												
Total Pelvic Force (sum of acetabular and iliac forces)	N	5525	3155																												
Maximum Thoracic Rib Deflection	mm	38*	30																												
Maximum Abdomen Rib Deflection	mm	45*	18																												
*Proposed IARV																															
The doors on the struck side of the vehicle did not separate from the body at the hinges or latches and the opposite doors did not open during the side impact event.																															
17. Key Words New Car Assessment Program (NCAP) Side Impact MDB ES-2re SID-IIs		18. Distribution Statement Copies of this report are available from: National Highway Traffic Safety Administration Technical Information Services Division, NPO-411 1200 New Jersey Ave, SE Washington, DC 20590 e-mail: tis@nhtsa.dot.gov FAX: 202-493-2833																													
19. Security Classification of Report Unclassified	20. Security Classification of Page Unclassified	21. No. of Pages 223	22. Price																												

TABLE OF CONTENTS

<u>Section</u>		<u>Page No.</u>
1	Test Purpose and Procedure	1
2	Summary of Test Results	2
3	Occupant and Vehicle Information / Data Sheets	4

<u>Data Sheet No.</u>		<u>Page No.</u>
1	General Test and Vehicle Parameter Data	5
2	Seat, Seat Belt, Steering Wheel Adjustment and Fuel System Data	9
3	Dummy Longitudinal Clearance Dimensions	13
4	Dummy Lateral Clearance Dimensions	14
5	Camera and Instrumentation Data	15
6	Test Vehicle Accelerometer Locations	16
7	MDB Accelerometer Locations	17
8	Post-Test Observations	18
9	MDB Summary of Results	20
10	Test Vehicle Profile Measurements	21
11	Test Vehicle Exterior Crush Measurements	22
12	MDB Exterior Static Crush Measurements	25
13	Vehicle and MDB Damage Profile Distances	26
14	FMVSS No. 301 Static Rollover Results	27
15	Dummy/Vehicle Temperature Stabilization Data	28

<u>Appendix</u>		
A	Photographs	A
B	Dummy Response Data	B
C	Dummy Calibration and Performance Verification Data	C
D	Test Equipment and Instrumentation Calibration Data	D

SECTION 1
TEST PURPOSE AND PROCEDURE

This moving deformable barrier side impact test is part of the MY 2018 New Car Assessment Program Side Impact Test Program, sponsored by the National Highway Traffic Safety Administration (NHTSA), under Contract No. DTNH22-14-D-00353. The purpose of this test is to generate comparative side impact performance in a 2018 Honda Odyssey EX Minivan. The side impact test was conducted in accordance with the Office of Crashworthiness Standard's Side NCAP Laboratory Test Procedure dated October 2015.

SECTION 2 SUMMARY OF TEST RESULTS

A 2018 Honda Odyssey EX Minivan was impacted on the left (driver's) side by a Moving Deformable Barrier (MDB) which was moving forward in a 27° crabbed position to the tow road guidance system at a velocity of 62.59 km/h. The target vehicle was stationary and was positioned at an angle of 63° to the line of forward motion. The side impact test was conducted by MGA Research Corporation in Burlington, Wisconsin on August 10, 2017. Pre-test and post-test photographs of the test vehicle, the MDB, and the dummies (ES-2re and SID-IIs) are included in this report.

Dummies were placed in the driver and left rear designated seating positions according to instructions specified in the OCWS NCAP Side Laboratory Test Procedure dated October 2015. The side impact event was documented by eleven (11) cameras. Camera locations are included in this report.

The dummies were instrumented in the following manner:

DRIVER ATD (ES-2re)

Primary and Redundant Head CG Triaxial Accelerometers
 Chest Upper Rib, Middle Rib, and Lower Rib Y-Axis Displacement Potentiometers
 Abdomen Forward, Middle, and Rear Y-Axis Load Cells
 Lower Spine (T12) Triaxial Accelerometers
 Pubic Symphysis Y-Axis Load Cell

PASSENGER ATD (SID-IIs)

Primary and Redundant Head CG Triaxial Accelerometers
 Primary Head CG Angular Rate Sensors
 Chest Upper Rib, Middle Rib, and Lower Rib Y-Axis Displacement Potentiometers
 Abdomen Upper Rib and Lower Rib Y-Axis Displacement Potentiometers
 Lower Spine (T12) Triaxial Accelerometers
 Acetabulum and Iliac Wing Y-Axis Load Cells

Appendix B contains the dummy response data. Dummy configuration and performance verification data can be found in Appendix C of this report. Appendix D contains the test equipment and instrumentation calibration data.

Dummy Injury readings were recorded as follows:

DUMMY INJURY VALUES

Measurement Description	Driver ATD (ES-2re)		
	Units	Threshold	Result
Head Injury Criteria (HIC ₃₆)	N/A	1000	66
Maximum Thorax Rib Deflection	mm	44	13
Total Abdominal Force	N	2500	367
Pubic Symphysis Force	N	6000	1429
Resultant Lower Spine Acceleration	Gs	82*	16

Measurement Description	Passenger ATD (SID-IIs)		
	Units	Threshold	Result
Head Injury Criteria (HIC ₃₆)	N/A	1000	125
Resultant Lower Spine Acceleration	Gs	82	70
Total Pelvic Force (sum of acetabular and iliac forces)	N	5525	3155
Maximum Thoracic Rib Deflection	mm	38*	30
Maximum Abdomen Rib Deflection	mm	45*	18

*Proposed IARV

Supplemental restraint information is given below:

SUPPLEMENTAL RESTRAINT SYSTEM INFORMATION

Restraint Type	Struck Side Driver		Struck Side Rear Passenger	
	Mounted	Deployed	Mounted	Deployed
Frontal Airbag	Yes	No		
Knee Airbag	Yes	No		
Side Curtain Airbag	Yes	Yes	Yes	Yes
Side Torso/Pelvis Airbag	Yes	Yes	No	
Seat Belt Pretensioner	Yes	Yes	No	
Seat Belt Load Limiter	Yes		No	
Other:	No		No	

The test data can be found on the NHTSA website at www.nhtsa.dot.gov

GENERAL COMMENTS

Driver Lower Spine X recorded no valid data after 97ms.
MDB CG Z recorded questionable data.

MGA does not endorse or certify products. The manufacturer's name appears solely for identification purposes.

SECTION 3
OCCUPANT AND VEHICLE INFORMATION / DATA SHEETS

**DATA SHEET NO. 1
GENERAL TEST AND VEHICLE PARAMETER DATA**

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
Test Date: 8/10/2017

TEST VEHICLE INFORMATION AND OPTIONS

NHTSA No.	O20185302	Traction Control System (TCS)	Yes
Model Year	2018	Auto-Leveling System	No
Make	Honda	Automatic Door Locks (ADL)	Yes
Model	Odyssey EX	Power Window Auto-Reverse	Yes
Body Style	Minivan	Other Optional Feature	N/A
VIN	5FNRL6H50JB017336	Driver Front Airbag	Yes
Body Color	Pacific Pewter Metallic	Driver Curtain Airbag	Yes
Odometer Reading (km/mi)	167km / 104mi	Driver Head/Torso Airbag	No
Engine Displacement (L)	3.5L	Driver Torso Airbag	No
Type/No. Cylinders	6	Driver Torso/Pelvis Airbag	Yes
Engine Placement	Lateral	Driver Pelvis Airbag	No
Transmission Type	Automatic	Driver Knee Airbag	Yes
Transmission Speeds	9	Rear Pass. Curtain Airbag	Yes
Overdrive	Yes	Rear Pass. Head/Torso Airbag	No
Final Drive	FWD	Rear Pass. Torso Airbag	No
Roof Rack	No	Rear Pass. Torso/Pelvis Airbag	No
Sunroof/T-Top	No	Rear Pass. Pelvis Airbag	No
Running Boards	No	Driver Seat Belt Pretensioner	Yes
Tilt Steering Wheel	Yes	Rear Pass. Seat Belt Pretensioner	No
Power Seats	Yes	Driver Load Limiter	Yes
Anti-Lock Brakes (ABS)	Yes	Rear Pass. Load Limiter	No
		Other Restraint Feature	N/A

Does owner's manual provide instruction to turn off automatic door locks?	Yes
---	-----

DATA FROM CERTIFICATION LABEL

Manufactured By	HONDA MFG. OF ALABAMA, LLC	GVWR (kg)	2730
Date of Manufacture	06/17	GAWR Front (kg)	1310
Vehicle Type	MPV	GAWR Rear (kg)	1465

VEHICLE SEATING AND WEIGHT CAPACITY DATA

Measured Parameter	Front	Rear	Third	Total	
Designated Seating Capacity (DSC)	2	3	3	8	
Capacity Weight (VCW) (kg)				608	(A)
DSC x 68.04 kg				544	(B)
Rated Cargo and Luggage Weight (RCLW) (kg)				64	(A-B)

VEHICLE SEAT TYPE


Seating Location	Type of Seat Pan				Type of Seat Back		
	Bucket	Bench	Split Bench	Contoured	Fixed	Adjustable	
						Manual	Power
Front Seat	X						X
Rear or Second Row Seat	X					w/ Lever	
Third Row Seat			X			w/ Lever	

DATA SHEET NO. 1 (CONTINUED)
GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017

VEHICLE TIRE INFORMATION



Measured Parameter	Front	Rear
Max. Tire Pressure (kPa)	300	300
Cold Pressure (kPa)	240	240
Recommended Tire Size	235/60 R18	235/60 R18
Tire Size on Vehicle	235/60 R18	235/60 R18
Tire Manufacturer	Bridgestone	Bridgestone
Tire Model	Turanza	Turanza
Treadwear	480	480
Traction	A	A
Temperature Grade	A	A
Tire Plies Sidewall	2 Polyester	2 Polyester
Tire Plies Body	1 Polyester, 2 Steel, 1 Nylon	1 Polyester, 2 Steel, 1 Nylon
Load Index/Speed Symbol	103H	103H
Tire Material	Rubber	Rubber
DOT Safety Code Left	7X45 JB2 2217	7X45 JB2 2217
DOT Safety Code Right	7X45 JB2 2217	7X45 JB2 2217

DATA SHEET NO. 1 (CONTINUED)
GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017

TEST PRESSURES

	Units	LF	RF	LR	RR
As Delivered	kPa	250	240	240	240
Tire Placard	kPa	240	240	240	240
Owner's Manual	kPa	240	240	240	240
As Tested	kPa	240	240	240	240

MDB TIRE SPECIFICATIONS

Requirement	Units	LF	RF	LR	RR
Tire Size	P205/75R15	P205/75R15	P205/75R15	P205/75R15	P205/75R15
Tire	200 ± 21	200	200	200	200

TEST VEHICLE AXLE WEIGHTS

	Units	As Delivered (UVW)			As Tested (ATW)			Fully Loaded		
		Front	Rear	Total	Front	Rear	Total	Front	Rear	Total
Left	kg	554.5	451.0		602.0	532.0		599.5	535.5	
Right	kg	553.5	450.0		543.0	518.0		554.5	513.0	
Ratio	%	55.2%	44.8%		52.2%	47.8%		52.4%	47.6%	
Totals	kg	1108.0	901.0	2009.0	1145.0	1050.0	2195.0	1154.0	1048.5	2202.5

TARGET TEST WEIGHT CALCULATION

Measured Parameter	Units	Value	
Total Delivered Weight (UVW)	kg	2009.0	(A)
Sum of Actual Weight of 2 P572 ATDs Used	kg	129	(B)
Rated Cargo/Luggage Weight (RCLW)	kg	64	(C)
Calculated Test Vehicle Target Weight (TVTW)	kg	2202.0	(A+B+C)

Does the measured As Tested Vehicle Weight lie within the required weight range (i.e. Calculated Test Vehicle Target Weight – 4.5 kg to 9 kg)? **YES**

TEST VEHICLE ATTITUDES AND CG

	Units	Fully Loaded	As Tested	Meets Requirement***
Left Front	mm	766	766	Yes
Right Front	mm	777	768	Yes
Right Rear	mm	763	771	Yes
Left Rear	mm	760	759	Yes
Vehicle CG (Aft of Front Axle)	mm	1428	1435	
Vehicle CG (Left (+) / Right (-) from Longitudinal Centerline)	mm	26	1	

*** The "As Tested" vehicle attitude measurements must be equal to or within ± 10 mm of the "Fully Loaded" vehicle attitude measurements at each wheel well.

Test height adjustable suspension setting, if applicable:	Not Applicable
---	----------------

DATA SHEET NO. 1 (CONTINUED)
GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
Test Date: 8/10/2017

WEIGHT OF BALLAST AND VEHICLE COMPONENTS REMOVED TO MEET TVTW

Component Description	Weight (kg)
Weight of Ballast, if any	7
None	

DATA SHEET NO. 2
SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
 Test Date: 8/10/2017

SEAT POSITIONING

The driver's seat, front center seat (if applicable), and right front passenger's seat should be set to the mid-track, lowest, mid-angle position. The struck-side rear passenger's seat, rear center seat, and non-struck side rear passenger's seats should be set to the rear-most, lowest, mid-angle position.

SCRL ANGLE RANGE

Seat	SCRL (°)		
	Max	Min	Mid
Driver Seat	26.0	13.4	19.7
Front Passenger Seat	Fixed	Fixed	Fixed
Front Center Seat			
Struck Side Rear Seat	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed
Rear Center Seat	Fixed	Fixed	Fixed

SEAT HEIGHT AND ANGLE

Seat	As-Tested SCRL Angle (Mid)	As-Tested SCRP Height (mm)	SCRP Height Position	SCRP Height (mm)		
				Rear-Most	Mid	Forward-Most
Driver Seat	19.7	0	Max	50	50	50
			Mid	25	25	25
			Min	0	0	0
Front Passenger Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed
Front Center Seat			Max			
			Mid			
			Min			
Struck Side Rear Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed
Rear Center Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed

DATA SHEET NO. 2 (CONTINUED)
SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test


NHTSA No. O20185302
 Test Date: 8/10/2017

SEAT FORE/AFT POSITIONS

Seat	Total Fore/Aft Travel		Test Position from Forward-Most Position	
	mm	Detents (1 st as 1)	mm	Detent (1 st as 0)
Driver Seat	218		109	
Front Passenger Seat	198		99	
Front Center Seat				
Struck Side Rear Seat	152	16	152	15
Non-Struck Side Rear Seat	152	16	152	15
Rear Center Seat	Fixed	Fixed	Fixed	Fixed

SEAT BACK ANGLE ADJUSTMENT

The driver's seat back is positioned to the manufacturer's designated design angle. The front passenger's seat back is positioned in a similar manner as the driver's seat back. The struck side rear seat back is adjusted following Appendix C, "Positioning Dummies in the Test Vehicle" in the NCAP Laboratory Test Procedure dated October 2015. The rear center and non-struck side rear outboard seat backs are positioned to match the struck side rear seat back.



Seat	Total Seat Back Angle Range		Test Position from Vertical	
	Degrees	Detents (1 st as 1)	Degrees	Detent (1 st as 0)
Driver Seat	79.3		2.2	
Front Passenger Seat	79.5		2.6	
Front Center Seat				
Struck Side Rear Seat	32.8	17	5.7	0
Non-Struck Side Rear Seat	32.8	17	5.7	0
Rear Center Seat	32.8	17	5.7	0

Seat back angles measured on outboard headrest post.

DATA SHEET NO. 2 (CONTINUED)
SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017

SEAT BELT ANCHORAGE ADJUSTMENT

Seat belt anchorages are adjusted in accordance with the information provided by the manufacturer on Form No. 1.

	Total # of Positions	Placed in Position #
Driver Seat	4	0 (Uppermost as 0)
Rear Seat	Fixed	

HEAD RESTRAINT ADJUSTMENT


The driver's head restraint is adjusted to the highest and most full forward in-use position. The struck-side rear passenger's head restraint is adjusted to the lowest and most full forward in-use position.

	Total # of Positions	Placed in Position #
Driver Seat	6	5 (Lowest as 0) / Fixed Fore-Aft
Rear Seat	5	0 (Lowest as 0) / Fixed Fore-Aft

STEERING COLUMN ADJUSTMENT

Steering wheel and column adjustments are made so that the steering wheel hub is at the center of its geometric locus it describes when it moves through its full range of motion.


	Wheel Angle (deg)	Fore/Aft Position (mm)
Lowermost, Position 1	67.2	238
Geometric Center, Position 2	64.8	218
Uppermost, Position 3	62.3	198
Telescoping Steering Wheel Travel		40
Test Position	64.8	218



FUEL PUMP

Describe the fuel pump type, details about how it operates and the location of the fuel filler pipe.

The vehicle is equipped with an electronic fuel pump. Ignition Stage 2 will activate the fuel pump to prime the system. The filler neck is located on the driver's side.



DATA SHEET NO. 2 (CONTINUED)
SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
Test Date: 8/10/2017

FUEL TANK CAPACITY DATA

	Liters
Usable Capacity of Standard Tank (see Form No. 1)	73.8
Usable Capacity of Optional Tank (see Form No. 1)	
Usable Capacity of Standard Tank as Specified in Owner's Manual	73.8
Usable Capacity of Optional Tank as Specified in Owner's Manual	
93% of Usable Capacity	68.6
Actual Amount of Solvent Used	68.5
1/3 of Usable Capacity	24.6


Is the actual amount of solvent used in the test equal to 93% + 1%
of the Usable Capacity stated in Form No. 1?

YES

DATA SHEET NO. 3 DUMMY LONGITUDINAL CLEARANCE DIMENSIONS

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017



LEFT SIDE VIEW

NOTE: 2-DOOR VEHICLE SHOWN.
 REAR DUMMY PHX & PHZ
 MEASUREMENTS FOR A 4-DOOR
 VEHICLE WOULD USE THE C-POST
 STRIKER AS A REFERENCE POINT


DUMMY LONGITUDINAL CLEARANCE DIMENSION INFORMATION

Driver Code	Pass. Code	Measurement Description	Driver		Passenger	
			Length (mm)	Angle (°)	Length (mm)	Angle (°)
HH		Head to Header	410	15.9		
HW		Head to Windshield	771	0		
HZ	HZ	Head to Roof Liner	221	90	328	90
NR	NB	Nose to Rim/Seat Back	481	11.4	561	10.1
CD	CB	Chest to Dashboard/Seat Back	622	35.8	578	9.5
CS		Chest to Steering Wheel	395	7.4		
KDL	KBL	Left Knee to Dash/Seat Back	180	36.9	319	9.0
KDR	KBR	Right Knee to Dash/Seat Back	182	40.6	315	9.3
PAX	PAX	Pelvic Tilt Angle X		24.6		22.1
PAY	PAY	Pelvic Tilt Angle Y		-1.3		-0.8
PHX	PHX	Hip Point to Striker (X-Axis)	223		366	
PHZ	PHZ	Hip Point to Striker (Z-Axis)	168		161	

**DATA SHEET NO. 4
DUMMY LATERAL CLEARANCE DIMENSIONS**

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
 Test Date: 8/10/2017




DUMMY LATERAL CLEARANCE DIMENSION INFORMATION

Code	Measurement Description	Units	Driver	Passenger
HR	Head to Side Header	mm	254	269
HS	Head to Side Window	mm	374	385
AD	Arm to Door	mm	120	168
HD	Hip Point to Door	mm	160	227

DATA SHEET NO. 5 CAMERA AND INSTRUMENTATION DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
 Test Date: 8/10/2017



CAMERA LOCATIONS AND DATA

No.	Camera View	Coordinates (mm)			Lens Length (mm)	Operating Frame Rate (fps)
		X*	Y*	Z*		
1	Overhead Overall	670	-1010	-4895	8.5	1000
2	Overhead Close-Up	0	0	-4895	20	1000
3	Left Impact Point (MDB)				50	1000
4	Side Overall (MDB)				16	1000
5	Rear	200	7274	-1450	24	1000
6	Left Front	-2080	-6544	-1450	24	1000
7	Driver Front (OB)				16	1000
8	Driver Side (OB)				8	1000
9	Passenger Side (OB)				8	1000
10	Real Time Left Rear					30
11	Real Time Inrun					30

Reference: Impact Point projected to Ground; +X = To Front of MDB, +Y = To Right of MDB, +Z = Down
 * All measurements accurate to ± 6 mm


INSTRUMENTATION

	Number of Channels
Driver Dummy	16
Passenger Dummy	19
Vehicle Structure	23
MDB Accelerometers	5
MDB Contacts	2
Total	65

**DATA SHEET NO. 6
TEST VEHICLE ACCELEROMETER LOCATIONS**

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
Test Date: 8/10/2017



TEST VEHICLE ACCELEROMETER LOCATIONS


Accelerometer Location				
No.	ID	Coordinates (mm)		
		X	Y	Z
1	Vehicle CG	3164	0	-250
2	Right Sill at Front Seat	2819	776	-230
3	Right Sill at Rear Seat	1775	776	-259
4	Left Sill at Front Door	3156	-776	-223
5	Left Sill at Rear Door	2190	-776	-231
6	Left Lower A-Post	3672	-892	-838
7	Left Middle A-Post	3670	-889	-645
8	Left Lower B-Post	2705	-791	-658
9	Left Middle B-Post	2611	-798	-978
10	Front Seat Track	2905	-403	-399
11	Rear Seat Structure	2275	-427	-441
12	Rt. Rear Occ. Compartment	2362	404	-420
13	Engine Block	4429	0	-879
14	Rear Above Axle	840	0	-448

Reference: X – Rear Surface of Vehicle (+ forward)
Y – Vehicle Centerline (+ to right)
Z – Ground Plane (+ down)

DATA SHEET NO. 7
MDB ACCELEROMETER LOCATIONS

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
Test Date: 8/10/2017



MDB ACCELEROMETER LOCATIONS

No.	Accelerometer Location	Coordinates (mm)		
		X	Y	Z
1	MDB CG	-1105	0	-330
2	MDB Rear	-2580	-650	-625

Reference: X – MDB Face (+ forward)
Y – MDB Centerline (+ to right)
Z – Ground Plane (+ down)

**DATA SHEET NO. 8
POST-TEST OBSERVATIONS**

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
Test Date: 8/10/2017

TEST DUMMY INFORMATION AND CONTACT POINTS

Description	Front Seat Dummy (ES-2re)	Rear Seat Dummy (SID-lis)
Face	Curtain Airbag	Curtain Airbag
Top of Head	Curtain Airbag	Curtain Airbag
Left Side of Head	Curtain Airbag	Curtain Airbag
Back of Head	Curtain Airbag, Headrest	Curtain Airbag
Left Shoulder	Curtain Airbag	Door Panel
Upper Torso	Seat Back	Seat Back
Lower Torso	Side Torso/Pelvis Airbag, Seat Back	Seat Back, Door Panel
Left Hip	Side Torso/Pelvis Airbag	Door Panel
Left Knee	None	Door Panel

POST-TEST DOOR PERFORMANCE

Description	Struck Side		Non-Struck Side		Rear Hatch / Other Door
	Front	Rear	Front	Rear	
Remained Closed and Operational	No	No	Yes	Yes	Yes
Total Separation from Vehicle at Hinges or Latches	No	No	No	No	No
Latch or Hinge Systems Pulled Out of Their Anchorages	No	No	No	No	No
Disengaged from Latched Position	No	No	No	No	No
Latch Separated from Striker	No	No	No	No	No
Jammed Shut	Yes	Yes	No	No	No
If Door Opened at Striker, Record Width of Opening at Striker (mm)					

POST-TEST SEAT PERFORMANCE

Description	Struck Side		Non-Struck Side	
	Front	Rear	Front	Rear
Seat Movement Along Seat Track	No	No	No	No
Seat Disengagement from Floor Pan	No	No	No	No
Seat Back Movement from Initial Position	No	No	No	No
Seat Back Collapse	No	No	No	No

POST-TEST STRUCTURAL OBSERVATIONS

Critical Areas of Performance	Observations and Conclusions
Pillar Performance	No Separation
Sill Separation	None
Windshield Damage	None
Side Window Damage	LF, LR Window Broken
Other Notable Effects	None

**DATA SHEET NO. 8 (CONTINUED)
POST-TEST OBSERVATIONS**

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
Test Date: 8/10/2017

SUPPLEMENTAL RESTRAINT SYSTEM INFORMATION

Restraint Type	Struck Side Driver		Struck Side Rear Passenger	
	Mounted	Deployed	Mounted	Deployed
Frontal Airbag	Yes	No		
Knee Airbag	Yes	No		
Side Curtain Airbag	Yes	Yes	Yes	Yes
Side Torso/Pelvis Airbag	Yes	Yes	No	
Seat Belt Pretensioner	Yes	Yes	No	
Seat Belt Load Limiter	Yes		No	
Other:	No		No	

IMPACT POINT LOCATION DATA

Measured Parameter	Units	Tolerance	Value
Vehicle Wheel Base	mm		3000
Vertical Impact Reference Line (Aft of Front Axle) (Intended Impact Point)	mm		508
Actual Impact Point (Aft of Front Axle)	mm		507
Horizontal Offset (+forward / -rearward)	mm	+/- 50 of intended impact point	1
Vertical Offset (+down / -up)	mm	+/- 20 of intended impact point	5

**DATA SHEET NO. 9
MDB SUMMARY OF RESULTS**

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
Test Date: 8/10/2017

MDB SPECIFICATIONS

Measurement Description	Length (mm)
Overall Width of Framework Carriage	1250
Overall Length Including Honeycomb Face	4119
Wheelbase of Framework Carriage	2584
CG Location aft of Front Axle	1128

MDB WEIGHTS

	Units	Front Axle	Rear Axle	Total
Left	kg	427.9	264.0	
Right	kg	340.6	331.2	
Ratio	%	56.4	43.6	
Totals	kg	768.5	595.2	


SPEED AND ANGLE AT IMPACT DATA

Measured Parameter	Units	Requirement	Value
Trap No. 1 Velocity (Primary)	km/h	61.1 to 62.7	62.59
Trap No. 2 Velocity (Redundant)	km/h	61.1 to 62.7	62.61
MDB CL to Target Vehicle CL	degrees	88.5 to 91.5	90.2
MDB Forward Line of Motion to Target Vehicle CL	degrees	62.5 to 63.5	63.0
MDB Crabbed Angle to MDB Forward Line of Motion	degrees	26 to 28	26.8

DATA SHEET NO. 10 TEST VEHICLE PROFILE MEASUREMENTS

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. Q20185302
Test Date: 8/10/2017



All measurements in (mm) with tolerance of ± 3 mm

LEFT SIDE VIEW


VEHICLE PRE- AND POST-TEST MEASUREMENT INFORMATION

Code	Measurement Description	Pre-Test	Post-Test	Difference
A	Wheelbase	3000	2997	3
B	Front Axle to FSOV	968	951	17
C	Rear Axle to RSOV	1196	1216	-20
D	Total Length at Centerline	5164	5164	0
E	Front Bumper Thickness	120	120	0
F	Front Bumper Bottom to Ground	172	180	-8
G	Sill Height at Front Wheel Well	228	231	-3
H	Sill Height at Front Door Leading Edge	203	206	-3
I	Sill Height at B Pillar	212	210	2
J1	Sill Height at Rear Wheel Well	233	237	-4
J2	Pinch Weld Height at Rear Wheel Well	207	210	-3
K	Sill Height Aft of Rear Wheel Well	242	257	-15
L	Rear Bumper Thickness	80	80	0
M	Rear Bumper Bottom to Ground	331	341	-10
N	Sill Height to Window Bottom Sill	860	811	49
O	Front Door Leading Edge to Impact CL	881	816	65
P	Rear Door Trailing Edge to Impact CL	1325	1254	71
Q	Front Window Opening	505	529	-24
R	Right Side Length	4450	4459	-9
S	Left Side Length	4450	4451	-1
T	Vehicle Width at B Post	1963	1890	73

DATA SHEET NO. 11
TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017



All Measurements Shown in mm

LEFT SIDE VIEW

MAXIMUM EXTERIOR CRUSH MEASUREMENTS

Level	Measurement Description	Height Above Ground	Maximum Exterior Static Crush	Distance from Impact
1	Sill Top	294	25	150
2	Occupant H-Point	664	187	1650
3	Mid Door	685	198	1650
4	Window Sill	998	141	1500
5	Window Top	1610	8	1050

Note: The measurements are taken along the vertical impact reference line. Vehicle measurements forward of the vertical impact reference line are negative.

DATA SHEET NO. 11 (CONTINUED)
TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017

	Pre-Test					Post-Test					Difference					
	1	2	3	4	5	1	2	3	4	5	1	2	3	4	5	
-2100																
-1950																
-1800																
-1650																
-1500																
-1350																
-1200																
-1050																
-900																
-750																
-600				213					231					18		
-450				194					216					22		
-300				182					204					22		
-150		119	118	171			126	126	188			7	8	17		
0	146	120	119	163		147	125	132	160		1	5	13	-3		
150	148	120	124			173	240	237			25	120	113			
300	148	132	133	147		165	290	291	223		17	158	158	76		
450	150	139	136	140		165	306	305	213		15	167	169	73		
600	150	140	136	137		171	314	314	202		21	174	178	65		
750	151	140	136	135	380	173	317	315	190	386	22	177	179	55	6	
900	151	139	135	134	373	173	286	286	175	378	22	147	151	41	5	
1050	152	138	135	133	369	175	235	234	164	377	23	97	99	31	8	
1200	153	138	134	134	368	169	282	283	211	351	16	144	149	77	-17	
1350	154	136	132	132	367	166	315	317	235	335	12	179	185	103	-32	
1500	155	133	130	132	367	163	318	325	273	322	8	185	195	141	-45	
1650	156	130	128	131	369	150	317	326	266	310	-6	187	198	135	-59	
1800	156	125	124	131	372	137	305	317	242	299	-19	180	193	111	-73	
1950	156	120	120	134	376	111	196	213	229	289	-45	76	93	95	-87	
2100		114	114	135	380		134	135	176	280		20	21	41	-100	
2250				137	387				112	392					-25	5
2400				148	397				154	401					6	4
2550				156	408				160	412					4	4
2700				162	419				167	424					5	5
2850				168	435				173	437					5	2
3000				175	451				178	454					3	3
3150					473					475						2
3300																
3450																
3600																
3750																
3900																


NOTE: Pre-test measurements are taken when the vehicle is in the "As Tested" weight condition. Vehicle measurements forward of the vertical impact reference line are negative. The crush profile grid is established prior to the test based on an estimated impact point.

DATA SHEET NO. 11 (CONTINUED)
TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017


24



DATA SHEET NO. 12
MDB EXTERIOR STATIC CRUSH MEASUREMENTS

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017



FRONT VIEW

MAXIMUM STATIC CRUSH OF HONEYCOMB IMPACT FACE

Vertical Location			From Centerline		Maximum Crush
Row	Description	Height	Distance	Direction	
A	Center of Bumper	432	100	Right	249
B	Top of Bumper	533	800	Right	145
C	Mid-Level	686	0	Centerline	103
D	Top of Stack	813	800	Left	125


DEFORMABLE BARRIER STATIC CRUSH

Stack Level	Distance Right of Center (mm)								C _L	Distance Left of Center (mm)							
	800	700	600	500	400	300	200	100		0	100	200	300	400	500	600	700
4	67	41	26	33	50	65	68	95	123	100	77	74	69	70	77	87	125
3	75	45	46	55	55	52	66	96	103	82	46	40	40	45	55	67	89
2	145	126	125	121	125	126	117	126	115	109	105	108	114	139	140	139	138
1	229	230	227	229	232	235	235	249	247	236	227	217	217	219	219	220	219

**DATA SHEET NO. 13
VEHICLE AND MDB DAMAGE PROFILE DISTANCES**

Test Vehicle: 2018 Honda Odyssey EX Minivan
Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
Test Date: 8/10/2017



TOP VIEW

VEHICLE DAMAGE PROFILE DISTANCES

DPD	Distance from Impact Point (mm)	Level	Post-Test (mm)	Pre-Test (mm)	Max. Static Crush (mm)
1	2150	3	124	127	-3
2	1712	3	325	126	199
3	1274	3	311	133	178
4	836	3	303	135	168
5	398	3	300	135	165
6	-40	3	101	119	-18

MDB DAMAGE PROFILE DISTANCES

DPD	Distance from Impact Point (mm)	Level	Post-Test (mm)	Pre-Test (mm)	Max. Static Crush (mm)
1	800 mm right of center	1	705	476	229
2	480 mm right of center	1	698	465	233
3	160 mm right of center	1	701	461	240
4	160 mm left of center	1	688	461	227
5	480 mm left of center	1	686	465	221
6	800 mm left of center	1	695	476	219

DATA SHEET NO. 14
FMVSS NO. 301 STATIC ROLLOVER RESULTS

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test


NHTSA No. O20185302
 Test Date: 8/10/2017

Test Time: 12:30 pm

Temperature: 21.8 °C

- A. From impact until vehicle motion ceases: 0.0 oz.
 (Maximum Allowable = 1 ounce)
- B. For the 5 minute period after motion ceases: 0.0 oz.
- C. For the following 25 minutes: None
 (Maximum Allowable = 1 ounce / minute)
- D. Spillage Details: None

FMVSS 301 STATIC ROLLOVER DATA



ROLLOVER SOLVENT COLLECTION TIME TABLE IN SECONDS

Test Phase	Rotation Time	Hold Time	Total Time
0° to 90°	92	300	392
90° to 180°	91	300	391
180° to 270°	83	300	383
270° to 360°	86	300	386

FMVSS 301 ROLLOVER SPILLAGE TABLE (units in ounces)

Test Phase	First 5 Minutes	Sixth Minute	Seventh Minute	Eighth Minute
0° to 90°	0.0	0.0	0.0	
90° to 180°	0.0	0.0	0.0	
180° to 270°	0.0	0.0	0.0	
270° to 360°	0.0	0.0	0.0	


ROLLOVER SOLVENT SPILLAGE LOCATION TABLE

Test Phase	Spillage Location
0° to 90°	
90° to 180°	
180° to 270°	
270° to 360°	

DATA SHEET NO. 15
DUMMY/VEHICLE TEMPERATURE STABILIZATION DATA

Test Vehicle: 2018 Honda Odyssey EX Minivan
 Test Program: NCAP Side MDB Impact Test

NHTSA No. O20185302
 Test Date: 8/10/2017



**APPENDIX A
PHOTOGRAPHS**

TABLE OF PHOTOGRAPHS

		<u>Page No.</u>
Photo No. 001	As Delivered Right Front Three-Quarter View of Test Vehicle	A-1
Photo No. 002	As Delivered Left Rear Three-Quarter View of Test Vehicle	A-1
Photo No. 003	Pre-Test Frontal View of Test Vehicle	A-2
Photo No. 004	Post-Test Frontal View of Test Vehicle	A-2
Photo No. 005	Pre-Test Left Front Three-Quarter View of Test Vehicle	A-3
Photo No. 006	Post-Test Left Front Three-Quarter View of Test Vehicle	A-3
Photo No. 007	Pre-Test Left Side View of Test Vehicle	A-4
Photo No. 008	Post-Test Left Side View of Test Vehicle	A-4
Photo No. 009	Pre-Test Left Three-Quarter Rear View of Test Vehicle	A-5
Photo No. 010	Post-Test Left Three-Quarter Rear View of Test Vehicle	A-5
Photo No. 011	Pre-Test Rear View of Test Vehicle	A-6
Photo No. 012	Post-Test Rear View of Test Vehicle	A-6
Photo No. 013	Pre-Test Right Side View of Test Vehicle	A-7
Photo No. 014	Post-Test Right Side View of Test Vehicle	A-7
Photo No. 015	Pre-Test Overhead View of Test Area	A-8
Photo No. 016	Post-Test Overhead View of Test Area	A-8
Photo No. 017	Pre-Test Left Side View of MDB Positioned Against Side of Test Vehicle	A-9
Photo No. 018	Pre-Test Right Side View of MDB Positioned Against Side of Test Vehicle	A-9
Photo No. 019	Pre-Test Close-Up View of Impact Point Target	A-10
Photo No. 020	Post-Test Close-Up View of Impact Point Target	A-10
Photo No. 021	Pre-Test Left Front Door Latch Close-Up	A-11
Photo No. 022	Post-Test Left Front Door Latch Close-Up	A-11

		<u>Page No.</u>
Photo No. 023	Pre-Test Left Rear Door Latch Close-Up	A-12
Photo No. 024	Post-Test Left Rear Door Latch Close-Up	A-12
Photo No. 025	Pre-Test Front Close-Up View of Driver Dummy	A-13
Photo No. 026	Post-Test Front Close-Up View of Driver Dummy	A-13
Photo No. 027	Pre-Test Left Side View of Driver Dummy Showing Belt and Chalking	A-14
Photo No. 028	Pre-Test Left Side View of Driver Dummy Shoulder and Door Top View	A-14
Photo No. 029	Post-Test Left Side View of Driver Dummy Shoulder and Door Top View	A-15
Photo No. 030	Pre-Test Frontal View of Driver Seat Back Prior to Dummy Positioning	A-15
Photo No. 031	Pre-Test Frontal View of Driver Dummy Head and Shoulders in Relation to Head Restraint	A-16
Photo No. 032	Pre-Test Frontal View of Driver Seat Pan Prior to Dummy Positioning	A-16
Photo No. 033	Pre-Test Overhead View of Driver Dummy Thighs on Seat Pan	A-17
Photo No. 034	Pre-Test Placement of Driver Dummy's Feet	A-17
Photo No. 035	Pre-Test View of Belt Anchorage for Driver Dummy	A-18
Photo No. 036	Pre-Test Left Side View of Steering Wheel	A-18
Photo No. 037	Pre-Test View of Disengaged Parking Brake	A-19
Photo No. 038	Pre-Test View of Parking Brake	A-19
Photo No. 039	Pre-Test Close-Up Left Side View of Driver Seat Track	A-20
Photo No. 040	Pre-Test Close-Up Left Side View of Driver Seat Back	A-20
Photo No. 041	Pre-Test Close-Up View of Driver Seat Back or Head Restraint	A-21
Photo No. 042	Pre-Test Driver Dummy and Door Clearance View	A-21
Photo No. 043	Post-Test Driver Dummy and Door Clearance View	A-22
Photo No. 044	Pre-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment	A-22

		<u>Page No.</u>
Photo No. 045	Post-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment	A-23
Photo No. 046	Pre-Test Driver Inner Door Panel View	A-23
Photo No. 047	Post-Test Driver Inner Door Panel View	A-24
Photo No. 048	Post-Test Driver Dummy Close-up Head Contact with Vehicle Interior View	A-24
Photo No. 049	Post-Test Driver Dummy Close-up Head Contact with Side Airbag View	A-25
Photo No. 050	Post-Test Driver Dummy Close-up Torso Contact with Vehicle Interior View	A-25
Photo No. 051	Post-Test Driver Dummy Close-up Torso Contact with Side Airbag View	A-26
Photo No. 052	Post-Test Driver Dummy Close-up Pelvis Contact with Vehicle Interior View	A-26
Photo No. 053	Post-Test Driver Dummy Close-up Pelvis Contact with Side Airbag View	A-27
Photo No. 054	Post-Test Driver Dummy Close-up Knee Contact View	A-27
Photo No. 055	Pre-Test Left Side View of Rear Passenger Dummy Showing Belt and Chalking	A-28
Photo No. 056	Pre-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View	A-28
Photo No. 057	Post-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View	A-29
Photo No. 058	Pre-Test Frontal View of Rear Passenger Seat Back Prior to Dummy Positioning	A-29
Photo No. 059	Pre-Test Frontal View of Rear Passenger Dummy Head and Shoulders in Relation to Head Restraint	A-30
Photo No. 060	Pre-Test Overhead View of Rear Passenger Seat Pan Prior to Dummy Positioning	A-30
Photo No. 061	Pre-Test Overhead View of Rear Passenger Dummy Thighs on Seat Pan	A-31
Photo No. 062	Pre-Test View of Rear Passenger Dummy's Neck Showing Position of Adjustable Neck Bracket	A-31
Photo No. 063	Pre-Test View of Rear Passenger Dummy's Head Showing Dummy's Head is Level	A-32
Photo No. 064	Pre-Test Placement of Rear Passenger Dummy's Feet	A-32
Photo No. 065	Pre-Test View of Belt Anchorage for Rear Passenger Dummy	A-33
Photo No. 066	Pre-Test Close-Up Left Side View of Rear Passenger Seat Track	A-33

		<u>Page No.</u>
Photo No. 067	Pre-Test Close-Up Left Side View of Rear Passenger Seat Back	A-34
Photo No. 068	Pre-Test Close-up View of Rear Passenger Seat Back or Head Restraint	A-34
Photo No. 069	Pre-Test Rear Passenger Dummy and Door Clearance View	A-35
Photo No. 070	Post-Test Rear Passenger Dummy and Door Clearance View	A-35
Photo No. 071	Pre-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment	A-36
Photo No. 072	Post-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment	A-36
Photo No. 073	Pre-Test Rear Passenger Inner Door Panel View	A-37
Photo No. 074	Post-Test Rear Passenger Inner Door Panel View	A-37
Photo No. 075	Post-Test Rear Passenger Dummy Close-up Head Contact with Vehicle Interior View	A-38
Photo No. 076	Post-Test Rear Passenger Dummy Close-up Head Contact with Side Airbag View	A-38
Photo No. 077	Post-Test Rear Passenger Dummy Close-up Torso Contact with Vehicle Interior View	A-39
Photo No. 078	Post-Test Rear Passenger Dummy Close-up Torso Contact with Side Airbag View	A-39
Photo No. 079	Post-Test Rear Passenger Dummy Close-up Pelvis Contact with Vehicle Interior View	A-40
Photo No. 080	Post-Test Rear Passenger Dummy Close-up Pelvis Contact with Side Airbag View	A-40
Photo No. 081	Post-Test Rear Passenger Dummy Close-up Knee Contact View	A-41
Photo No. 082	Pre-Test View of Fuel Filler Cap or Fuel Filler Neck	A-41
Photo No. 083	Post-Test View of Fuel Filler Cap or Fuel Filler Neck	A-42
Photo No. 084	Pre-Test Front View of MDB Impactor Face	A-42
Photo No. 085	Post-Test Front View of MDB Impactor Face	A-43
Photo No. 086	Pre-Test Top View of MDB Impactor Face	A-43
Photo No. 087	Post-Test Top View of MDB Impactor Face	A-44
Photo No. 088	Pre-Test Left Side View of MDB Impactor Face	A-44

		<u>Page No.</u>
Photo No. 089	Post-Test Left Side View of MDB Impactor Face	A-45
Photo No. 090	Pre-Test Right Side View of MDB Impactor Face	A-45
Photo No. 091	Post-Test Right Side View of MDB Impactor Face	A-46
Photo No. 092	Close-Up View of Vehicle's Certification Label	A-46
Photo No. 093	Close-Up View of Vehicle's Tire Information Placard or Label	A-47
Photo No. 094	Pre-Test Ballast View	A-47
Photo No. 095	Post-Test Primary and Redundant Speed Trap Read-Out	A-48
Photo No. 096	FMVSS No. 301 Static Rollover 0 Degrees	A-48
Photo No. 097	FMVSS No. 301 Static Rollover 90 Degrees	A-49
Photo No. 098	FMVSS No. 301 Static Rollover 180 Degrees	A-49
Photo No. 099	FMVSS No. 301 Static Rollover 270 Degrees	A-50
Photo No. 100	FMVSS No. 301 Static Rollover 360 Degrees	A-50
Photo No. 101	Impact Event	A-51
Photo No. 102	Monroney Label	A-51
Photo No. 103	Head Restraint Use and Adjustment Information from Vehicle Owner's Manual	A-52



Photo No. 001 - As Delivered Right Front Three-Quarter View of Test Vehicle



Photo No. 002 - As Delivered Left Rear Three-Quarter View of Test Vehicle




Photo No. 003 - Pre-Test Frontal View of Test Vehicle



Photo No. 004 - Post-Test Frontal View of Test Vehicle



Photo No. 005 - Pre-Test Left Front Three-Quarter View of Test Vehicle




Photo No. 006 - Post-Test Left Front Three-Quarter View of Test Vehicle



Photo No. 007 - Pre-Test Left Side View of Test Vehicle



Photo No. 008 - Post-Test Left Side View of Test Vehicle



Photo No. 009 - Pre-Test Left Three-Quarter Rear View of Test Vehicle



Photo No. 010 - Post-Test Left Three-Quarter Rear View of Test Vehicle




Photo No. 011 - Pre-Test Rear View of Test Vehicle




Photo No. 012 - Post-Test Rear View of Test Vehicle



Photo No. 013 - Pre-Test Right Side View of Test Vehicle



Photo No. 014 - Post-Test Right Side View of Test Vehicle



Photo No. 015 - Pre-Test Overhead View of Test Area




Photo No. 016 - Post-Test Overhead View of Test Area



Photo No. 017 - Pre-Test Left Side View of MDB Positioned Against Side of Test Vehicle



Photo No. 018 - Pre-Test Right Side View of MDB Positioned Against Side of Test Vehicle



Photo No. 019 - Pre-Test Close-Up View of Impact Point Target



Photo No. 020 - Post-Test Close-Up View of Impact Point Target



Photo No. 021 - Pre-Test Left Front Door Latch Close-Up



Photo No. 022 - Post-Test Left Front Door Latch Close-Up




Photo No. 023 - Pre-Test Left Rear Door Latch Close-Up




Photo No. 024 - Post-Test Left Rear Door Latch Close-Up



Photo No. 025 - Pre-Test Front Close-Up View of Driver Dummy



Photo No. 026 - Post-Test Front Close-Up View of Driver Dummy



Photo No. 027 - Pre-Test Left Side View of Driver Dummy Showing Belt and Chalking



Photo No. 028 - Pre-Test Left Side View of Driver Dummy Shoulder and Door Top View



Photo No. 029 - Post-Test Left Side View of Driver Dummy Shoulder and Door Top View




Photo No. 030 - Pre-Test Frontal View of Driver Seat Back Prior to Dummy Positioning

PHOTOGRAPH NOT AVAILABLE

Photo No. 031 - Pre-Test Frontal View of Driver Dummy Head and Shoulders in Relation to Head Restraint

PHOTOGRAPH NOT AVAILABLE

Photo No. 032 - Pre-Test Frontal View of Driver Seat Pan Prior to Dummy Positioning



Photo No. 033 - Pre-Test Overhead View of Driver Dummy Thighs on Seat Pan



Photo No. 034 - Pre-Test Placement of Driver Dummy Feet



Photo No. 035 - Pre-Test View of Belt Anchorage for Driver Dummy



Photo No. 036 - Pre-Test Left Side View of Steering Wheel



Photo No. 037 - Pre-Test View of Disengaged Parking Brake




Photo No. 038 - Pre-Test View of Parking Brake

PHOTOGRAPH NOT AVAILABLE

Photo No. 039 - Pre-Test Close-Up Left Side View of Driver Seat Track



Photo No. 040 - Pre-Test Close-Up Left Side View of Driver Seat Back



Photo No. 041 - Pre-Test Close-Up View of Driver Seat Back or Head Restraint



Photo No. 042 - Pre-Test Driver Dummy and Door Clearance View



Photo No. 043 - Post-Test Driver Dummy and Door Clearance View



Photo No. 044 - Pre-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment



Photo No. 045 - Post-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment




Photo No. 046 - Pre-Test Driver Inner Door Panel View



Photo No. 047 - Post-Test Driver Inner Door Panel View



Photo No. 048 - Post-Test Driver Dummy Close-up Head Contact with Vehicle Interior View



Photo No. 049 - Post-Test Driver Dummy Close-up Head Contact with Side Airbag View



Photo No. 050 - Post-Test Driver Dummy Close-up Torso Contact with Vehicle Interior View



Photo No. 051 - Post-Test Driver Dummy Close-up Torso Contact with Side Airbag View



Photo No. 052 - Post-Test Driver Dummy Close-up Pelvis Contact with Vehicle Interior View



Photo No. 053 - Post-Test Driver Dummy Close-up Pelvis Contact with Side Airbag View




Photo No. 054 - Post-Test Driver Dummy Close-up Knee Contact View



Photo No. 055 - Pre-Test Left Side View of Rear Passenger Dummy Showing Belt and Chalking



Photo No. 056 - Pre-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View



Photo No. 057 - Post-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View




Photo No. 058 - Pre-Test Frontal View of Rear Passenger Seat Back Prior to Dummy Positioning




Photo No. 059 - Pre-Test Frontal View of Rear Passenger Dummy Head and Shoulders in Relation to Head Restraint

PHOTOGRAPH NOT APPLICABLE

Photo No. 060 - Pre-Test Overhead View of Rear Passenger Seat Pan Prior to Dummy Positioning



Photo No. 061 - Pre-Test Overhead View of Rear Passenger Dummy Thighs on Seat Pan



Photo No. 062 - Pre-Test View of Rear Passenger Dummy Neck Showing Position of Adjustable Neck Bracket




Photo No. 063 - Pre-Test View of Rear Passenger Dummy Head Showing Dummy Head is Level



Photo No. 064 - Pre-Test Placement of Rear Passenger Dummy Feet



Photo No. 065 - Pre-Test View of Belt Anchorage for Rear Passenger Dummy




Photo No. 066 - Pre-Test Close-Up Left Side View of Rear Passenger Seat Track



Photo No. 067 - Pre-Test Close-Up Left Side View of Rear Passenger Seat Back



Photo No. 068 - Pre-Test Close-up View of Rear Passenger Seat Back or Head Restraint



Photo No. 069 - Pre-Test Rear Passenger Dummy and Door Clearance View



Photo No. 070 - Post-Test Rear Passenger Dummy and Door Clearance View



Photo No. 071 - Pre-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment



Photo No. 072 - Post-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment

PHOTOGRAPH NOT AVAILABLE

Photo No. 073 - Pre-Test Rear Passenger Inner Door Panel View



Photo No. 074 - Post-Test Rear Passenger Inner Door Panel View



Photo No. 075 - Post-Test Rear Passenger Dummy Close-up Head Contact with Vehicle Interior View



Photo No. 076 - Post-Test Rear Passenger Dummy Close-up Head Contact with Side Airbag View



Photo No. 077 - Post-Test Rear Passenger Dummy Close-up Torso Contact with Vehicle Interior View




Photo No. 078 - Post-Test Rear Passenger Dummy Close-up Torso Contact with Side Airbag View



Photo No. 079 - Post-Test Rear Passenger Dummy Close-up Pelvis Contact with Vehicle Interior View




Photo No. 080 - Post-Test Rear Passenger Dummy Close-up Pelvis Contact with Side Airbag View



Photo No. 081 - Post-Test Rear Passenger Dummy Close-up Knee Contact View



Photo No. 082 - Pre-Test View of Fuel Filler Cap or Fuel Filler Neck



Photo No. 083 - Post-Test View of Fuel Filler Cap or Fuel Filler Neck




Photo No. 084 - Pre-Test Front View of MDB Impactor Face



Photo No. 085 - Post-Test Front View of MDB Impactor Face




Photo No. 086 - Pre-Test Top View of MDB Impactor Face



Photo No. 087 - Post-Test Top View of MDB Impactor Face



Photo No. 088 - Pre-Test Left Side View of MDB Impactor Face



Photo No. 089 - Post-Test Left Side View of MDB Impactor Face



Photo No. 090 - Pre-Test Right Side View of MDB Impactor Face



Photo No. 091 - Post-Test Right Side View of MDB Impactor Face




Photo No. 092 - Close-Up View of Vehicle Certification Label




Photo No. 093 - Close-Up View of Vehicle Tire Information Placard or Label




Photo No. 094 - Pre-Test Ballast View



Photo No. 095 - Post-Test Primary and Redundant Speed Trap Read-Out



Photo No. 096 - FMVSS Photo No. 301 Static Rollover 0 Degrees




Photo No. 097 - FMVSS Photo No. 301 Static Rollover 90 Degrees




Photo No. 098 - FMVSS Photo No. 301 Static Rollover 180 Degrees



Photo No. 099 - FMVSS Photo No. 301 Static Rollover 270 Degrees



Photo No. 100 - FMVSS Photo No. 301 Static Rollover 360 Degrees




Photo No. 101 - Impact Event

HONDA

2018 ODYSSEY EX
 EXT: PACIFIC PEWTER M. ENGINE NUMBER: J35Y7-1024682
 INT: MOCHA

STANDARD EQUIPMENT AT NO EXTRA COST

- TECHNICAL FEATURES***
 - 280hp 3.5-Liter VTEC V6 Engine with Variable Cylinder Management (VCM)
 - 9-Speed Automatic Transmission
 - Paddle Shifters
 - Intelligent Traction Management
 - Electric Power Steering
- SAFETY FEATURES***
 - Driver's and Front Passenger's Airbags
 - Driver's and Front Passenger's Side Airbags
 - Three Row Side Curtain Airbags
 - Driver's and Front Passenger's Knee Airbags
 - Vehicle Stability Assist (VSA)
 - Anti-Lock Braking System (ABS)
 - Electronic Brake Distribution (EBD)
 - Tire Pressure Monitoring System
 - LED Daytime Running Lights
 - LATCH System for Child Seats
- INTERIOR FEATURES***
 - Audio System with 7 Speakers
 - Display Audio with Multi-View Rear Camera
 - TFT Meter Display
 - CarPlay/Android Auto Integration
 - SiriusXM Satellite Radio
 - HD Radio
 - HondaLink with Smart Phone Integration
 - Bluetooth HandsFreeLink
 - CabinControl Capability
 - USB Audio Interface

Manufacturer's Suggested Retail Price
\$33,860.00

Full Tank of Fuel **No Charge**

- SiriusXM Includes: Free Activation and 3 Months Free Service (excl. AK & HI)
- Honda Roadside Assistance 3YR/36K Mile Warranty Term

Destination and Handling 940.00

TOTAL VEHICLE PRICE
 (includes Pre-Delivery Service)
\$34,800.00

License and title fees, state and local taxes and dealer options and accessories are not included in the manufacturer's suggested retail price.

EXTERIOR FEATURES*

- Push-Button Start
- Tp-Zone Automatic Climate Control
- Driver's 12-Way Power Seat
- Heated Front Seats
- Front Passenger's 4-Way Power Seat
- Tilt & Telescopic Steering Column
- Illuminated Visor Vanity Mirrors
- Magic Slide 2nd Row Seats
- 60/40 Fold-Down 3rd Row
- Floor Mats
- Second-Row Sunshades

EPA DOT Fuel Economy and Environment Gasoline Vehicle

These estimates reflect new EPA methods beginning with 2017 models. Minivans range from 19 to 32 MPG. The best vehicle rates 128 MPG.

Fuel Economy
22 19 28 MPG
combined city/hwy city highway

You spend \$1,500 in fuel costs over 5 years compared to the average new vehicle.

Annual fuel cost \$1,650

Fuel Economy & Greenhouse Gas Rating (tailpipe only) **Smog Rating** (tailpipe only)

1 4 10 1 3 10
Best Best

This vehicle emits 406 grams CO₂ per mile. The best emits 0 grams per mile (tailpipe only). Producing and distributing fuel also create emissions. Learn more at fuel-economy.gov

Actual results will vary for many reasons, including driving conditions and how you drive and maintain your vehicle. The average new vehicle gets 27 MPG and costs 46,750 to fuel over 5 years. Cost estimates are based on 15,000 miles per year at \$2.40 per gallon. MPG is miles per gasoline gallon consumed. Vehicle emissions are a significant cause of climate change and smog.

fuel-economy.gov
Calculate personalized estimates on 3-estimate vehicles.

PARTS CONTENT INFORMATION

FOR VEHICLES IN THIS CARLINE
 U.S./Canadian Parts Content: **75 %**

NOTE: Parts content does not include final assembly, distribution or other non-parts costs.

GOVERNMENT 5-STAR SAFETY RATING

Overall Vehicle Score Not Rated
Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and weight.

Frontal Crash	Driver Passenger	Not Rated Not Rated
<small>Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and weight.</small>		
Side Crash	Front seat Rear seat	Not Rated Not Rated
<small>Based on the risk of injury in a side impact.</small>		
Rollover		Not Rated
<small>Based on the risk of rollover in a single vehicle crash.</small>		

Star Ratings range from 1 to 5 stars (★★★★★) with 5 being the highest. Source: National Highway Traffic Safety Administration (NHTSA). www.safercar.gov or 1-888-327-4236

DAVID HOBBS HONDA
 6100 NO. GREEN BAY AVE
 GLENDALE, WI 53209

VIN: 5FNRL6H50JB017336

PORT OF ENTRY: ALABAMA
 DELIVERY POINT: SCHAUMBURG
 SHIP#:
 ROW/SPACE: 735-007
 TRANS METHOD: E62 TALLADEGA
 N50 ELWOOD

ORIG. DLR: 207671
 REF. NO: 40832
 HN CODE: HN-9446
 EMISSION: 50 STATE
 CONTROL NO: 279223
 DEALER: 207671

FOR THIS VEHICLE
 Final Assembly Point:
**LINCOLN, ALABAMA
 USA**

Country of Origin: Engine:
U.S.A.

Transmission:
U.S.A.

Photo No. 102 - Monroney Label

- ⚠ WARNING**
Reclining the seat-back too far can result in serious injury or death in a crash.
Adjust the seat-back to an upright position and sit well back in the seat.
- ⚠ WARNING**
Sitting too close to a front airbag can result in serious injury or death if the front airbags inflate.
Always sit as far back from the front airbags as possible while maintaining control of the vehicle.
- ⚠ WARNING**
Sitting improperly or out of position can result in serious injury or death in a crash.
Always sit upright, well back in the seat, with your feet on the floor.

Lumbar Support Adjustment Switch*


- Press the top:** To move the lumbar support up.
- Press the bottom:** To move the lumbar support down.
- Press the front:** To increase the entire lumbar support.
- Press the rear:** To decrease the entire lumbar support.



Adjusting the Head Restraints

Your vehicle is equipped with head restraints in all seating positions. Head restraints are most effective for protection against whiplash and other rear-impact crash injuries.

The center of the back of the occupant's head should rest against the center of the restraint. The tops of the occupant's ears should be level with the center height of the restraint.



*if equipped 47

- NAVIGATION
- DRIVING
- HANDLING THE UNEXPECTED
- MAINTENANCE
- SPECIFICATIONS
- CUSTOMER INFORMATION
- VOICE COMMAND INDEX
- INDEX
- TABLE OF CONTENTS
- VISUAL INDEX
- SAFETY INFORMATION
- INSTRUMENT PANEL
- VEHICLE CONTROLS
- AUDIO AND CONNECTIVITY
- BLUETOOTH®/HANDSFREELINK®
- HONDALINK®

To raise the head restraint: Pull it upward.



To lower the head restraint: Push it down while pressing the release button.



To remove the head restraint: Pull the restraint up as far as it will go. Then push the release button and pull the restraint up and out.

To reinstall a head restraint: Insert the legs back in place. Adjust the head restraint to an appropriate height while pressing the release button. Pull up on the restraint to make sure it is locked in position.

⚠ WARNING

Improperly positioning head restraints reduces their effectiveness and increases the likelihood of serious injury in a crash.

Make sure head restraints are in place and positioned properly before driving.

⚠ WARNING

Failure to reinstall or correctly reinstall the head restraints can result in severe injury during a crash.

Always replace the head restraints before driving.

For a head restraint system to work properly:

- Do not hang any items on the head restraint or from the restraint legs.
- Do not place any objects between an occupant and the seat-back.
- Install each restraint in its proper location.

Photo No. 103 - Head Restraint Use and Adjustment Information from Vehicle Owners Manual

APPENDIX B
DUMMY RESPONSE DATA PLOTS

TABLE OF DATA PLOTS
Driver Dummy Instrumentation Plots

<u>No.</u>	<u>Description</u>	<u>Page No.</u>
Figure No. 1.	Driver Head Acceleration (X) Primary vs. Time	B-1
Figure No. 2.	Driver Head Acceleration (Y) Primary vs. Time	B-1
Figure No. 3.	Driver Head Acceleration (Z) Primary vs. Time	B-1
Figure No. 4.	Driver Head Resultant Acceleration Primary vs. Time	B-1
Figure No. 5.	Driver Upper Thorax Rib Deflection (Y) vs. Time	B-2
Figure No. 6.	Driver Middle Thorax Rib Deflection (Y) vs. Time	B-2
Figure No. 7.	Driver Lower Thorax Rib Deflection (Y) vs. Time	B-2
Figure No. 8.	Driver Thorax Rib Deflection Maximum vs. Time	B-2
Figure No. 9.	Driver Anterior Abdomen Force (Y) vs. Time	B-3
Figure No. 10.	Driver Middle Abdomen Force (Y) vs. Time	B-3
Figure No. 11.	Driver Posterior Abdomen Force (Y) vs. Time	B-3
Figure No. 12.	Driver Total Abdominal Force (Y) vs. Time	B-3
Figure No. 13.	Driver Pubic Symphysis Force (Y) vs. Time	B-4
Figure No. 14.	Passenger Head Acceleration (X) Primary vs. Time	B-5
Figure No. 15.	Passenger Head Acceleration (Y) Primary vs. Time	B-5
Figure No. 16.	Passenger Head Acceleration (Z) Primary vs. Time	B-5
Figure No. 17.	Passenger Head Resultant Acceleration Primary vs. Time	B-5
Figure No. 18.	Passenger Lower Spine T12 Acceleration (X) vs. Time	B-6
Figure No. 19.	Passenger Lower Spine T12 Acceleration (Y) vs. Time	B-6
Figure No. 20.	Passenger Lower Spine T12 Acceleration (Z) vs. Time	B-6
Figure No. 21.	Passenger Lower Spine T12 Resultant Acceleration vs. Time	B-6
Figure No. 22.	Passenger Iliac Force on Impact Side (Y) vs. Time	B-7
Figure No. 23.	Passenger Acetabulum Force on Impact Side (Y) vs. Time	B-7
Figure No. 24.	Passenger Total Pelvic Force on Impact Side (Y) vs. Time	B-7

The following additional data for this test can be obtained from the Research and Development section of the NHTSA website. The website can be found at www.NHTSA.dot.gov

Additional Driver & Passenger Dummy Instrumentation Data

Passenger Head Angular Velocity (X)
Passenger Head Angular Velocity (Y)
Passenger Head Angular Velocity (Z)
Driver Lower Spine T12 Acceleration (X)
Driver Lower Spine T12 Acceleration (Y)
Driver Lower Spine T12 Acceleration (Z)
Passenger Upper Thorax Rib Deflection (Y)
Passenger Middle Thorax Rib Deflection (Y)
Passenger Lower Thorax Rib Deflection (Y)
Passenger Upper Abdomen Rib Deflection (Y)
Passenger Lower Abdomen Rib Deflection (Y)
Driver Head Acceleration Redundant (X)
Driver Head Acceleration Redundant (Y)
Driver Head Acceleration Redundant (Z)
Passenger Head Acceleration Redundant (X)
Passenger Head Acceleration Redundant (Y)
Passenger Head Acceleration Redundant (Z)

Vehicle Instrumentation Data

Vehicle Center of Gravity Acceleration (X)
Vehicle Center of Gravity Acceleration (Y)
Vehicle Center of Gravity Acceleration (Z)
Right Side Sill at Front Seat Acceleration (X)
Right Side Sill at Front Seat Acceleration (Y)
Right Side Sill at Front Seat Acceleration (Z)
Right Side Sill at Rear Seat Acceleration (X)
Right Side Sill at Rear Seat Acceleration (Y)
Right Side Sill at Rear Seat Acceleration (Z)
Left Side Sill at Front Seat Acceleration (Y)
Left Side Sill at Rear Seat Acceleration (Y)
Lower A-Post Acceleration (Y)
Middle A-Post Acceleration (Y)
Lower B-Post Acceleration (Y)
Middle B-Post Acceleration (Y)
Front Seat Track Acceleration (Y)
Rear Seat Track Acceleration (Y)
Right Rear Occupant Compartment Acceleration (Y)
Engine Block (X)
Engine Block (Y)
Rear Floorpan Above Axle Acceleration (X)
Rear Floorpan Above Axle Acceleration (Y)
Rear Floorpan Above Axle Acceleration (Z)

MDB Instrumentation Data

MDB Center of Gravity Acceleration (X)

MDB Center of Gravity Acceleration (Y)





MDB Center of Gravity Acceleration (Z)

MDB Rear Acceleration (X)


MDB Rear Acceleration (Y)

Left MDB Contact Switch


Right MDB Contact Switch




DRIVER UPPER RIB DISPLACEMENT (mm) vs Time (msec)




DRIVER MID RIB DISPLACEMENT (mm) vs Time (msec)








DRIVER LOWER RIB DISPLACEMENT (mm) vs Time (msec)











DRIVER MAXIMUM RIB DISPLACEMENT (mm) vs Time (msec)
















APPENDIX C
DUMMY CONFIGURATION AND PERFORMANCE VERIFICATION DATA

ES-2re External Measurements
SN: 032

No.	Name	Spec. (mm)	Result	Pass/Fail
1	Sitting Height	900 - 918	915	Pass
2	Seat to Shoulder Joint	558 - 572	568	Pass
3	Seat to Lower Face of Thoracic Spine Box	346 - 356	355	Pass
4	Seat to Hip Joint (center of bolt)	97 - 103	98	Pass
5	Sole to Seat, Sitting	333 - 451	440	Pass
6	Head Width	152 - 158	157	Pass
7	Shoulder/Arm Width	461 - 479	464	Pass
8	Thorax Width	322 - 332	323	Pass
9	Abdomen Width	273 - 287	281	Pass
10	Pelvis Lap Width	359 - 373	370	Pass
11	Head Depth	196 - 206	203	Pass
12	Thorax Depth	262 - 272	264	Pass
13	Abdomen Depth	194 - 204	196	Pass
14	Pelvis Depth	235 - 245	236	Pass
15	Back of Buttocks to Hip Joint (center of bolt)	150 - 160	151	Pass
16	Back of Buttocks to Front Knee	597 - 615	607	Pass

MGA RESEARCH CORPORATION

HEAD DROP TEST

ES-2re DUMMY

ATD Serial No: 032

Test ID: D171871


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	18.9 to 25.6	21.4	Pass
Laboratory Relative Humidity	%	10 to 70	58	Pass
Peak Resultant Acceleration	G's	125 to 155	131	Pass
Peak Longitudinal Acceleration	G's	<= +/- 15.0	7.3	Pass
Unimodal	N/A	Yes	Yes	Pass
Oscillations	N/A	within 15% of peak	Yes	Pass
Overall Test Results				Pass





 Laboratory Technician



07/11/2017

 Test Date



 Approved By





MGA RESEARCH CORPORATION
NECK PENDULUM TEST
ES-2re DUMMY


ATD Serial No: 032



Test I.D.: D171872



Tested Parameter		Units	Specification	Result	Pass/Fail
Laboratory Temperature		deg C	20.6 to 22.2	21.4	Pass
Laboratory Relative Humidity		%	10 to 70	58	Pass
Pendulum Speed		m/s	3.30 to 3.50	3.50	Pass
Pendulum Velocity	1 ms	m/s	-0.05 to 0.00	-0.00	Pass
	3 ms	m/s	-0.25 to -0.375	-0.33	Pass
	14 ms	m/s	-3.20 to -3.70	-3.51	Pass
	17 ms	m/s	>= -3.70	-3.43	Pass
Maximum Flexion Angle		deg	49.0 to 59.0	50.2	Pass
Time of Maximum Flexion Angle		ms	54.0 to 66.0	58.3	Pass
Head Rotation Decay Time to 0 Degree		ms	53.0 to 88.0	60.6	Pass
Overall Results					Pass



 Laboratory Technician

07/11/2017
 Test Date


 Approved By







MGA RESEARCH CORPORATION
SHOULDER IMPACT TEST
ES-2re DUMMY

ATD Serial No: 032

Test I.D: D171873


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.1	Pass
Laboratory Relative Humidity	%	10 to 70	49	Pass
Pendulum Speed	m/s	4.20 to 4.40	4.34	Pass
Peak Impactor Acceleration	G's	7.5 to 10.5	9.8	Pass
Overall Test Results				Pass



 Laboratory Technician

07/11/2017

 Test Date




 Approved By



TEST DESC: SHOULDER IMPACT
VELOCITY: 14.25 ft/s, 4.34 m/s

TEST DATE: 07/11/2017
TEST #: D171873



MGA RESEARCH CORPORATION

UPPER RIB TEST

ES-2re DUMMY


ATD Serial No: 032

Test I.D: D171874

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.1	Pass
Laboratory Relative Humidity	%	10 to 70	49	Pass
Displacement at 459 mm	mm	36.0 to 40.0	37.4	Pass
Displacement at 815 mm	mm	46.0 to 51.0	47.1	Pass
Overall Test Results				Pass



Laboratory Technician

07/11/2017
Test Date



Approved By



UPPER RIB DISPLACEMENT @ 459 mm (mm) vs TIME (ms)



UPPER RIB DISPLACEMENT @ 815 mm (mm) vs TIME (ms)



MGA RESEARCH CORPORATION


MID RIB TEST

ES-2re DUMMY

ATD Serial No: 032



Test I.D: D171875

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.1	Pass
Laboratory Relative Humidity	%	10 to 70	49	Pass
Displacement at 459 mm	mm	36.0 to 40.0	36.6	Pass
Displacement at 815 mm	mm	46.0 to 51.0	48.0	Pass
Overall Test Results				Pass


Laboratory Technician

07/11/2017
Test Date


Approved By



MGA RESEARCH CORPORATION

LOWER RIB TEST

ES-2re DUMMY


ATD Serial No: 032

Test I.D: D171876

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.1	Pass
Laboratory Relative Humidity	%	10 to 70	49	Pass
Displacement at 459 mm	mm	36.0 to 40.0	37.4	Pass
Displacement at 815 mm	mm	46.0 to 51.0	49.7	Pass
Overall Test Results				Pass



Laboratory Technician

07/11/2017
Test Date



Approved By



LOWER RIB DISPLACEMENT @ 459 mm (mm) vs TIME (ms)



LOWER RIB DISPLACEMENT @ 815 mm (mm) vs TIME (ms)



MGA RESEARCH CORPORATION


ABDOMEN TEST

ES-2re DUMMY

ATD Serial No: 032

Test I.D: D171877


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.1	Pass
Laboratory Relative Humidity	%	10 to 70	49	Pass
Probe Speed	m/s	3.90 to 4.10	4.10	Pass
Maximum Impactor Force	N	4000 to 4800	4474	Pass
Time of Maximum Impactor Force	ms	10.6 to 13.0	12.1	Pass
Maximum Total Abdomen Force	N	2200 to 2700	2390	Pass
Time of Maximum Abdomen Force	ms	10.0 to 12.3	11.7	Pass
Overall Test Results				Pass





Laboratory Technician



07/11/2017


Test Date



Approved By







MGA RESEARCH CORPORATION
LUMBAR SPINE TEST
ES-2re DUMMY


ATD Serial No: 032



Test I.D.: D171878



Tested Parameter	Units	Specification	Result	Pass/Fail	
Laboratory Temperature	deg C	20.6 to 22.2	21.4	Pass	
Laboratory Relative Humidity	%	10 to 70	58	Pass	
Pendulum Speed	m/s	5.95 to 6.15	6.12	Pass	
Pendulum Velocity	1 ms	m/s	-0.05 to 0.00	-0.01	Pass
	3.7 ms	m/s	-0.425 to -0.24	-0.419	Pass
	27 ms	m/s	-6.50 to -5.80	-6.10	Pass
	30 ms	m/s	>= -6.50	-6.07	Pass
Maximum Flexion Angle	deg	45.0 to 55.0	46.4	Pass	
Time of Maximum Flexion Angle	ms	39.0 to 53.0	45.8	Pass	
Headform Rotation Decay to Initial Position	ms	37 to 57	48	Pass	
Overall Results				Pass	



 Laboratory Technician

07/11/2017
 Test Date


 Approved By








MGA RESEARCH CORPORATION

**PELVIS TEST
ES-2re DUMMY**

ATD Serial No: 032

Test I.D: D171879


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.1	Pass
Laboratory Relative Humidity	%	10 to 70	49	Pass
Probe Speed	m/s	4.20 to 4.40	4.23	Pass
Maximum Impactor Force	N	4700 to 5400	4767	Pass
Time of Maximum Impactor Force	ms	11.8 to 16.1	14.0	Pass
Maximum Pubic Force	N	1230 to 1590	1260	Pass
Time of Maximum Pubic Force	ms	12.2 to 17.0	15.7	Pass
Overall Test Results				Pass





 Laboratory Technician

07/11/2017

 Test Date



 Approved By




MGA RESEARCH CORPORATION
THORAX IMPACT TEST
ES-2re DUMMY


ATD Serial No: 032



Test I.D: D171870

Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.1	Pass
Humidity	%	10 to 70	49	Pass
Probe Speed	m/s	5.40 to 5.60	5.58	Pass
Maximum Impactor Force (after 6 ms)	N	5100 to 6200	5725	Pass
Upper Rib Displacement	mm	34.0 to 41.0	37.9	Pass
Middle Rib Displacement	mm	37.0 to 45.0	41.1	Pass
Lower Rib Displacement	mm	37.0 to 44.0	40.4	Pass
Overall Test Results				Pass


 Laboratory Technician


07/11/2017
 Test Date


 Approved By






MIDDLE RIB DISPLACEMENT (mm) vs TIME (ms)



LOWER RIB DISPLACEMENT (mm) vs TIME (ms)



ES-2re External Measurements
SN: 032

No.	Name	Spec. (mm)	Result	Pass/Fail
1	Sitting Height	900 - 918	915	Pass
2	Seat to Shoulder Joint	558 - 572	568	Pass
3	Seat to Lower Face of Thoracic Spine Box	346 - 356	355	Pass
4	Seat to Hip Joint (center of bolt)	97 - 103	98	Pass
5	Sole to Seat, Sitting	333 - 451	440	Pass
6	Head Width	152 - 158	157	Pass
7	Shoulder/Arm Width	461 - 479	464	Pass
8	Thorax Width	322 - 332	323	Pass
9	Abdomen Width	273 - 287	281	Pass
10	Pelvis Lap Width	359 - 373	370	Pass
11	Head Depth	196 - 206	203	Pass
12	Thorax Depth	262 - 272	264	Pass
13	Abdomen Depth	194 - 204	196	Pass
14	Pelvis Depth	235 - 245	236	Pass
15	Back of Buttocks to Hip Joint (center of bolt)	150 - 160	151	Pass
16	Back of Buttocks to Front Knee	597 - 615	607	Pass

MGA RESEARCH CORPORATION
HEAD DROP TEST
ES-2re DUMMY

ATD Serial No: 032



Test ID: D172161



Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	18.9 to 25.6	22.0	Pass
Laboratory Relative Humidity	%	10 to 70	46	Pass
Peak Resultant Acceleration	G's	125 to 155	136	Pass
Peak Longitudinal Acceleration	G's	<= +/- 15.0	6.5	Pass
Unimodal	N/A	Yes	Yes	Pass
Oscillations	N/A	within 15% of peak	Yes	Pass
Overall Test Results				Pass

Danielle Redinlaugh
 Laboratory Technician

08/11/2017
 Test Date

Robert Schaub
 Approved By






**MGA RESEARCH CORPORATION
NECK PENDULUM TEST
ES-2re DUMMY**

ATD Serial No: 032

Test I.D.: D172162


Tested Parameter	Units	Specification	Result	Pass/Fail	
Laboratory Temperature	deg C	20.6 to 22.2	21.5	Pass	
Laboratory Relative Humidity	%	10 to 70	44	Pass	
Pendulum Speed	m/s	3.30 to 3.50	3.46	Pass	
Pendulum Velocity	1 ms	m/s	-0.05 to 0.00	-0.00	Pass
	3 ms	m/s	-0.25 to -0.375	-0.33	Pass
	14 ms	m/s	-3.20 to -3.70	-3.40	Pass
	17 ms	m/s	>= -3.70	-3.38	Pass
Maximum Flexion Angle	deg	49.0 to 59.0	49.4	Pass	
Time of Maximum Flexion Angle	ms	54.0 to 66.0	58.7	Pass	
Head Rotation Decay Time to 0 Degree	ms	53.0 to 88.0	55.1	Pass	
Overall Results				Pass	





 Laboratory Technician



08/11/2017

 Test Date



 Approved By








TEST DESC: NECK BENDING
VELOCITY: 11.34 ft/s, 3.46 m/s

TEST DATE: 08/11/2017
TEST #: D172162




MGA RESEARCH CORPORATION
SHOULDER IMPACT TEST
ES-2re DUMMY


ATD Serial No: 032

Test I.D: D172163

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	20.6	Pass
Laboratory Relative Humidity	%	10 to 70	45	Pass
Pendulum Speed	m/s	4.20 to 4.40	4.23	Pass
Peak Impactor Acceleration	G's	7.5 to 10.5	9.6	Pass
Overall Test Results				Pass


 Laboratory Technician


08/14/2017
 Test Date


 Approved By



TEST DESC: SHOULDER IMPACT
VELOCITY: 13.89 ft/s, 4.23 m/s

TEST DATE: 08/14/2017
TEST #: D172163



MGA RESEARCH CORPORATION


UPPER RIB TEST

ES-2re DUMMY


ATD Serial No: 032



Test I.D: D172164

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	22.0	Pass
Laboratory Relative Humidity	%	10 to 70	46	Pass
Displacement at 459 mm	mm	36.0 to 40.0	37.0	Pass
Displacement at 815 mm	mm	46.0 to 51.0	47.3	Pass
Overall Test Results				Pass


Laboratory Technician

08/11/2017
Test Date


Approved By



MGA RESEARCH CORPORATION

MID RIB TEST

ES-2re DUMMY


ATD Serial No: 032



Test I.D: D172165

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	22.0	Pass
Laboratory Relative Humidity	%	10 to 70	46	Pass
Displacement at 459 mm	mm	36.0 to 40.0	36.5	Pass
Displacement at 815 mm	mm	46.0 to 51.0	47.9	Pass
Overall Test Results				Pass


Laboratory Technician

08/11/2017
Test Date


Approved By



MGA RESEARCH CORPORATION

LOWER RIB TEST

ES-2re DUMMY


ATD Serial No: 032



Test I.D: D172166

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	22.0	Pass
Laboratory Relative Humidity	%	10 to 70	46	Pass
Displacement at 459 mm	mm	36.0 to 40.0	37.2	Pass
Displacement at 815 mm	mm	46.0 to 51.0	49.4	Pass
Overall Test Results				Pass


Laboratory Technician

08/11/2017
Test Date


Approved By



MGA RESEARCH CORPORATION


ABDOMEN TEST

ES-2re DUMMY

ATD Serial No: 032

Test I.D: D172167


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	20.6	Pass
Laboratory Relative Humidity	%	10 to 70	45	Pass
Probe Speed	m/s	3.90 to 4.10	4.10	Pass
Maximum Impactor Force	N	4000 to 4800	4687	Pass
Time of Maximum Impactor Force	ms	10.6 to 13.0	12.2	Pass
Maximum Total Abdomen Force	N	2200 to 2700	2420	Pass
Time of Maximum Abdomen Force	ms	10.0 to 12.3	11.9	Pass
Overall Test Results				Pass





Laboratory Technician



08/14/2017

Test Date



Approved By








TEST DESC: ABDOMEN IMPACT
VELOCITY: 13.44 ft/s, 4.10 m/s

TEST DATE: 08/14/2017
TEST #: D172167



MGA RESEARCH CORPORATION
LUMBAR SPINE TEST
ES-2re DUMMY


ATD Serial No: 032



Test I.D.: D172168



Tested Parameter	Units	Specification	Result	Pass/Fail	
Laboratory Temperature	deg C	20.6 to 22.2	22.0	Pass	
Laboratory Relative Humidity	%	10 to 70	46	Pass	
Pendulum Speed	m/s	5.95 to 6.15	6.12	Pass	
Pendulum Velocity	1 ms	m/s	-0.05 to 0.00	-0.02	Pass
	3.7 ms	m/s	-0.425 to -0.24	-0.422	Pass
	27 ms	m/s	-6.50 to -5.80	-5.93	Pass
	30 ms	m/s	>= -6.50	-5.98	Pass
Maximum Flexion Angle	deg	45.0 to 55.0	47.6	Pass	
Time of Maximum Flexion Angle	ms	39.0 to 53.0	44.5	Pass	
Headform Rotation Decay to Initial Position	ms	37 to 57	47	Pass	
Overall Results				Pass	



 Laboratory Technician

08/11/2017
 Test Date


 Approved By







MGA RESEARCH CORPORATION


PELVIS TEST

ES-2re DUMMY


ATD Serial No: 032



Test I.D: D172169

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	20.6	Pass
Laboratory Relative Humidity	%	10 to 70	45	Pass
Probe Speed	m/s	4.20 to 4.40	4.27	Pass
Maximum Impactor Force	N	4700 to 5400	4700	Pass
Time of Maximum Impactor Force	ms	11.8 to 16.1	13.5	Pass
Maximum Pubic Force	N	1230 to 1590	1285	Pass
Time of Maximum Pubic Force	ms	12.2 to 17.0	15.0	Pass
Overall Test Results				Pass


Laboratory Technician

08/14/2017
Test Date


Approved By



MGA RESEARCH CORPORATION
THORAX IMPACT TEST
ES-2re DUMMY


ATD Serial No: 032



Test I.D: D172160



Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	20.6	Pass
Humidity	%	10 to 70	45	Pass
Probe Speed	m/s	5.40 to 5.60	5.52	Pass
Maximum Impactor Force (after 6 ms)	N	5100 to 6200	5642	Pass
Upper Rib Displacement	mm	34.0 to 41.0	37.3	Pass
Middle Rib Displacement	mm	37.0 to 45.0	40.1	Pass
Lower Rib Displacement	mm	37.0 to 44.0	39.0	Pass
Overall Test Results				Pass


 Laboratory Technician

08/14/2017
 Test Date


 Approved By





SID-IIsD External Measurements
SN: 296


No.	Name	Spec. (mm)	Result	Pass/Fail
A	Sitting Height	772 - 788	784	Pass
B	Shoulder Pivot Height	437 - 453	442	Pass
C	H-point Height	79 - 89	83	Pass
D	H-point from Seatback	141 - 151	145	Pass
E	Shoulder Pivot from Backline	97 - 107	99	Pass
F	Thigh Clearance	119 - 135	121	Pass
G	Head Breadth	140 - 148	142	Pass
H	Head Back from Backline	40 - 46	45	Pass
I	Head Depth	178 - 188	180	Pass
J	Head Circumference	541 - 551	548	Pass
K	Buttock to Knee Length	514 - 540	535	Pass
L	Popliteal Height	343 - 369	358	Pass
M	Knee Pivot to Floor Height	392 - 409	404	Pass
N	Buttock Popliteal Length	416 - 442	435	Pass
O	Chest Depth w/o Jacket	195 - 211	206	Pass
P	Foot Length	216 - 232	219	Pass
Q	Hip Breadth (w/ pelvic plugs)	313 - 323	316	Pass
R	Arm Length	249 - 259	250	Pass
S	Knee Joint to Seatback	477 - 493	481	Pass
V	Shoulder Width	341 - 357	346	Pass
W	Foot Width	78 - 94	85	Pass
Y	Chest Circumference w/ jacket	851 - 881	870	Pass
Z	Waist Circumference	761 - 791	772	Pass

**MGA RESEARCH CORPORATION
HEAD DROP TEST
SID-IIs BUILD LEVEL D DUMMY**

ATD Serial No: 296

Test ID: D171861


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.4	Pass
Laboratory Relative Humidity	%	10 to 70	59	Pass
Peak Resultant Acceleration	G's	115 to 137	132	Pass
Peak Longitudinal Acceleration	G's	+/- 15	3.0	Pass
Unimodal	N/A	Yes	Yes	Pass
Oscillations	N/A	<15%	Yes	Pass
Overall Test Results				Pass





Laboratory Technician



07/10/2017

Test Date



Approved By





**MGA RESEARCH CORPORATION
LATERAL NECK PENDULUM TEST
SID-IIs BUILD LEVEL D DUMMY**

ATD Serial No: 296

Test I.D.: D171862


Tested Parameter	Units	Specification	Result	Pass/Fail	
Temperature	deg C	20.6 to 22.2	21.4	Pass	
Humidity	%	10 to 70	58	Pass	
Impact Velocity	m/s	5.51 to 5.63	5.58	Pass	
Pendulum Velocity	10 ms	m/s	2.20 to 2.80	2.73	Pass
	15 ms	m/s	3.30 to 4.10	4.03	Pass
	20 ms	m/s	4.40 to 5.40	5.40	Pass
	25 ms	m/s	5.40 to 6.10	5.56	Pass
	25-100 ms	m/s	5.50 to 6.20	5.59	Pass
Maximum D-Plane Rotation	deg	71 to 81	72	Pass	
Time of Maximum D-Plane Rotation	ms	50 to 70	60	Pass	
Maximum Occipital Condyle Moment	Nm	-44 to -36	-43	Pass	
Time of Moment Decay to 0 Nm	ms	102 to 126	112	Pass	
Overall Test Results				Pass	





Laboratory Technician


07/10/2017

Test Date



Approved By





**MGA RESEARCH CORPORATION
SHOULDER IMPACT TEST
SID-II's BUILD LEVEL D DUMMY**


ATD Serial No: 296



Test ID: D171863

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.4	Pass
Laboratory Relative Humidity	%	10 to 70	59	Pass
Impact Velocity	m/s	4.20 to 4.40	4.38	Pass
Maximum Probe Acceleration	G's	13 to 18	15	Pass
Shoulder Displacement	mm	28 to 37	33	Pass
Upper Spine (T1) Y Acceleration	G's	17 to 22	18	Pass
Overall Test Results				Pass


Laboratory Technician

07/10/2017
Test Date



Approved By





TEST DESC: SHOULDER IMPACT
VELOCITY: 14.37 ft/s, 4.38 m/s

TEST DATE: 07/10/2017
TEST #: D171863




**MGA RESEARCH CORPORATION
THORAX (WITH ARM) IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY**

ATD Serial No: 296

Test I.D: D171864


Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.4	Pass
Humidity	%	10 to 70	59	Pass
Impact Velocity	m/s	6.60 to 6.80	6.68	Pass
Maximum Probe Acceleration	G's	30 to 36	31	Pass
Shoulder Displacement	mm	31 to 40	38	Pass
Upper Rib Displacement	mm	25 to 32	29	Pass
Middle Rib Displacement	mm	30 to 36	32	Pass
Lower Rib Displacement	mm	32 to 38	34	Pass
Upper Spine (T1) Y Acceleration	G's	34 to 43	35	Pass
Lower Spine (T12) Y Acceleration	G's	29 to 37	32	Pass
Overall Test Results				Pass





Laboratory Technician



07/10/2017



Test Date




Approved By










MGA RESEARCH CORPORATION
THORAX (WITHOUT ARM) IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY

ATD Serial No: 296

Test I.D: D171865


Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.4	Pass
Humidity	%	10 to 70	59	Pass
Impact Velocity	m/s	4.20 to 4.40	4.38	Pass
Maximum Probe Acceleration	G's	14 to 18	15	Pass
Upper Rib Displacement	mm	32 to 40	38	Pass
Middle Rib Displacement	mm	39 to 45	42	Pass
Lower Rib Displacement	mm	35 to 43	39	Pass
Upper Spine (T1) Y Acceleration	G's	13 to 17	15	Pass
Lower Spine (T12) Y Acceleration	G's	7 to 11	8	Pass
Overall Test Results				Pass





Laboratory Technician

07/10/2017

Test Date




Approved By






MIDDLE RIB DISPLACEMENT (mm) vs TIME (ms)




LOWER RIB DISPLACEMENT (mm) vs TIME (ms)






UPPER SPINE Y ACCELERATION (G's) vs TIME (ms)



LOWER SPINE Y ACCELERATION (G's) vs TIME (ms)




MGA RESEARCH CORPORATION
ABDOMINAL IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY

ATD Serial No: 296

Test I.D: D171866


Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.4	Pass
Humidity	%	10 to 70	59	Pass
Impact Velocity	m/s	4.20 to 4.40	4.34	Pass
Maximum Probe Acceleration	G's	12 to 16	14	Pass
Upper Abdomen Rib Displacement	mm	36 to 47	41	Pass
Lower Abdomen Rib Displacement	mm	33 to 44	40	Pass
Lower Spine (T12) Y Acceleration	G's	9 to 14	10	Pass
Overall Test Results				Pass





Laboratory Technician



07/10/2017

Test Date



Approved By






**MGA RESEARCH CORPORATION
 PELVIS IMPACT TEST
 SID-IIs BUILD LEVEL D DUMMY**

ATD Serial No: 296

Test I.D.: D171867


Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.4	Pass
Humidity	%	10 to 70	59	Pass
Impact Velocity	m/s	6.60 to 6.80	6.60	Pass
Maximum Probe Acceleration	G's	38 to 47	43	Pass
Pelvis Y Acceleration After 6 ms	G's	34 to 42	41	Pass
Peak Acetabulum Force	N	3600 to 4300	3,901	Pass
Overall Test Results				Pass





Laboratory Technician


07/10/2017

Test Date



Approved By






MGA RESEARCH CORPORATION
ILIAC IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY

ATD Serial No: 296

Test I.D: D171868


Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.4	Pass
Humidity	%	10 to 70	59	Pass
Impact Velocity	m/s	4.20 to 4.40	4.30	Pass
Maximum Probe Acceleration	G's	36 to 45	36	Pass
Pelvis Y Acceleration	G's	28 to 39	29	Pass
Peak Pelvis Iliac Force	N	4100 to 5100	4,168	Pass
Overall Test Results				Pass





Laboratory Technician

07/10/2017

Test Date




Approved By





TEST DESC: ILLIAC
VELOCITY: 14.12 ft/s, 4.30 m/s

TEST DATE: 07/10/2017
TEST #: D171868



SID-IIsD External Measurements
SN: 296


No.	Name	Spec. (mm)	Result	Pass/Fail
A	Sitting Height	772 - 788	784	Pass
B	Shoulder Pivot Height	437 - 453	442	Pass
C	H-point Height	79 - 89	83	Pass
D	H-point from Seatback	141 - 151	145	Pass
E	Shoulder Pivot from Backline	97 - 107	99	Pass
F	Thigh Clearance	119 - 135	121	Pass
G	Head Breadth	140 - 148	142	Pass
H	Head Back from Backline	40 - 46	45	Pass
I	Head Depth	178 - 188	180	Pass
J	Head Circumference	541 - 551	548	Pass
K	Buttock to Knee Length	514 - 540	535	Pass
L	Popliteal Height	343 - 369	358	Pass
M	Knee Pivot to Floor Height	392 - 409	404	Pass
N	Buttock Popliteal Length	416 - 442	435	Pass
O	Chest Depth w/o Jacket	195 - 211	206	Pass
P	Foot Length	216 - 232	219	Pass
Q	Hip Breadth (w/ pelvic plugs)	313 - 323	316	Pass
R	Arm Length	249 - 259	250	Pass
S	Knee Joint to Seatback	477 - 493	481	Pass
V	Shoulder Width	341 - 357	346	Pass
W	Foot Width	78 - 94	85	Pass
Y	Chest Circumference w/ jacket	851 - 881	870	Pass
Z	Waist Circumference	761 - 791	772	Pass

MGA RESEARCH CORPORATION
HEAD DROP TEST
SID-IIs BUILD LEVEL D DUMMY

ATD Serial No: 296

Test ID: D172151


Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.6	Pass
Laboratory Relative Humidity	%	10 to 70	45	Pass
Peak Resultant Acceleration	G's	115 to 137	133	Pass
Peak Longitudinal Acceleration	G's	+/- 15	2.4	Pass
Unimodal	N/A	Yes	Yes	Pass
Oscillations	N/A	<15%	Yes	Pass
Overall Test Results				Pass





Laboratory Technician



08/10/2017

Test Date



Approved By






MGA RESEARCH CORPORATION
LATERAL NECK PENDULUM TEST
SID-IIs BUILD LEVEL D DUMMY

ATD Serial No: 296

Test I.D.: D172152


Tested Parameter	Units	Specification	Result	Pass/Fail	
Temperature	deg C	20.6 to 22.2	22.0	Pass	
Humidity	%	10 to 70	46	Pass	
Impact Velocity	m/s	5.51 to 5.63	5.58	Pass	
Pendulum Velocity	10 ms	m/s	2.20 to 2.80	2.62	Pass
	15 ms	m/s	3.30 to 4.10	3.84	Pass
	20 ms	m/s	4.40 to 5.40	5.21	Pass
	25 ms	m/s	5.40 to 6.10	5.70	Pass
	25-100 ms	m/s	5.50 to 6.20	5.73	Pass
Maximum D-Plane Rotation	deg	71 to 81	74	Pass	
Time of Maximum D-Plane Rotation	ms	50 to 70	60	Pass	
Maximum Occipital Condyle Moment	Nm	-44 to -36	-42	Pass	
Time of Moment Decay to 0 Nm	ms	102 to 126	112	Pass	
Overall Test Results				Pass	





Laboratory Technician


08/11/2017

Test Date



Approved By





**MGA RESEARCH CORPORATION
SHOULDER IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY**

ATD Serial No: 296

Test ID: D172153

Tested Parameter	Units	Specification	Result	Pass/Fail
Laboratory Temperature	deg C	20.6 to 22.2	21.5	Pass
Laboratory Relative Humidity	%	10 to 70	48	Pass
Impact Velocity	m/s	4.20 to 4.40	4.30	Pass
Maximum Probe Acceleration	G's	13 to 18	15	Pass
Shoulder Displacement	mm	28 to 37	29	Pass
Upper Spine (T1) Y Acceleration	G's	17 to 22	18	Pass
Overall Test Results				Pass

Emily Fliess



Laboratory Technician


08/11/2017

Test Date

Robert Schaub

Approved By





**MGA RESEARCH CORPORATION
THORAX (WITH ARM) IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY**

ATD Serial No: 296

Test I.D: D172154

Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.5	Pass
Humidity	%	10 to 70	48	Pass
Impact Velocity	m/s	6.60 to 6.80	6.77	Pass
Maximum Probe Acceleration	G's	30 to 36	32	Pass
Shoulder Displacement	mm	31 to 40	38	Pass
Upper Rib Displacement	mm	25 to 32	29	Pass
Middle Rib Displacement	mm	30 to 36	32	Pass
Lower Rib Displacement	mm	32 to 38	33	Pass
Upper Spine (T1) Y Acceleration	G's	34 to 43	36	Pass
Lower Spine (T12) Y Acceleration	G's	29 to 37	31	Pass
Overall Test Results				Pass

Emily Fliess



Laboratory Technician



08/11/2017



Test Date


Robert Schaub

Approved By









MGA RESEARCH CORPORATION
THORAX (WITHOUT ARM) IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY


ATD Serial No: 296



Test I.D: D172155



Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.5	Pass
Humidity	%	10 to 70	48	Pass
Impact Velocity	m/s	4.20 to 4.40	4.34	Pass
Maximum Probe Acceleration	G's	14 to 18	15	Pass
Upper Rib Displacement	mm	32 to 40	38	Pass
Middle Rib Displacement	mm	39 to 45	42	Pass
Lower Rib Displacement	mm	35 to 43	40	Pass
Upper Spine (T1) Y Acceleration	G's	13 to 17	15	Pass
Lower Spine (T12) Y Acceleration	G's	7 to 11	8	Pass
Overall Test Results				Pass




 Laboratory Technician

08/11/2017
 Test Date


 Approved By







**MGA RESEARCH CORPORATION
 ABDOMINAL IMPACT TEST
 SID-IIs BUILD LEVEL D DUMMY**


ATD Serial No: 296



Test I.D: D172156



Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.5	Pass
Humidity	%	10 to 70	48	Pass
Impact Velocity	m/s	4.20 to 4.40	4.27	Pass
Maximum Probe Acceleration	G's	12 to 16	13	Pass
Upper Abdomen Rib Displacement	mm	36 to 47	42	Pass
Lower Abdomen Rib Displacement	mm	33 to 44	41	Pass
Lower Spine (T12) Y Acceleration	G's	9 to 14	10	Pass
Overall Test Results				Pass


 Laboratory Technician

08/11/2017
 Test Date


 Approved By






MGA RESEARCH CORPORATION
PELVIS IMPACT TEST
SID-IIs BUILD LEVEL D DUMMY

ATD Serial No: 296

Test I.D: D172157


Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.5	Pass
Humidity	%	10 to 70	48	Pass
Impact Velocity	m/s	6.60 to 6.80	6.60	Pass
Maximum Probe Acceleration	G's	38 to 47	43	Pass
Pelvis Y Acceleration After 6 ms	G's	34 to 42	41	Pass
Peak Acetabulum Force	N	3600 to 4300	3,951	Pass
Overall Test Results				Pass





Laboratory Technician


08/11/2017

Test Date



Approved By





**MGA RESEARCH CORPORATION
 ILIAC IMPACT TEST
 SID-IIs BUILD LEVEL D DUMMY**


ATD Serial No: 296



Test I.D: D172158

Tested Parameter	Units	Specification	Result	Pass/Fail
Temperature	deg C	20.6 to 22.2	21.5	Pass
Humidity	%	10 to 70	48	Pass
Impact Velocity	m/s	4.20 to 4.40	4.38	Pass
Maximum Probe Acceleration	G's	36 to 45	38	Pass
Pelvis Y Acceleration	G's	28 to 39	29	Pass
Peak Pelvis Iliac Force	N	4100 to 5100	4,306	Pass
Overall Test Results				Pass


 Laboratory Technician

08/11/2017
 Test Date



 Approved By





TEST DESC: ILLIAC
VELOCITY: 14.37 ft/s, 4.38 m/s

TEST DATE: 08/11/2017
TEST #: D172158





SID-IIs Pelvis Plug Certification Test


Plug S/N 11170
 Test Number 2543
 Report Number 2538
 Test Date 4/26/2016 8:04:14 AM

	<u>Test Results</u>	<u>Spec Min</u>	<u>Spec Max</u>
Force @ 0.5 mm (N)	317.51	50.00	600.00
Force @ 1.5 mm (N)	1,071.09	850.00	1,400.00
Force @ 2.5 mm (N)	1,380.67	1,306.00	1,618.00
Force @ 3.0 mm (N)	1,499.82	1,361.00	1,673.00

Testing Machine STM-20 5965542
 Load Cell S/N (TI240813), Units (LBS) 1000
 Crosshead Speed (mm / min) or Rate 12.7
 Extension or Position Measured by XHD_100 (XHD100)

Notes:

Force (-N) vs Extension (-mm)



Operator DC
 Part Number 180-4450

Template No 107 26-Apr-16
 SACO Research

By: DC Date: 4/26/16



SID-IIs Pelvis Plug Certification Test


Plug S/N 11303
 Test Number 2690
 Report Number 2686
 Test Date 5/2/2016 8:15:58 AM

	<u>Test Results</u>	<u>Spec Min</u>	<u>Spec Max</u>
Force @ 0.5 mm (N)	449.30	50.00	600.00
Force @ 1.5 mm (N)	1,149.72	850.00	1,400.00
Force @ 2.5 mm (N)	1,444.60	1,306.00	1,618.00
Force @ 3.0 mm (N)	1,528.02	1,361.00	1,673.00

Testing Machine STM-20 5965542
 Load Cell S/N (TI240813), Units (LBS) 1000
 Crosshead Speed (mm / min) or Rate 12.7
 Extension or Position Measured by XHD_100 (XHD100)

Notes:

Force (-N) vs Extension (-mm)



Operator DC
 Part Number 180-4450

Template No 107 02-May-16
 SACO Research

By: DC Date: 5/2/16

APPENDIX D
TEST EQUIPMENT AND INSTRUMENTATION CALIBRATION DATA

Table 1 – Dummy Instrumentation (ES-2re)

		ES-2re S/N 032			
		Serial Number	Manufacturer	Calibration Date	
Head CG Accelerometers		X	P79711	Endevco	07/05/17
		Y	P79712	Endevco	07/05/17
		Z	P88170	Endevco	07/05/17
		Xr	P94783	Endevco	06/27/17
		Yr	P94784	Endevco	06/27/17
		Zr	P94786	Endevco	06/27/17
Thorax Rib Displacement Potentiometers	Upper	Y	G176	Honeywell	07/11/17
	Middle	Y	G169	Honeywell	07/11/17
	Lower	Y	G164	Honeywell	07/11/17
Abdomen Load Cells	Forward	Y	ABG1513	Denton	10/26/16
	Middle	Y	ABG1531	Denton	10/26/16
	Rear	Y	ABG1536	Denton	10/26/16
Lower Spine Accelerometers (T12)		X	P79012	Endevco	07/05/17
		Y	P79832	Endevco	07/05/17
		Z	P82603	Endevco	07/05/17
Public Symphysis Load Cell		Y	PG462	Denton	10/26/16

Table 2 – Dummy Instrumentation (SID-IIs)

				SID-IIs S/N 296			
				Serial Number	Manufacturer	Calibration Date	
Head CG Accelerometers				X	P94783	Endevco	06/27/17
				Y	P94784	Endevco	06/27/17
				Z	P94786	Endevco	06/27/17
				Xr	P94934	Endevco	06/27/17
				Yr	P94936	Endevco	06/27/17
				Zr	P94938	Endevco	06/27/17
Head Angular Rate Sensors				X	ARS7413	DTS	07/15/14
				Y	ARS7421	DTS	07/15/14
				Z	ARS7423	DTS	07/15/14
Displacement Potentiometers	Thoracic Rib	Upper	Y	G012	FTSS	06/28/17	
		Middle	Y	G1163	FTSS	06/28/17	
		Lower	Y	G1158	FTSS	06/28/17	
	Abdominal Rib	Upper	Y	G1146	FTSS	06/28/17	
		Lower	Y	G1126	FTSS	06/28/17	
Lower Spine Accelerometers (T12)				X	P79418	Endevco	06/27/17
				Y	P79439	Endevco	06/27/17
				Z	P79614	Endevco	06/27/17
Acetabulum Load Cell				Y	ACG4285	Denton	04/20/17
Iliac Wing Load Cell				Y	IWG3023	Denton	04/20/17
Pelvis Plug (struck side)					11170	FTSS	04/26/16
Pelvis Plug (non-struck side)					11303	FTSS	05/02/16

Table 3 – Vehicle Instrumentation

			Serial Number	Manufacturer	Calibration Date
1	Vehicle Center of Gravity	X	PCB702	PCB	05/03/17
	Vehicle Center of Gravity	Y	PCB424	PCB	06/02/17
	Vehicle Center of Gravity	Z	PCB425	PCB	06/02/17
2	Right Sill at Front Seat	X	PCB841	PCB	05/03/17
	Right Sill at Front Seat	Y	PCB790	PCB	05/03/17
	Right Sill at Front Seat	Z	PCB551	PCB	05/03/17
3	Right Sill at Rear Seat	X	PCB636	PCB	03/27/17
	Right Sill at Rear Seat	Y	PCB972	PCB	03/27/17
	Right Sill at Rear Seat	Z	PCB857	PCB	03/15/17
4	Left Sill at Front Door	Y	PCB691	PCB	03/24/17
5	Left Sill at Rear Door	Y	PCB653	PCB	03/13/17
6	Left A-Post Lower	Y	PCB881	PCB	04/12/17
7	Left A-Post Middle	Y	PCB871	PCB	04/15/17
8	Left B-Post Lower	Y	PCB744	PCB	03/24/17
9	Left B-Post Middle	Y	PCB873	PCB	03/16/17
10	Front Seat Track	Y	PCB578	PCB	06/02/17
11	Rear Seat Track or Structure	Y	PCB769	PCB	03/13/17
12	Right Rear Occ. Compartment	Y	PCB851	PCB	03/15/17
13	Engine Block	X	PCB970	PCB	03/09/17
	Engine Block	Y	PCB737	PCB	03/16/17
14	Rear Floorpan Above Axle	X	PCB633	PCB	06/12/17
	Rear Floorpan Above Axle	Y	PCB549	PCB	06/12/17
	Rear Floorpan Above Axle	Z	PCB587	PCB	06/12/17

Table 4 – MDB Instrumentation

		Serial Number	Manufacturer	Calibration Date
MDB Center of Gravity	X	PCB661D	PCB	02/15/17
MDB Center of Gravity	Y	PCB659D	PCB	02/15/17
MDB Center of Gravity	Z	PCB660D	PCB	02/15/17
Left Frame at Rear Axle Centerline	X	PCB495D	PCB	02/15/17
Left Frame at Rear Axle Centerline	Y	PCB494D	PCB	02/15/17