


REPORT NUMBER: 301R-CAL-19-005

**SAFETY COMPLIANCE TESTING FOR FMVSS 301R
FUEL SYSTEM INTEGRITY – REAR IMPACT**

**Nissan Motor Co. LTD.
2019 Infinity QX50**

NHTSA NUMBER: C20195201

**PREPARED BY:
CALSPAN CORPORATION
TRANSPORTATION TEST OPERATIONS
P.O. BOX 400
BUFFALO, NEW YORK 14225**



July 24, 2019

FINAL REPORT

**PREPARED FOR:
U. S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration Enforcement
Office of Vehicle Safety Compliance
Mail Code: NVS-220
1200 New Jersey Avenue, SE
Washington, DC 20590**

This Final Test Report was prepared for the U.S. Department of Transportation, National Highway Traffic Safety Administration, under Contract No. DTNH22-16-D-00032.

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof.

If trade or manufactures' names or products are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Prepared By: 

Amila Perera, Senior Test Engineer

Approved By: 

Vanessa Hansen, Operations Manager

Approval Date: July 24, 2019

FINAL REPORT ACCEPTANCE BY OVSC:

Accepted By: _____

Acceptance
Date: _____

TECHNICAL REPORT STANDARD TITLE PAGE

1. Report No. 301R-CAL-19-005	2. Government Accession No.		3. Recipient's Catalog No.	
4. Title and Subtitle Final Report of FMVSS 301R Compliance Rear Impact Testing of a 2019 Infinity QX50 NHTSA No.: C20195201		5. Report Date July 24, 2019		
		6. Performing Organization Code CAL		
7. Author(s) Amila Perera, Senior Test Engineer Vanessa Hansen, Operations Manager		8. Performing Organization Report No. CAL-DOT-2019-005		
9. Performing Organization Name and Address Calspan Corporation Transportation Test Operations P.O. Box 400 Buffalo, New York 14225		10. Work Unit No.		
		11. Contract or Grant No. DTNH22-16-D-00032		
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration Office of Vehicle Safety Compliance- Enforcement Mail Code: NVS-220 1200 New Jersey Avenue, SE Washington, D.C. 20590		13. Type of Report and Period Covered Final Test Report July 22, 2019 - July 24, 2019		
		14. Sponsoring Agency Code NVS-220		
15. Supplementary Notes				
16. Abstract A compliance test was conducted on a 2019 Infinity QX50 SUV in accordance with the specifications of the Office of Vehicle Safety Compliance Test Procedure No. TP-301R-02 for the determination of FMVSS 301R compliance. Test failures identified were as follows: None - The test vehicle appeared to comply with all requirements of FMVSS 301R "Fuel System Integrity – Rear Impact."				
17. Key Words Compliance Testing Safety Engineering FMVSS 301R		18. Distribution Statement <u>Copies of this report are available from:</u> National Highway Traffic Safety Administration Technical Reference Division (TIS) (NPO-230) 1200 New Jersey Avenue, SE Washington, D.C. 20590 Telephone No. (202) 366-4946		
19. Security Classification of Report UNCLASSIFIED	20. Security Classification of Page UNCLASSIFIED		21. No. of Pages 39	22. Price

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	Purpose and Test Procedure	1-1
2	Compliance Test Results Summary	2-1
3	Data Sheets	3-1
 <u>Data Sheet</u>		 <u>Page</u>
1	Test Vehicle Specifications	3-2
2	Pre-Test Data	3-3
3	Moving Deformable Barrier (MDB) Data	3-6
4	High Speed Camera Locations and Data Summary	3-7
5	Post-Test Data	3-8
6	FMVSS No. 301 Static Rollover Test Data	3-10
 <u>Appendix</u>		 <u>Page</u>
A	Photographs	A-1

SECTION 1

PURPOSE AND TEST PROCEDURE

This rear impact test is part of the FMVSS 301R Compliance Test Program sponsored by the National Highway Traffic Safety Administration (NHTSA) under Contract No. DTNH22-16-D-00032. The purpose of this test was to determine if the subject vehicle, a 2019 Infinity QX50 SUV, meets the performance requirements of FMVSS No. 301R "Fuel System Integrity – Rear Impact." The test was conducted in accordance with the Office of Vehicle Safety Compliance's Laboratory Test Procedure (TP-301R-02, dated January 17, 2007).

SECTION 2

COMPLIANCE TEST RESULTS SUMMARY

A 1,943 kg 2019 Infinity QX50SUV was impacted from the rear by a 1362.2 kg moving barrier at a velocity of 79.47 kph (49.38 mph). The test was performed by Calspan Corporation on July 22, 2019.

The test vehicle was equipped with a 60.2-liter fuel tank which was filled to 93 percent capacity with stoddard fluid prior to impact. Additional ballast (54.4 kg) was secured on the vehicle's rear passenger seat. Two ballast Part 572E 50th percentile male Anthropomorphic Test Devices (ATD) were placed in the front occupant seating positions.

The crash event was recorded by three high-speed cameras and one real-time camera. High-speed camera locations and other pertinent camera information can be found on page 3-7 of this report. Pre- and post-test photographs of the vehicle can be found in Appendix A.

There was no fuel system fluid spillage following the impact and including all portions of the static rollover test. The vehicle appeared to comply with all the requirements of FMVSS No. 301 "Fuel System Integrity."

SECTION 3

SUMMARY OF TEST RESULTS

This section contains information reporting for the following Data Sheets:

Data Sheet No. 1 – Test Vehicle Specifications

Data Sheet No. 2 – Pre-Test Data

Data Sheet No. 3 – Moving Deformable Barrier (MDB) Data

Data Sheet No. 4 – High Speed Camera Locations and Data Summary

Data Sheet No. 5 – Post-Test Data

Data Sheet No. 6 – FMVSS No. 301 Static Rollover Test Data

DATA SHEET NO. 1
TEST VEHICLE SPECIFICATIONS

Test Vehicle: 2019 Infinity QX50SUV
Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
Test Date: 07/22/2019

TEST VEHICLE INFORMATION AND OPTIONS

NHTSA No.	C20195201
Model Year	2019
Make	Infinity
Model	QX50
Body Style	Four Door SUV
Body Color	White
Odometer Reading (km/mi)	15 miles
Engine Displacement (L)	2.0
Type/No. Cylinders	I4
Engine Placement	Transverse
Transmission Type	Automatic
Transmission Speeds	CVT
Final Drive	Front Wheel Drive

Overdrive	Yes
Air Conditioning (AC)	Yes
All-Wheel Drive (AWD)	No
Anti-Lock Brakes (ABS)	Yes
Automatic Door Locks (ADL)	Yes
Power Brakes	Yes
Power Seats	Yes
Power Steering	Yes
Power Windows	Yes
Stability Control (Auto-Leveling)	No
Sunroof/T-Top	No
Tilt Steering Wheel	Yes
Traction Control System (TCS)	Yes

DEALER AND DELIVERY INFORMATION FROM CERTIFICATION LABEL

Manufactured By	Nissan Motor Co. LTD.
Date of Manufacture	12/18
VIN	3PCAJ5M15KF131236

GVWR (kg)	2230
GAWR Front (kg)	1280
GAWR Rear (kg)	1140

TIRE PLACARD & SIDEWALL INFORMATION

Tire Placard Location: Driver's Door Sill Spare Tire None

Measured Parameter	Front	Rear
Tire Manufacturer	Bridgestone	Bridgestone
Tire Name	Ecopia H/L 422 Plus	Ecopia H/L 422 Plus
Tire Type	All Season	All Season
Max. Tire Pressure (kPa)	350	350
Recommended Tire Size	235/55RF19	235/55RF19
Load Index/Speed Symbol	101V	101V
Recommended Cold Tire Pressure (kPa)	230	230
Tire Size on Vehicle	235/55RF19	235/55RF19
Treadwear/ Traction Grade/ Temperature Grade	600/A/A	600/A/A

VEHICLE CAPACITY DATA

Measured Parameter	Front	Rear	Third	Total
Designated Seating Capacity (DSC)	2	3	-	5
Seat Type (Bench, Bucket, or Split Bench)	Bucket	Bench	-	
Capacity Weight (VCW) (kg)				390
DSC X 68.04 (kg)				340.2
Cargo Weight (RCLW) (kg)				49.8

**DATA SHEET NO. 2
PRE-TEST DATA**

Test Vehicle: 2019 Infinity QX50SUV
Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
Test Date: 07/22/2019

TEST VEHICLE WEIGHTS

	Units	As Delivered (UVW)			As Tested (ATW)		
		Front	Rear	Total	Front	Rear	Total
Left	kg	521	357		566	409	
Right	kg	517	349		560	408	
Ratio	%	59.5	40.5		57.9	42.1	
Totals	kg	1038	706	1744	1126	817	1943

TARGET TEST WEIGHT CALCULATION (TTW)

Measured Parameter	Units	Value	
Total Unloaded Vehicle Weight (UVW)	kg	1744	(A)
Rated Cargo/Luggage Weight (RCLW)	kg	49.8	(B)
Weight of two P572E ATDS	kg	155.4	(C)
Target Vehicle Test Weight (TVTWT)	kg	1949.2	(A+B+C)

GENERAL TEST VEHICLE DATA

Measured Parameter	Units	Value
Vehicle Wheelbase	mm	2795
Vehicle Length (at Centerline)	mm	4692
Vehicle Width (B-Pillar)	mm	1886
Weight of Ballast Secured in Cargo Area ¹	kg	54.4
Type of Ballast		Lead-shot Bag
Method of Securing Ballast		Rear Passenger Footwell
Components Removed for Weight Reduction		0
Vehicle Width at Widest Point	mm	1906
Vehicle Width at Widest Point Location		C-Pillar
Centerline offset for impact line	mm	469.3
Filler neck side (left/right)		Left

¹ Ballast weight does not include the weight of instrumentation, on-board cameras and data acquisition system

TEST VEHICLE ATTITUDE AND CG

	Units	Left		Right		CG (aft of front axle)
		Front	Rear	Front	Rear	
As Delivered (UVW)	mm	794	801	792	806	1132
As Tested (ATW)	mm	777	783	776	775	1175

DATA SHEET NO. 2 (Continued)
PRE-TEST DATA

Test Vehicle: 2019 Infinity QX50SUV
Test Program: FMVSS 301R Compliance Rear Impact Test


NHTSA No.: C20195201
Test Date: 07/22/2019

SEATING

Nominal Design Riding Position (for adjustable driver and passenger seat backs). *Please describe how to position the inclinometer to measure the seat back angle. Include description of the location of the adjustment latch detent, if applicable.*

Driver Seat Instructions: The driver seat back was positioned according to the Nominal Design Riding position listed in FORM 1.

Passenger Seat Instructions: The passenger seat back was positioned to the Nominal Design Riding position listed in FORM 1.




Measured Parameter	Deg.
Driver Seat Back Angle	0.2
Passenger Seat Back Angle	0.5

SEAT FORE/AFT POSITIONING

Driver Seat: Was positioned according to the Nominal Design Riding position listed in FORM1.

Passenger Seat: Was positioned according to the Nominal Design Riding position listed in FORM1.

	Total Travel	Test Position
Driver Seat	260	130
Passenger Seat	260	130



FUEL TANK CAPACITY DATA

Measured Parameter	Reference	Liters
Fuel System Capacity (Standard Tank)	Owner's Manual	60.2
COTR Usable Capacity (Standard Tank)	Form No. 1	60.2
Test Volume Range	92-94% of Usable Capacity	55.4 – 56.6
Actual Test Volume (Solvent Used)	93% of Usable Capacity	56.0

FUEL SYSTEM DATA

Measured Parameter	Value
Test Fluid Type	Stoddard Solvent
Test Fluid Specific Gravity	0.764
Test Fluid Kinematic Viscosity (centistokes)	0.96
Test Fluid Color	Purple
Electric Fuel Pump?	Yes
Can Activate Electric Fuel Pump with Ignition Switch On but Engine Off?	Yes

Fuel Pump Comments : None


DATA SHEET NO. 2 (Continued)
PRE-TEST DATA

Test Vehicle: 2019 Infinity QX50SUV
Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
Test Date: 07/22/2019

STEERING COLUMN ADJUSTMENT

Steering wheel and column adjustments are made so that the steering wheel hub is at the center of its geometric locus it describes when it moves through its full range of motion.



Operational Instructions: Tilt wheel was positioned to mid-range at 25.2 degrees and 26.5 mm.

SEAT BELT UPPER ANCHORAGE

Nominal design riding position

Operational Instructions: Anchorage were placed in the uppermost position.

COMMENTS: None

DATA SHEET NO. 3
MOVING DEFORMABLE BARRIER (MDB) DATA

Test Vehicle: 2019 Infinity QX50SUV
 Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
 Test Date: 07/22/2019

MDB Face Manufacturer: Plascore MDB Face Serial No. A0319053

MDB SPECIFICATIONS

Measurement Description	Length (mm)
Overall Width of Framework Carriage	1250
Overall Length of MDB (incl. honeycomb impactor face)	4120
Wheelbase of Framework Carriage	2583
Tread of Framework Carriage (Front & Rear)	1880
CG Location of Front Axle	1105.8

MDB WEIGHTS

	Units	Front	Rear	Total
Left	kg	392.0	293.3	685.3
Right	kg	387.1	289.8	676.9
Ratio	%	57.2%	42.8%	100.0%
Totals	kg	779.1	583.1	1362.2

MDB TIRE SIZE & PRESSURES

	Units	Requirement	Left Front	Right Front	Left Rear	Right Rear
Tire Size		P205/75R15	P205/75R15	P205/75R15	P205/75R15	P205/75R15
Tire Pressure	kPa	200 ± 21	207	207	207	207


Brake Abort System? (Yes/No): Yes

Date of Last MDB Calibration: July 8, 2019

DATA SHEET NO. 4
HIGH SPEED CAMERA LOCATIONS AND DATA SUMMARY

Test Vehicle: 2019 Infinity QX50SUV
 Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
 Test Date: 07/22/2019



No.	Camera View	Coordinates (mm)			Angle (Deg)	Lens (mm)	Film Speed (fps)
		X*	Y*	Z*			
1	Left Side View	1762	10737	1319	1.4	24	1000
2	Real-Time Camera						60
3	Overhead View	727	0	9370	90	12.5	1000
4	Right Side View	1799	10448	1204	1.6	24	1000

* Reference (from point of impact); all measurements accurate to within ± 6 mm.

X = (Impact Point) + Forward

Y = (Impact Point) + To Right

Z = (Ground Level) + Down

**DATA SHEET NO. 5
POST-TEST DATA**

Test Vehicle: 2019 Infinity QX50SUV
Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
Test Date: 07/22/2019

VIN: 3PCAJ5M15KF131236

REQUIRED IMPACT VELOCITY RANGE: 78.5 to 80.1 km/h

ACTUAL IMPACT VELOCITY (WITHIN 1.5 M OF IMPACT PLANE)

Measurement Description	Units	Speed
Trap No. 1	km/h	79.47
Trap No. 2	km/h	79.36

WELDING ROD IMPACT POINT

Measurement Description	Tolerance	Units	Value
Vertical distance from target center (+ is above)	±40 mm	mm	+2
Horizontal distance from target center (+ is right)	±50 mm	mm	+2

STODDARD SOLVENT SPILLAGE MEASUREMENT:

A. From impact until vehicle motion ceases:
(Maximum allowable is 28 grams) 0 grams

B. For the 5-minute period after motion ceases:
(Maximum allowable is 28 grams) 0 grams

C. For the next 25 minutes:
(Maximum allowable is 28 grams/minute) 0 grams

D. Spillage Details: No Spillage Occurred

DATA SHEET NO. 5
POST-TEST DATA (Continued)

Test Vehicle: 2019 Infinity QX50SUV
Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
Test Date: 07/22/2019

DOOR OPENING AND SEAT TRACK INFORMATION

Description	Driver	Passenger
Locked/Unlocked Doors	Unlocked	Unlocked
Front Door Opening	Opens/Operational	Opens/Operational
Rear Door Opening	Unlatches/Not Operational	Opens/Operational
Seat Track Shift (mm)	0	0
Seat Back Failure	Reclined	Reclined
Glazing Damage	None	None


POST TEST STRUCTURAL OBSERVATIONS

Critical Areas of Performance	Observations and Conclusions
Windshield Damage	None
Window Damage	None
Other Notable Effects	None

DATA SHEET NO. 6
FMVSS NO. 301 STATIC ROLLOVER TEST DATA

Test Vehicle: 2019 Infinity QX50SUV
 Test Program: FMVSS 301R Compliance Rear Impact Test

NHTSA No.: C20195201
 Test Date: 07/22/2019



ROLLOVER SOLVENT COLLECTION TIME TABLE

Test Phase	Rotation Time (spec. 1 -3 min)		Hold Time	Total Time		Next Whole Minute Interval
	Minutes	Seconds	Minutes	Minutes	Seconds	Minutes
0° to 90°	1	8	5	6	8	7
90° to 180°	1	9	5	6	9	7
180° to 270°	1	6	5	6	6	7
270° to 360°	1	7	5	6	7	7

FMVSS 301 REQUIREMENTS TABLE (Maximum allowable solvent spillage)

First 5 Minutes (grams)	6th Minute (grams)	7th Minute (grams)	8th Minute (grams)
142	28	28	28

ACTUAL TEST VEHICLE STODDARD SOLVENT SPILLAGE TABLE

Test Phase	First 5 Minutes (grams)	6th Minute (grams)	7th Minute (grams)	8th Minute (grams)
0° to 90°	0	0	0	
90° to 180°	0	0	0	
180° to 270°	0	0	0	
270° to 360°	0	0	0	


ROLLOVER STODDARD SOLVENT SPILLAGE LOCATION TABLE

Test Phase	Spillage Location
0° to 90°	None
90° to 180°	None
180° to 270°	None
270° to 360°	None

APPENDIX A
PHOTOGRAPHS


TABLE OF PHOTOGRAPHS

Fig.	Description	Page
1	Vehicle Certification Placard	A-3
2	Vehicle Tire Placard	A-3
3	Pre-Test Front View	A-4
4	Post-Test Front View	A-4
5	Pre-Test Left Side View	A-5
6	Post-Test Left Side View	A-5
7	Pre-Test Right Side View	A-6
8	Post-Test Right Side View	A-6
9	Pre-Test Left Front 3/4 View	A-7
10	Post-Test Left Front 3/4 View	A-7
11	Pre-Test Right Front 3/4 View	A-8
12	Post-Test Right Front 3/4 View	A-8
13	Pre-Test Left Rear 3/4 View	A-9
14	Post-Test Left Rear 3/4 View	A-9
15	Pre-Test Right Rear 3/4 View	A-10
16	Post-Test Right Rear 3/4 View	A-10
17	Pre-Test Rear View	A-11
18	Post-Test Rear View	A-11
19	Pre-Test MDB Front View	A-12
20	Post-Test MDB Front View	A-12
21	Pre-Test MDB Left Side View	A-13
22	Post-Test MDB Left Side View	A-13
23	Pre-Test MDB Right Side View	A-14
24	Post-Test MDB Right Side View	A-14
25	Pre-Test MDB Top View	A-15
26	Post-Test MDB Top View	A-15
27	Pre-Test Overhead Vehicle and MDB View	A-16
28	Post-Test Impact Target View	A-16
29	Pre-Test Front Underbody View	A-17
30	Post-Test Front Underbody View	A-17
31	Pre-Test Mid Underbody View	A-18
32	Post-Test Mid Underbody View	A-18
33	Pre-Test Rear Underbody View	A-19
34	Post-Test Rear Underbody View	A-19
35	Pre-Test Fuel Filler Cap View	A-20
36	Post-Test Fuel Filler Cap View	A-20
37	Impact View	A-21
38	Speed Trap View	A-21
39	Rollover 90° View	A-22
40	Rollover 180° View	A-22
41	Rollover 270° View	A-23
42	Rollover 360° View	A-23



C20195201

Figure A-1: Vehicle Certification Placard



C20195201

Figure A-2: Vehicle Tire Placard




Figure A-3: Pre-Test Front View



Figure A-4: Post-Test Front View



Figure A-5: Pre-Test Left Side View



Figure A-6: Post-Test Left Side View



Figure A-7: Pre-Test Right Side View



Figure A-8: Post-Test Right Side View



Figure A-9: Pre-Test Left Front 3/4 View



Figure A-10: Post-Test Left Front 3/4 View



Figure A-11: Pre-Test Right Front 3/4 View



Figure A-12: Post-Test Right Front 3/4 View



Figure A-13: Pre-Test Left Rear 3/4 View



Figure A-14: Post-Test Left Rear 3/4 View



Figure A-15: Pre-Test Right Rear 3/4 View



Figure A-16: Post-Test Right Rear 3/4 View



Figure A-17: Pre-Test Rear View



Figure A-18: Post-Test Rear View




Figure A-19: Pre-Test MDB Front View



Figure A-20: Post-Test MDB Front View




Figure A-21: Pre-Test MDB Left Side View



Figure A-22: Post-Test MDB Left Side View




Figure A-23: Pre-Test MDB Right Side View



Figure A-24: Post-Test MDB Right Side View




Figure A-25: Pre-Test MDB Top View



Figure A-26: Post-Test MDB Top View




Figure A-27: Pre-Test Overhead Vehicle and MDB View




Figure A-28: Post-Test Impact Target View




Figure A-29: Pre-Test Front Underbody View




Figure A-30: Post-Test Front Underbody View



Figure A-31: Pre-Test Mid Underbody View



Figure A-32: Post-Test Mid Underbody View



Figure A-33: Pre-Test Rear Underbody View



Figure A-34: Post-Test Rear Underbody View



Figure A-35: Pre-Test Fuel Filler Cap View



Figure A-36: Post-Test Fuel Filler Cap View



Figure A-37: Impact View



Figure A-38: Speed Trap View*




Figure A-39: Rollover 90° View



Figure A-40: Rollover 180° View



Figure A-41: Rollover 270° View




Figure A-42: Rollover 360° View