

REPORT NUMBER: SideNCAPPole-KAR-24-012
NEW CAR ASSESSMENT PROGRAM (NCAP)
SIDE IMPACT POLE TEST

SUBARU CORPORATION
2025 SUBARU FORESTER 5-DOOR MPV

NHTSA No: O20255501

PREPARED BY:
APPLUS IDIADA KARCO ENGINEERING, LLC.
9270 HOLLY ROAD
ADELANTO, CA 92301



DECEMBER 10, 2024

FINAL REPORT

PREPARED FOR:
U.S. DEPARTMENT OF TRANSPORTATION
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
OFFICE OF CRASHWORTHINESS STANDARDS
MAIL CODE: NRM-110
1200 NEW JERSEY AVE, SE
WASHINGTON, D.C. 20590

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names or products are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Prepared By: _____



Mr. Christopher A. Juarez, Project Engineer
Applus IDIADA KARCO Engineering, LLC.

Reviewed By: _____



Mr. Rushlan Amin, Project Engineer
Applus IDIADA KARCO Engineering, LLC.

Approved By: _____



Mr. Michael L. Dunlap, Director of Operations
Applus IDIADA KARCO Engineering, LLC.

Approval Date: _____ December 10, 2024

FINAL REPORT ACCEPTANCE BY OCWS:

Division Chief, New Car Assessment Program
NHTSA, Office of Crashworthiness Standards

Date: _____

COTR, New Car Assessment Program
NHTSA, Office of Crashworthiness Standards

Date: _____

TECHNICAL REPORT DOCUMENTATION PAGE

1. Report No. SideNCAPPole-KAR-24-012	2. Government Accession No.	3. Recipient's Catalog No.																												
4. Title and Subtitle Final Report of New Car Assessment Program Side Impact Pole Testing of a 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501		5. Report Date December 10, 2024																												
		6. Performing Organization Code KAR																												
7. Authors Mr. Christopher A. Juarez, Project Engineer, Applus IDIADA KARCO Engineering, LLC Mr. Rushlan Amin, Project Engineer, Applus+ IDIADA KARCO Engineering LLC.		8. Performing Organization Report No. TR-P44318-01-NC																												
		10. Work Unit No.																												
9. Performing Organization Name and Address Applus IDIADA KARCO Engineering, LLC. 9270 Holly Rd. Adelanto, CA 92301		11. Contract or Grant No. 693JJ920D000015																												
		13. Type of Report and Period Covered Final Test Report, November 21 - December 10, 2024																												
12. Sponsoring Agency Name and Address U. S. Department of Transportation National Highway Traffic Safety Administration Office of Crashworthiness Standards (NRM-110) 1200 New Jersey Ave., SE Washington, D.C. 20590		14. Sponsoring Agency Code NRM-110																												
		15. Supplementary Notes																												
16. Abstract A 32.2 km/h 75° rigid pole side NCAP impact test was conducted on the subject 2025 Subaru Forester 5-Door MPV in accordance with the specifications of the Office of Crashworthiness Standards Side NCAP Pole Laboratory Test Procedure for the generation of consumer information on vehicle side pole crash protection. The test was conducted at the Applus IDIADA KARCO Engineering, LLC. facility in Adelanto, California on November 21, 2024. The impact velocity was 32.28 km/h and the outside ambient temperature at the struck (driver's) side of the vehicle was 20.0°C. The target vehicle's maximum post-test static crush was 352 mm located at level 3. The test vehicle's occupant performance data is as follows: <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th rowspan="2">Measurement Description</th> <th colspan="3">Driver ATD (SID-IIs)</th> </tr> <tr> <th>Units</th> <th>Threshold</th> <th>Result</th> </tr> </thead> <tbody> <tr> <td>Head Injury Criteria (HIC₃₆)</td> <td></td> <td>1000</td> <td>166.702</td> </tr> <tr> <td>Resultant Lower Spine Acceleration</td> <td>g</td> <td>82</td> <td>33.782</td> </tr> <tr> <td>Total Pelvic Force (Sum of Acetabular and Iliac Forces)</td> <td>N</td> <td>5525</td> <td>2618.227</td> </tr> <tr> <td>Maximum Thoracic Rib Deflection</td> <td>mm</td> <td>38</td> <td>16.885</td> </tr> <tr> <td>Maximum Abdominal Rib Deflection</td> <td>mm</td> <td>45</td> <td>11.350</td> </tr> </tbody> </table>				Measurement Description	Driver ATD (SID-IIs)			Units	Threshold	Result	Head Injury Criteria (HIC ₃₆)		1000	166.702	Resultant Lower Spine Acceleration	g	82	33.782	Total Pelvic Force (Sum of Acetabular and Iliac Forces)	N	5525	2618.227	Maximum Thoracic Rib Deflection	mm	38	16.885	Maximum Abdominal Rib Deflection	mm	45	11.350
Measurement Description	Driver ATD (SID-IIs)																													
	Units	Threshold	Result																											
Head Injury Criteria (HIC ₃₆)		1000	166.702																											
Resultant Lower Spine Acceleration	g	82	33.782																											
Total Pelvic Force (Sum of Acetabular and Iliac Forces)	N	5525	2618.227																											
Maximum Thoracic Rib Deflection	mm	38	16.885																											
Maximum Abdominal Rib Deflection	mm	45	11.350																											
17. Key Words New Car Assessment Program (NCAP) Side Impact Pole Part 572V SID-IIs		18. Distribution Statement Copies of this report are available from: National Highway Traffic Safety Admin. Office of Crashworthiness Standards (NRM-110) 1200 New Jersey Ave., SE Washington, DC 20590																												
		19. Security Classification of this report UNCLASSIFIED																												
20. Security Classification of this page UNCLASSIFIED		21. No. of Pages 104	22. Price																											

TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1	Purpose and Summary of the Test	1
2	Occupant and Vehicle Information / Data Sheets	3
<u>Data Sheet</u>		<u>Page</u>
1	General Test and Vehicle Parameter Data	4
2	Seat, Seat Belt, Steering Wheel Adjustment, and Fuel System Data	8
3	Dummy Longitudinal Clearance Dimensions	12
4	Dummy Lateral Clearance Dimensions	13
5	Camera and Instrumentation Data	14
6	Test Vehicle Accelerometer Locations	15
7	Rigid Pole Load Cell Data	16
8	Post-Test Observations	17
9	Test Vehicle Profile Measurements	19
10	Test Vehicle Exterior Crush Measurements	20
11	Vehicle Damage Profile Distances	23
12	FMVSS No. 301 Static Rollover Results	24
13	Dummy/Vehicle Temperature and Humidity Stabilization	25
<u>Appendix</u>		<u>Page</u>
A	Photographs	A
B	Vehicle and Dummy Response Data Plots	B
C	ATD Configuration and Performance Verification Data	C
D	Test Equipment and Instrumentation Calibration Data	D

SECTION 1

TEST PURPOSE AND SUMMARY OF TEST

PURPOSE

This side impact test is part of the 2025 New Car Assessment Program Side Impact Test Program, sponsored by the National Highway Traffic Safety Administration (NHTSA), under contract number 693JJ920D000015. The purpose of this test is to generate comparative side impact performance in a 2025 Subaru Forester 5-Door MPV. The side impact test was conducted in accordance with the Office of Crashworthiness Standard's Laboratory Test Procedure dated March 2020.

SUMMARY

A rigid pole side impact test was conducted on a 2025 Subaru Forester 5-Door MPV. The subject vehicle was towed into the rigid pole at an angle of 75.2° and a velocity of 32.28 km/h. The test was conducted by Applus IDIADA KARCO Engineering, LLC. in Adelanto, California on November 21, 2024. Pre- and post-test photographs of the test vehicle and side impact dummy (SID-IIs) are included in Appendix A of this report.

One 299 (SID-IIs) dummy was placed in the driver designated seating position according to instructions specified in the OCWS Side NCAP Pole Laboratory Test Procedure, dated March 2020. Camera locations and other pertinent camera information are included in this report.

The 299 (SID-IIs) was instrumented accordingly:

- Primary and redundant head CG tri-axial accelerometers
- Head triaxial angular rate sensors
- Thorax upper, middle and lower rib displacement potentiometers
- Abdomen upper and lower rib displacement potentiometers
- Lower spine (12) tri-axial accelerometers
- Iliac load cell
- Acetabulum load cell

Appendix B contains the vehicle and dummy response data. Dummy configuration and performance verification data can be found in Appendix C of this report. Appendix D contains the test equipment and instrumentation calibration data.

SECTION 1 ...(CONTINUED)
TEST PURPOSE AND SUMMARY OF TEST

Injury readings for the SID-IIs dummy were recorded as follows:

Measurement Description	Units	Driver ATD (SID-IIs)	
		IARV	Result
Head Injury Criteria (HIC ₃₆)		1000	166.702
Lower Spine (T12) Resultant Acceleration	g	82	33.782
Total Pelvic Force (sum of acetabular and iliac forces)	N	5525	2618.227
Maximum Thoracic Rib Deflection	mm	38*	16.885
Maximum Abdominal Rib Deflection	mm	45*	11.350

**Proposed IARV*

Supplemental restraint information is given below:

Restraint Type	Left Front (Driver) Occupant Location 1		Left Rear (Passenger) Occupant Location 4	
	Mounted	Deployed	Mounted	Deployed
Frontal Air Bag	Yes	No		
Knee Air Bag	Yes	No		
Side Air Bag 1 (Curtain)	Yes	Yes	Yes	Yes
Side Air Bag 2 (Torso/Pelvis)	Yes	Yes	No	
Seat Belt Pretensioner	Yes	Yes	Yes	Yes
Seat Belt Load Limiter	Yes	Yes	Yes	Yes

GENERAL COMMENTS: NONE

SECTION 2

OCCUPANT AND VEHICLE INFORMATION/DATA SHEETS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

CONVERSION FACTORS

Quantity	Typical Application	Std Units	Metric Unit	Multiply By
Mass	Vehicle Weight	lb	kg	0.4536
Linear Velocity	Impact Velocity	miles/hr	km/hr	1.609344
Length or Distance	Measurements	in	mm	25.4
Volume	Fuel Systems	gal	liter	3.785
Volume	Small Fluids	oz	mL	29.574
Pressure	Tire Pressures	lbf/in ²	kPa	6.895
Temperature	General Use	°F	°C	$=(T_f - 32)/1.8$
Force	Dynamic Forces	lbf	N	4.448
Moment	Torque	lbf-ft	N•m	1.355

DATA SHEET NO. 1

GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

TEST VEHICLE INFORMATION AND OPTIONS

NHTSA Number	O20255501
Model Year	2025
Make	Subaru
Model	Forester
Body Style	5-Door MPV
VIN	JF2SLDACXSH452821
Body Color	Magnetite Gray Metallic
Odometer Reading (km / mi)	16/10
Engine Displacement (L)	2.5
Type / No. of Cylinders	4 Cylinders
Engine Placement	Longitudinal
Transmission Type	Automatic
Transmission Speeds	Lineartronic CVT
Overdrive	Yes
Final Drive	AWD
Roof Rack	Yes
Sunroof / T-Top	No
Running Boards	No
Tilt Steering Wheel	Yes
Power Seats	No
Anti-Lock Brakes (ABS)	Yes

Traction Control System (TCS)	Yes
Auto-Leveling System	No
Automatic Door Locks	Yes
Power Window Auto-Reverse	Yes
Other Optional Feature	Yes
Driver Front Air Bag	Yes
Driver Curtain Air Bag	Yes
Driver Head/Torso Air Bag	No
Driver Torso Air Bag	No
Driver Torso/Pelvis Air Bag	Yes
Driver Pelvis Air Bag	No
Driver Knee Air Bag	Yes
Rear Pass. Curtain Air Bag	Yes
Rear Pass. Head/Torso Air Bag	No
Rear Pass. Torso Air Bag	No
Rear Pass. Torso/Pelvis Air Bag	No
Rear Pass. Pelvis Air Bag	No
Driver Seat Belt Pretensioner	Yes
Rear Pass. Seat Belt Pretensioner	Yes
Driver Load Limiter	Yes
Rear Pass. Load Limiter	Yes
Other Safety Restraint	Yes

Does Owner's Manual provide instructions to turn off automatic door locks?

Yes; Page 231

DATA FROM CERTIFICATION LABEL

Manufactured By	Subaru Corporation
Date of Manufacture	Jul-24
Vehicle Type	MPV/VTUM

GVWR (kg)	2223
GAWR Front (kg)	1302
GAWR Rear (kg)	1130

VEHICLE SEATING AND CAPACITY WEIGHT INFORMATION

Measured Parameter	Front	Rear	Third	Total	
Designated Seating Capacity	2	3		5	
Capacity Weight (VCW) (kg)				408.0	A
DSC x 68 (kg)				340.0	B
Cargo Weight (RCLW) (kg)				68.0	A-B*

*For trucks or MPVs, if A-B>136, RCLW=136 kg

VEHICLE SEAT TYPE

Seating Location	Type of Seat Pan				Type of Seat Back		
	Bucket	Bench	Split Bench	Contoured	Fixed	Adjustable	
						w/ Lever	w/ Knob
Front Seat	Yes					Yes	
Rear or Second Row Seat		Yes			Yes		
Third Row Seat							

DATA SHEET NO. 1 ... (CONTINUED)

GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

TIRE PRESSURES

	Units	LF	RF	LR	RR
As Delivered	kPa	230	230	220	220
Tire Placard	kPa	230	230	220	220
Owner's Manual	kPa	230	230	220	220
As Tested	kPa	230	230	220	220

TEST VEHICLE AXLE WEIGHTS

	Units	As Delivered (UVW)			As Tested (ATW)			Fully Loaded		
		Front	Rear	Total	Front	Rear	Total	Front	Rear	Total
Left	kg	473.0	336.5		485.5	389.0		519.0	370.5	
Right	kg	448.5	331.5		449.0	377.5		452.5	365.0	
Ratio	%	58.0%	42.0%	100.0%	54.9%	45.1%	100.0%	56.9%	43.1%	100.0%
Total	kg	921.5	668.0	1589.5	934.5	766.5	1701.0	971.5	735.5	1707.0

TARGET TEST WEIGHT CALCULATION+

Measured Parameter	Units	Value
Total Delivered Weight (UVW)	kg	1589.5
Actual Weight of 1 SID II-s ATD Used	kg	49.0
Rated Cargo/Luggage Wt (RCLW)	kg	68.0
Calculated Vehicle Target Wt (TVTW)	kg	1706.5

A
B
C
A+B+C

Does the measured As Tested Vehicle Weight lie within the required weight range (i.e.

Calculated Test Vehicle Target Weight -4.5 kg to -9.0 kg)? ☒ Yes ☐ No

TEST VEHICLE ATTITUDE AND CG

Measurement Description	Units	As Delivered	As Tested	Fully Loaded	Meets Requirement***
Driver Door Sill Angle (front-to-rear)*	°	0.2	0.0	-0.1	Yes
Front Passenger Sill Angle (front-to-rear)*	°	1.4	-0.1	-0.3	Yes
Front Bumper-Line Angle (left-to-right)**	°	-1.1	-1.3	-1.6	Yes
Rear Bumper-Line Angle (left-to-right)**	°	0.8	-0.1	-0.1	Yes
Vehicle CG (Aft of Front Axle)	mm	1121	1202	1149	
Vehicle CG (Left (+)/Right (-) from Longitudinal Centerline)	mm	15	22	33	

*ND=Nose Down (-), NU=Nose Up (+) **LD=Left Down (-), LU=Left Up (+)

***The "As Tested" vehicle attitude angle measurements must be within "As Delivered" and the "Fully Loaded" vehicle attitude measurements at each location. Indicate "Yes" or "No" for "Meets Requirement"

DATA SHEET NO. 1 ... (CONTINUED)

GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

WEIGHT OF BALLAST AND VEHICLE COMPONENTS REMOVED TO MEET TVTW

Component Description	Weight (kg)
Spare Tire and Tools Removed	14.5
Trim Removed	3.0

TEST SURFACE MARKINGS

	Distance from 75° Impact Location Line (mm)
Fore 25 mm target	0
Aft 25 mm target	0

DATA SHEET NO. 2**SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT, AND FUEL SYSTEM DATA**

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

SEAT POSITIONING

The driver's seat, front center seat (if applicable), and front passenger's seat should be set to the forward most, mid-height, mid-angle position. The struck side rear passenger's seat, rear center seat, and non-struck side rear passenger's seat should be set to the rear most, lowest, mid-angle position.

SCRL ANGLE RANGE

Seat	SCRL (°)		
	Max	Min	Mid
Driver Seat	13.7	9.4	11.5
Front Passenger Seat			13.4
Front Center Seat			
Struck Side Rear Seat	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed
Rear Center Seat	Fixed	Fixed	Fixed

SEAT HEIGHT AND ANGLE

Seat	As Tested SCRL Angle (Mid) (°)	As Tested SCR Height (mm)	SCR Height Position	SCR Height (mm)		
				Rearmost	Mid Fore/Aft	Forwardmost
Driver Seat	11.5	617	Max			
			Mid	613	617	621
			Min			
Front Passenger Seat	13.4	542	Max			
			Mid	672	675	680
			Min			
Front Center Seat			Max			
			Mid			
			Min			
Struck Side Rear Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed
Rear Center Seat	Fixed	Fixed	Max	Fixed	Fixed	Fixed
			Mid	Fixed	Fixed	Fixed
			Min	Fixed	Fixed	Fixed

DATA SHEET NO. 2 ... (CONTINUED)

SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT, AND FUEL SYSTEM DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24


SEAT FORE/AFT POSITION

Seat	Total Fore/Aft Travel		Test Position From Forwardmost Position	
	mm	Detents*	mm	Detent*
Driver Seat	260	26	0	0
Front Passenger Seat	260	26	0	0
Front Center Seat				
Struck Side Rear Seat	Fixed	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed	Fixed
Rear Center Seat	Fixed	Fixed	Fixed	Fixed

*Detent zero (0) is the forward most detent

SEAT BACK ADJUSTMENT

The driver's seat back is positioned such that the dummy's head is level. The front passenger's seat back is positioned in a similar manner to the driver's seat. The struck side rear passenger seat back is positioned in accordance with the information provided by the manufacturer in Form 1 for the 5th percentile female dummy in a Side NCAP MDB Test. The rear center and non-struck side rear passenger's seat back is set to match the struck side rear seat back. Seat back angle is measured using an inclinometer along the bottom of the headrest post.



Seat	Total Seat Back Angle Range		Test Position from Most Upright	
	Degrees	Detents*	Degree	Detent*
Driver Seat w/Seated Dummy	75.9	37		6
Front Passenger Seat	75.8	37		6
Front Center Seat				
Struck Side Rear Seat w/Seated Dummy	Fixed	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed	Fixed
Rear Center Seat	Fixed	Fixed	Fixed	Fixed

*Detent zero (0) is the forward most detent

DATA SHEET NO. 2 ... (CONTINUED)

SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT, AND FUEL SYSTEM DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

SEAT BELT ANCHORAGE ADJUSTMENT

Seat belt anchorages are adjusted in accordance with the information provided by the manufacturer on Form No. 1. The positions are marked H, M2, M1, L from top to bottom.

	Total No. of Positions	Placed in Position
Driver Seat	4	M2

HEAD RESTRAINT ADJUSTMENT


The driver's head restraint is adjusted to the lowest and most full forward in-use position.

	Total No. of Positions	Placed in Position
Driver Seat	4	L

STEERING COLUMN ADJUSTMENT

Steering wheel and column adjustments are made so that the steering wheel hub is at the center of the geometric locus it describes when it moves through its full range of motion.

	Degrees	Fore-Aft Position (mm)
Lowermost - Position 1	25.9	79
Geometric Center - Position 2	27.7	104.5
Uppermost - Position 3	29.5	130
Telescoping Steering Wheel Travel		51
Test Position	27.7	104.5




DATA SHEET NO. 2 ... (CONTINUED)

SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT, AND FUEL SYSTEM DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

FUEL PUMP

The vehicle is equipped with an electric fuel pump. The pump will work at "ignition on" until pressure in the system has reached working pressure in the system; then it will stop pumping fuel until the engine has been started.



FUEL TANK CAPACITY


Description	Liters
Usable Capacity of "Standard Tank" (see Form No. 1)	62.84
Usable Capacity of "Optional Tank" (see Form No. 1)	
Usable Capacity of "Standard Tank" (see Owner's Manual)*	62.84
Usable Capacity of "Optional Tank" (see Owner's Manual)*	
93% of Usable Capacity	58.29
Actual amount of Solvent Used in Test	58.29
1/3 of Usable Capacity	20.95

Is the Actual Amount of Solvent Used in the test equal to 93% $\pm$ 1% of the Usable Capacity stated in the Form No. 1? ☒ Yes ☐ No

DATA SHEET NO. 3

DUMMY LONGITUDINAL CLEARANCE DIMENSIONS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24




Driver Code	Description	Driver	
		Length (mm)	Angle (°)
HH	Head to Header	315	
HW	Head to Windshield	583	0
HZ	Head to Roof	235	90
NR	Nose to Rim	265	
CD	Chest to Dash	410	
CS	Chest to Steering Wheel	155	0
KD(L)/KDA(L)°	Left Knee to Dash	125	6.7
KD(R)/KDA(R)°	Right Knee to Dash	115	5.4
PAX°	Pelvic Tilt Angle (x-axis)		19.1
PAY°	Pelvic Tilt Angle (y-axis)		0.0
PHX	Hip Point to Striker (x-axis)	369	
PHZ	Hip Point to Striker (z-axis)	193	

DATA SHEET NO. 4

DUMMY LATERAL CLEARANCE DIMENSIONS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24




Code	Measurement Description	Units	Driver
HR	Head to Side Header	mm	370
HS	Head to Side Window	mm	395
AD	Arm to Door	mm	175
HD	Hip Point to Door	mm	180

DATA SHEET NO. 5

CAMERA AND INSTRUMENTATION DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24



Reference from Point of Impact for X and Y; from Ground for Z):
 +X = Forward of Vehicle, +Y = Right of Vehicle, +Z = Down

Camera No.	View	Coordinates (m)			Lens (mm)	Film Speed (fps)
		X*	Y*	Z*		
1	Real Time Pan View of Impact	8.89	46.57	-3.04		30
2	Front Ground Level - Impact View	8.34	-0.05	-0.93	35	1000
3	Impact Side 45° - Forward Pole View	4.10	-2.15	-1.15	25	1000
4	Overhead Close-Up View of Impact	0.00	0.00	-5.79	35	1000
5	On-Board - Dummy Front View	-1.18	-0.84	-0.83	8	1000
6	On-Board - Dummy Side View	-1.19	-0.84	-0.82	6	1000
7	On-Board - Dummy Rear Oblique View	0.90	-0.92	-0.55	6	1000
8	Rear Ground Level - Impact View	-1.30	1.68	-1.26	35	1000
9	Impact Side 45° - Rearward Pole View	-8.02	0.04	-1.01	25	1000
10	Overhead Wide View of Impact	-0.06	0.22	-5.79	15	1000
11	Real Time Dummy Front View	0.88	-0.96	-0.54		30

*All measurements accurate to ± 6 mm

NOTE: Vehicle is at a 75 angle to the rigid pole.

If applicable, explain why camera(s) did not operate as intended: N/A


INSTRUMENTATION

Driver Dummy Channels	19
Vehicle Structure Accelerometers	18
Pole Load Cells	8
Total	45

DATA SHEET NO. 6

TEST VEHICLE ACCELEROMETER LOCATIONS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24




Loc. No.	Sensor Description	Coordinates (mm)		
		X	Y	Z
1	Vehicle CG	1800	0	-450
2	Left Floor Sill	2650	-740	-300
3	A-Pillar Sill	3500	-840	-490
4	A-Pillar Low	3500	-840	-770
5	A-Pillar Mid	3500	-840	-960
6	B-Pillar Sill	1900	-730	-470
7	B-Pillar Low	1900	-730	-660
8	B-Pillar Mid	1900	-730	-900
9	Driver Seat Track	2370	-620	-490
10	Engine Top	3980	-20	-690
11	Firewall	3450	-170	-990
12	Right Roof	1910	520	-1690
13	Right Floor Sill	2550	740	-300
14	Rear Floorpan	930	0	-670

Reference: X – Rear surface of vehicle (+ forward)
 Y – Vehicle centerline (+ to right)
 Z – Ground plane (+ down)

DATA SHEET NO. 7
RIGID POLE LOAD CELL DATA

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24



ID	Units	Height From Ground
1	mm	87
2	mm	468
3	mm	648
4	mm	978
5	mm	1168
6	mm	1651
7	mm	1816
8	mm	2057

DATA SHEET NO. 8
POST-TEST OBSERVATIONS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

TEST DUMMY INFORMATION AND CONTACT POINTS

Dummy Body Part	Driver SID-IIs Dummy
Face	Curtain Air Bag
Top of Head	Curtain Air Bag
Left Side of Head	Curtain Air Bag
Back of Head	Curtain Air Bag, Headrest
Left Shoulder	Torso/Pelvis Air Bag
Upper Torso	Torso/Pelvis Air Bag, Seat Bolster
Lower Torso	Torso/Pelvis Air Bag, Seat Bolster
Left Hip	Torso/Pelvis Air Bag, Seat Bolster
Left Knee	Door Panel

POST-TEST DOOR PERFORMANCE

Description	Struck Side		Non-Struck Side		Rear Hatch/Other Door
	Front	Rear	Front	Rear	
Remained Closed and Operational	No	No	Yes	Yes	Yes
Total Separation from Vehicle at Hinges or Latches	No	No	No	No	No
Latch or Hinge System Pulled Out of Their Anchorages	No	No	No	No	No
Disengaged from Latched Position	No	No	No	No	No
Latch Separated from Striker	No	No	No	No	No
Jammed Shut	Yes	Yes	No	No	No
If Door Opened at Striker, Record Width of Opening at Striker (mm)	No	No	No	No	No

POST-TEST SEAT PERFORMANCE

Description	Struck Side		Non-Struck Side	
	Front	Rear	Front	Rear
Seat Movement Along Seat Track	No		No	
Seat Disengagement from Floor Pan	No	No	No	No
Seat Back Movement from Initial Position	No	No	No	No
Seat Back Collapse	No	No	No	No

DATA SHEET NO. 8 ... (CONTINUED)**POST-TEST OBSERVATIONS**

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

POST-TEST STRUCTURAL OBSERVATIONS

Critical Areas of Performance	Observations and Conclusions
Pillar Performance	Good
Sill Separation	None
Windshield Damage	Broken
Side Window Damage	Broken
Other Notable Effects	None

SUPPLEMENTAL RESTRAINT SYSTEM INFORMATION

Restraint Type	Struck Side Driver		Struck Side Rear Passenger	
	Mounted	Deployed	Mounted	Deployed
Frontal Air Bag	Yes	No		
Knee Air Bag	Yes	No		
Side Air Bag 1 (Curtain)	Yes	Yes	Yes	Yes
Side Air Bag 2 (Torso/Pelvis)	Yes	Yes	No	
Seat Belt Pretensioner	Yes	Yes	Yes	Yes
Seat Belt Load Limiter	Yes	Yes	Yes	Yes


IMPACT POINT LOCATION DATA

Measured Parameter	Units	Tolerance	Value
Vertical Impact Reference Line (Aft of Front Axle)(Intended Impact Point)	mm		1069
Actual Impact Point (Aft of Front Axle)	mm		1065
Horizontal Offset (+ forward / - rearward)	mm	± 38 of Intended Impact Point	-4
Angle Between Vehicle's Longitudinal Centerline and Line of Forward Motion	°	75 ± 3	75.2
Trap No. 1 Velocity (Primary)	km/h	31.4 to 33.0	32.28
Trap No. 2 Velocity (Redundant)	km/h	31.4 to 33.0	32.30

DATA SHEET NO. 9

TEST VEHICLE PROFILE MEASUREMENTS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24



LEFT SIDE VIEW

All measurements in mm with tolerance of $\pm 3\text{mm}$


VEHICLE PRE- AND POST-TEST MEASUREMENT INFORMATION

Code	Description	Pre-Test	Post-Test	Change
A	Wheelbase	2666	2570	-96
B	Front Axle to FSOV	996	1061	65
C	Rear Axle to RSOV	994	985	-9
D	Total Length at Centerline	4656	4616	-40
E	Front Bumper Thickness	146	145	-1
F	Front Bumper Bottom to Ground	455	438	-17
G	Sill Height at Front Wheel Well	370	327	-43
H	Sill Height at Front Door Leading Edge	382	340	-42
I	Sill Height at B-Pillar	322	313	-9
J1	Sill Height at Rear Wheel Well	371	375	4
J2	Pinch Weld Height at Rear Wheel Well	262	275	13
K	Sill Height Aft of Rear Wheel Well	449	448	-1
L	Rear Bumper Thickness	182	180	-2
M	Rear Bumper Bottom to Ground	464	466	2
N	Sill Height to Bottom of Front Window Sill	630	645	15
O	Front Door Leading Edge to Impact CL	587	520	-67
P	Rear Door Trailing Edge to Impact CL	1505	1414	-91
Q	Front Window Opening	441	429	-12
R	Right Side Length	3400	3409	9
S	Left Side Length	3403	3291	-112
T	Vehicle Width at B-Pillar	1829	1738	-91

DATA SHEET NO. 10

TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24



NOTE: All measurements in mm with tolerance of $\pm 3\text{mm}$

MAXIMUM EXTERIOR CRUSH MEASUREMENTS

Level	Description	Height Above Ground (mm)	Maximum Exterior Static Crush	Distance from Impact
1	Sill Top	312	328	0
2	Occupant H-Point	698	348	0
3	Mid-Door	749	352	0
4	Window Sill	1088	261	0
5	Window Top	1560	125	150

DATA SHEET NO. 10 ... (CONTINUED)

TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

EXTERIOR CRUSH MEASUREMENTS AT EACH LEVEL

	Pre-Test (mm)					Post-Test (mm)					Crush (mm)				
	1	2	3	4	5	1	2	3	4	5	1	2	3	4	5
-900				690					600					-90	
-750			586	685				529	618				-57	-67	
-600	635	587	588	679		592	550	562	635		-43	-37	-26	-44	
-450	630	589	590	690		658	610	619	715		28	21	29	25	
-300	613	589	589	691		729	715	718	788		116	126	129	97	
-150	608	588	588	690		819	836	838	872		211	248	250	182	
0	607	588	587	688	876	935	936	939	949	982	328	348	352	261	106
150	606	588	587	690	878	886	909	912	943	1003	280	321	325	253	125
300	608	589	588	688	882	789	784	788	851	972	181	195	200	163	90
450	609	591	589	691	886	709	681	685	784	951	100	90	96	93	65
600	610	593	591	693	889	652	643	642	746	930	42	50	51	53	41
750	614	596	594	696	892	635	629	630	738	913	21	33	36	42	21
900	621	597	596	697	894	629	616	618	729	905	8	19	22	32	11
1050	631	591	592	700	897	623	596	600	721	902	-8	5	8	21	5
1200		584	584	703	898		577	579	713	900		-7	-5	10	2
1350			585	707	898			567	707	900			-18	0	2
1500				712	897				715	900				3	3
1650															
1800															
1950															
2100															
2250															
2400															
2550															
2700															
2850															

DATA SHEET NO. 10 ... (CONTINUED)


TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2025 Subaru Forester 5-Door MPV

NHTSA No. O20255501

Test Program: NCAP Side Pole Impact Test

Test Date: 11/21/24




DATA SHEET NO. 11

VEHICLE DAMAGE PROFILE DISTANCES

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501

Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24



DPD	Distance From Impact Point (mm)	Level	Pre-Test (mm)	Post-Test (mm)	Crush (mm)
1	1500	4	712	715	3
2	900	4	697	729	32
3	450	1	609	709	100
4	0	3	587	939	352
5	-450	3	590	619	29
6	-900	4	690	600	-90


DATA SHEET NO. 12

FMVSS NO. 301 STATIC ROLLOVER RESULTS

Test Vehicle: 2025 Subaru Forester 5-Door MPV NHTSA No. O20255501
 Test Program: NCAP Side Pole Impact Test Test Date: 11/21/24

Temperature at Time of Impact: 20.0° C Test Time: 12:00 PM

- A. From impact until vehicle motion ceases: 0 oz.
 (Maximum allowable = 1 oz.)
- B. For the 5 minute period after motion ceases: 0 oz.
 (Maximum allowable = 5 oz.)
- C. For the following 25 minutes: 0 oz.
 (Maximum allowable = 1 oz./minute)
- D. Spillage Details: There was no Stoddard solvent spillage.



SOLVENT COLLECTION TIME TABLE IN SECONDS

Test Phase	Rotation Time	Hold Time	Total Time
0° To 90°	80	300	380
90° To 180°	82	300	382
180° To 270°	81	300	381
270° To 360°	85	300	385

FMVSS 301 SPILLAGE TABLE

Test Phase	First 5 Minutes	Sixth Minute	Seventh Minute	Eighth Minute
0° To 90°				
90° To 180°				
180° To 270°				
270° To 360°				

SOLVENT SPILLAGE LOCATION TABLE

Test Phase	Spillage Location
0° To 90°	
90° To 180°	
180° To 270°	
270° To 360°	

DATA SHEET NO. 13


DUMMY/VEHICLE TEMPERATURE AND HUMIDITY STABILIZATION

Test Vehicle: 2025 Subaru Forester 5-Door MPV

NHTSA No. O20255501

Test Program: NCAP Side Pole Impact Test

Test Date: 11/21/24



APPENDIX A
PHOTOGRAPHS

TABLE OF PHOTOGRAPHS

Figure		Page
1	As Delivered Right Front $\frac{3}{4}$ View of Test Vehicle	A-1
2	As Delivered Left Rear $\frac{3}{4}$ View of Test Vehicle	A-1
3	Pre-Test Frontal View of Test Vehicle	A-2
4	Post-Test Frontal View of Test Vehicle	A-2
5	Pre-Test Left Front $\frac{3}{4}$ View of Test Vehicle	A-3
6	Post-Test Left Front $\frac{3}{4}$ View of Test Vehicle	A-3
7	Pre-Test Left Side View of Test Vehicle	A-4
8	Post-Test Left Side View of Test Vehicle	A-4
9	Pre-Test Left Rear $\frac{3}{4}$ View of Test Vehicle	A-5
10	Post-Test Left Rear $\frac{3}{4}$ View of Test Vehicle	A-5
11	Pre-Test Rear View of Test Vehicle	A-6
12	Post-Test Rear View of Test Vehicle	A-6
13	Pre-Test Right Side View of Test Vehicle	A-7
14	Post-Test Right Side View of Test Vehicle	A-7
15	Pre-Test Overhead View of Test Area	A-8
16	Post-Test Overhead View of Test Area	A-8
17	Pre-Test Left Side View of Pole Positioned Against Side of Vehicle	A-9
18	Pre-Test Right Side View of Pole Positioned Against Side of Vehicle	A-9
19	Pre-Test Close-Up View of Impact Point Target	A-10
20	Post-Test Close-Up View of Impact Point Target Showing Impact Location	A-10
21	Pre-Test Front Close-Up View of Dummy Head and Chest	A-11
22	Post-Test Front Close-Up View of Dummy	A-11
23	Pre-Test Left Side View of Dummy Showing Belt and Chalking	A-12
24	Pre-Test Left Side View of Dummy Shoulder and Door Top View	A-12
25	Post-Test Left Side View of Dummy Shoulder and Door Top View	A-13
26	Pre-Test Frontal View of Seat Back Prior to Dummy Positioning	A-13
27	Pre-Test Frontal Close-Up View of Dummy Head and Shoulders in Relation to Head Restraint	A-14
28	Pre-Test Overhead View of Seat Pan Prior to Dummy Positioning	A-14
29	Pre-Test Overhead View of Dummy Thighs on Seat Pan	A-15
30	Pre-Test Left Side View of Dummy's Neck Showing Position of Adjustable Neck Bracket	A-15
31	Pre-Test Left Side View of Dummy's Head Showing Dummy's Head is Level	A-16
32	Pre-Test Placement of Dummy's Feet	A-16
33	Pre-Test View of Belt Anchorage for Dummy	A-17
34	Pre-Test Left Side View of Steering Wheel	A-17
35	View of Disengaged Parking Brake	A-18

TABLE OF PHOTOGRAPHS ... (CONTINUED)

Figure		Page
36	Pre-Test View of Parking Brake	A-18
37	Pre-Test Close-Up Left Side View of Driver Seat Track	A-19
38	Pre-Test Close-Up Left Side View of Driver Seat Back	A-19
39	Pre-Test Close-Up View of Driver Seat Back or Head Restraint	A-20
40	Pre-Test Dummy and Door Clearance View	A-20
41	Post-Test Dummy and Door Clearance View	A-21
42	Pre-Test Right Side View of Dummy and Front Seat of Occupant Compartment	A-21
43	Post-Test Right Side View of Dummy and Front Seat of Occupant Compartment	A-22
44	Pre-Test Inner Door Panel View	A-22
45	Post-Test Inner Door Panel View Showing Dummy Contact Locations	A-23
46	Post-Test Dummy Close-Up Head Contact with Vehicle Interior View	A-23
47	Post-Test Dummy Close-Up Head Contact with Side Air Bag View	A-24
48	Post-Test Dummy Close-Up Torso Contact with Vehicle Interior View	A-24
49	Post-Test Dummy Close-Up Torso Contact with Side Air Bag View	A-25
50	Post-Test Dummy Close-Up Pelvis Contact with Vehicle Interior View	A-25
51	Post-Test Dummy Close-Up Pelvis Contact with Side Air Bag View	A-26
52	Post-Test Dummy Close-Up Knee Contact with Vehicle Interior View	A-26
53	Post-Test Right Side View of Dummy and Rear Seat of Occupant Compartment	A-27
54	Pre-Test Inner Rear Passenger Torso Air Bag Deployment View	A-27
55	Pre-Test View of Fuel Filler Cap or Fuel Filler Neck	A-28
56	Post-Test View of Fuel Filler Cap or Fuel Filler Neck	A-28
57	Close-Up View of Vehicle's Certification Label	A-29
58	Close-Up View of Vehicle's Tire Information Placard or Label	A-29
59	Pre-Test Pole Barrier Front View	A-30
60	Post-Test Pole Barrier Front View	A-30
61	Pre-Test Pole Barrier Side View	A-31
62	Post-Test Pole Barrier Side View	A-31
63	Pre-Test Ballast View	A-32
64	Post-Test Primary and Redundant Speed Trap Read-Out	A-32
65	FMVSS No. 301 Static Rollover 0 Degrees	A-33
66	FMVSS No. 301 Static Rollover 90 Degrees	A-33
67	FMVSS No. 301 Static Rollover 180 Degrees	A-34
68	FMVSS No. 301 Static Rollover 270 Degrees	A-34
69	FMVSS No. 301 Static Rollover 360 Degrees	A-35
70	Impact Event	A-35

TABLE OF PHOTOGRAPHS ... (CONTINUED)

Figure		Page
71	Monroney Label	A-36
72	Head Restraint Use and Adjustment Information from Vehicle Owner's Manual	A-36
73	Post-Test View of Shattered Vehicle Inner Door Panel	A-37



FIGURE 1. As-Delivered Right Front 3/4 View of Test Vehicle



FIGURE 2. As-Delivered Left Rear 3/4 View of Test Vehicle



FIGURE 3. Pre-Test Frontal View of Test Vehicle



FIGURE 4. Post-Test Frontal View of Test Vehicle



FIGURE 5. Pre-Test Left Front 3/4 View of Test Vehicle



FIGURE 6. Post-Test Left Front 3/4 View of Test Vehicle



FIGURE 7. Pre-Test Left Side View of Test Vehicle



FIGURE 8. Post-Test Left Side View of Test Vehicle



FIGURE 9. Pre-Test Left Rear 3/4 View of Test Vehicle



FIGURE 10. Post-Test Left Rear 3/4 View of Test Vehicle



FIGURE 11. Pre-Test Rear View of Test Vehicle



FIGURE 12. Post-Test Rear View of Test Vehicle



FIGURE 13. Pre-Test Right Side View of Test Vehicle



FIGURE 14. Post-Test Right Side View of Test Vehicle



FIGURE 15. Pre-Test Overhead View of Test Area




FIGURE 16. Post-Test Overhead View of Test Area



FIGURE 17. Pre-Test Left Side View of Pole Positioned Against Side of Vehicle



FIGURE 18. Pre-Test Right Side View of Pole Positioned Against Side of Vehicle



FIGURE 19. Pre-Test Close-Up View of Impact Point Target



FIGURE 20. Post-Test Close-Up View of Impact Point Target Showing Impact Location



FIGURE 21. Pre-Test Front Close-Up View of Dummy Head and Chest



FIGURE 22. Post-Test Front Close-Up View of Dummy



FIGURE 23. Pre-Test Left Side View of Dummy Showing Belt and Chalking



FIGURE 24. Pre-Test Left Side View of Dummy Shoulder and Door Top View



FIGURE 25. Post-Test Left Side View of Dummy Shoulder and Door Top View



FIGURE 26. Pre-Test Frontal View of Seat Back Prior to Dummy Positioning



FIGURE 27. Pre-Test Frontal View of Dummy Head and Shoulders in Relation to Head Restraint



FIGURE 28. Pre-Test Frontal View of Seat Pan Prior to Dummy Positioning



FIGURE 29. Pre-Test Overhead View of Dummy Thighs on Seat Pan



FIGURE 30. Pre-Test Left Side View of Dummy's Neck Showing Position of Adjustable Neck Bracket



FIGURE 31. Pre-Test Left Side View of Dummy's Head Showing Head is Level



FIGURE 32. Pre-Test Placement of Dummy's Feet



FIGURE 33. Pre-Test View of Belt Anchorage for Dummy



FIGURE 34. Pre-Test Left Side View of Steering Wheel



FIGURE 35. View of Disengaged Parking Brake



FIGURE 36. Pre-Test View of Parking Brake



FIGURE 37. Pre-Test Close-Up Left Side View of Driver Seat Track



FIGURE 38. Pre-Test Close-Up Left Side View of Driver Seat Back



FIGURE 39. Pre-Test Close-Up View of Driver Seat Back or Head Restraint



FIGURE 40. Pre-Test Dummy and Door Clearance View



FIGURE 41. Post-Test Dummy and Door Clearance View



FIGURE 42. Pre-Test Right Side View of Dummy and Front Seat of Occupant Compartment



FIGURE 43. Post-Test Right Side View of Dummy and Front Seat of Occupant Compartment



FIGURE 44. Pre-Test Inner Door Panel View



FIGURE 45. Post-Test Inner Door Panel View Showing Dummy Contact Locations



FIGURE 46. Post-Test Dummy Close-Up Head Contact With Vehicle Interior View



FIGURE 47. Post-Test Dummy Close-Up Head Contact With Side Air Bag View



FIGURE 48. Post-Test Dummy Close-Up Torso Contact With Vehicle Interior View



FIGURE 49. Post-Test Dummy Close-Up Torso Contact With Side Air Bag View



FIGURE 50. Post-Test Dummy Close-Up Pelvis Contact With Vehicle Interior View



FIGURE 51. Post-Test Dummy Close-Up Pelvis Contact With Side Air Bag View



FIGURE 52. Post-Test Dummy Close-Up Knee Contact with Vehicle Interior View



FIGURE 53. Post-Test Right Side View of Dummy and Rear Seat of Occupant Compartment



FIGURE 54. Pre-Test Inner Rear Passenger Torso Air Bag Deployment View



FIGURE 55. Pre-Test View of Fuel Filler Cap or Fuel Filler Neck



FIGURE 56. Post-Test View of Fuel Filler Cap or Fuel Filler Neck



FIGURE 57. Close-Up View of Vehicle's Certification Label



FIGURE 58. Close-Up View of Vehicle's Tire Information Placard or Label



FIGURE 59. Pre-Test Pole Barrier Front View



FIGURE 60. Post-Test Pole Barrier Front View



FIGURE 61. Pre-Test Pole Barrier Side View



FIGURE 62. Post-Test Pole Barrier Side View




FIGURE 63. Pre-Test Ballast View



FIGURE 64. Post-Test Primary and Redundant Speed Trap Read-Out



FIGURE 65. FMVSS No. 301 Static Rollover 0 Degrees



FIGURE 66. FMVSS No. 301 Static Rollover 90 Degrees



FIGURE 67. FMVSS No. 301 Static Rollover 180 Degrees



FIGURE 68. FMVSS No. 301 Static Rollover 270 Degrees



FIGURE 69. FMVSS No. 301 Static Rollover 360 Degrees



FIGURE 70. Impact Event



FIGURE 71. Monroney Label




FIGURE 72. Head Restraint Use and Adjustment Information from Vehicle Owner's Manual

Photograph Not Applicable

Inner Door Panel Was Not Shattered

FIGURE 73. Post-Test View of Shattered Vehicle Inner Door Panel

APPENDIX B
DUMMY RESPONSE DATA

TABLE OF DATA PLOTS

Plot		Page
1	Driver Head Acceleration (X) Primary	B-1
2	Driver Head Acceleration (Y) Primary	B-1
3	Driver Head Acceleration (Z) Primary	B-1
4	Driver Head Acceleration Primary Resultant	B-1
5	Driver Lower Spine T12 Acceleration (X)	B-2
6	Driver Lower Spine T12 Acceleration (Y)	B-2
7	Driver Lower Spine T12 Acceleration (Z)	B-2
8	Driver Lower Spine T12 Acceleration Resultant	B-2
9	Driver Acetabulum Force on Impact Side (Y)	B-3
10	Driver Iliac Wing Force on Impact Side (Y)	B-3
11	Driver Total Pelvis Force on Impact Side (Y)	B-3

The following additional data for this test can be obtained from the Research and Development section of the NHTSA website. The website can be found at

www.NHTSA.gov

Additional Driver Dummy Instrumentation Data

Driver Head Acceleration Redundant (X)

Driver Head Acceleration Redundant (Y)





Driver Head Acceleration Redundant (Z)




Vehicle Instrumentation Data




Vehicle Center of Gravity Acceleration (X)
Vehicle Center of Gravity Acceleration (Y)
Vehicle Center of Gravity Acceleration (Z)
Left Floor Sill Acceleration (Y)
Left A-Pillar Sill Acceleration (Y)
Left Lower A-Pillar Acceleration (Y)
Left Mid A-Pillar Acceleration (Y)
Left B-Pillar Sill Acceleration
Left Lower B-Pillar Acceleration (Y)
Left Mid B-Pillar Acceleration (Y)
Driver Seat Track at Dummy Hip Point Acceleration (Y)
Engine Top Acceleration (X)
Engine Top Acceleration (Y)
Firewall Center Acceleration (Y)
Right Roof at Vertical Impact Reference Line Acceleration (Y)
Right Sill at Vertical Impact Reference Line Acceleration (Y)
Rear Floorpan Behind Rear Axle at Centerline Acceleration (X)
Rear Floorpan Behind Rear Axle at Centerline Acceleration (Y)

Pole Instrumentation Data

Load Cell Pole Barrier #1 Force (Y)
Load Cell Pole Barrier #2 Force (Y)
Load Cell Pole Barrier #3 Force (Y)
Load Cell Pole Barrier #4 Force (Y)
Load Cell Pole Barrier #5 Force (Y)
Load Cell Pole Barrier #6 Force (Y)
Load Cell Pole Barrier #7 Force (Y)
Load Cell Pole Barrier #8 Force (Y)







APPENDIX C
ATD CONFIGURATION AND PERFORMANCE VERIFICATION DATA

APPENDIX C

Pre-Test ATD Qualification and Performance Verification

SID-IIs Small Side Impact ATD, Left Side Configuration

S/N: 299

ATD Serial No.: 299

Test Date: 2024-11-08

Tested Parameter	Units	Spec Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.9	Pass
Laboratory Relative Humidity	%	10	70	42	Pass
A - Sitting Height	mm	772	788	779	Pass
B - Shoulder Pivot Height	mm	437	453	450	Pass
C - Hpoint Height	mm	79	89	85	Pass
D - H Point From Seatback	mm	141	151	149	Pass
E - Shoulder Pivot From Backline	mm	97	107	103	Pass
F - Thigh Clearance	mm	119	135	123	Pass
G - Head Breadth	mm	140	148	143	Pass
H - Head Back From Backline	mm	40	46	44	Pass
I - Head Depth	mm	178	188	181	Pass
J - Head Circumference	mm	541	551	546	Pass
K - Buttock To Knee Length	mm	514	540	526	Pass
L - Popliteal Height	mm	343	369	358	Pass
K - Knee Pivot To Floor Height	mm	392	409	403	Pass
N - Buttock Popliteal Length	mm	416	442	431	Pass
O - Chest Depth W/O Jacket	mm	195	211	207	Pass
P - Foot Length	mm	216	232	223	Pass
Q - Hip Breadth (W/Pelvic Plugs)	mm	313	323	316	Pass
R - Arm Length	mm	249	259	252	Pass
S - Knee Joint To Seatback	mm	477	493	483	Pass
V - Shoulder Width	mm	341	357	346	Pass
W - Foot Width	mm	78	94	85	Pass
Y - Chest Circumference W/Jacket	mm	851	881	865	Pass
Z - Waist Circumference	mm	761	791	772	Pass
				Overall Test Results	Pass

Technician:





J. Coronel

Approved By:



J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	18.9	25.6	21.1	Pass
Laboratory Relative Humidity	%	10	70	38	Pass
Peak Resultant Acceleration	g	115.0	137.0	123.0	Pass
Peak Head Ax	g	-15.0	15.0	-9.1	Pass
Oscillations After Main Pulse	%	0.0	15.0	2.4	Pass
Is Acceleration Unimodal?	Yes/No	Yes		Yes	Pass
			Overall Test Results	Pass	



Technician:

J. Coronel


J. Coronel

Approved By:

J. Hernandez

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.1	Pass
Laboratory Relative Humidity	%	10	70	40	Pass
Pendulum Velocity	m/s	5.51	5.63	5.60	Pass
Pendulum Decel at 10 ms	m/s	-2.80	-2.20	-2.57	Pass
Pendulum Decel at 15 ms	m/s	-4.10	-3.30	-3.83	Pass
Pendulum Decel at 20 ms	m/s	-5.40	-4.40	-5.11	Pass
Pendulum Decel at 25 ms	m/s	-6.10	-5.40	-5.80	Pass
Pendulum Decel from 25-100 ms	m/s	-6.20	-5.50	-6.01/-5.72	Pass
Peak "D" Plane Rotation	deg	-81.0	-71.0	-77.2	Pass
Time of Peak "D" Plane Rotation	ms	50.0	70.0	60.6	Pass
Peak Occ. Condyle Moment	Nm	36.0	44.0	41.5	Pass
Time of Moment Decay to 0 Nm	ms	102.0	126.0	112.9	Pass
				Overall Test Results	Pass






Technician:


J. Coronel

Approved By:

J. Hernandez



Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.3	Pass
Laboratory Relative Humidity	%	10	70	38	Pass
Impactor Velocity	m/s	4.20	4.40	4.33	Pass
Peak Shoulder Dy	mm	28.0	37.0	31.1	Pass
Peak Upper Spine (T1) Ay	g	17.0	22.0	19.7	Pass
Peak Impactor Ax	g	-18.0	-13.0	-15.7	Pass
Overall Test Results					Pass





Technician:

J. Coronel

Approved By:

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.2	Pass
Laboratory Relative Humidity	%	10	70	39	Pass
Impactor Velocity	m/s	6.60	6.80	6.72	Pass
Peak Shoulder Dy	mm	31.0	40.0	36.8	Pass
Peak Upper Rib Dy	mm	25.0	32.0	28.1	Pass
Peak Middle Rib Dy	mm	30.0	36.0	33.1	Pass
Peak Lower Rib Dy	mm	32.0	38.0	35.6	Pass
Peak Upper Spine (T1) Ay	g	34.0	43.0	39.3	Pass
Peak Lower Spine (T12) Ay	g	29.0	37.0	34.6	Pass
Peak Impactor Ax	g	-36.0	-30.0	-32.8	Pass
Overall Test Results				Pass	Pass



Technician:

J. Coronel



J. Coronel

Approved By:

J. Hernandez

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.5	Pass
Laboratory Relative Humidity	%	10	70	39	Pass
Impactor Velocity	m/s	4.20	4.40	4.29	Pass
Peak Thorax Rib Upper Dy	mm	32.0	40.0	36.7	Pass
Peak Thorax Rib Middle Dy	mm	39.0	45.0	41.6	Pass
Peak Thorax Rib Lower Dy	mm	35.0	43.0	39.0	Pass
Peak Spine Upper T1 Ay	g	13.0	17.0	15.0	Pass
Peak Spine Lower T12 Ay	g	7.0	11.0	8.3	Pass
Peak Impactor Ax	g	-18.0	-14.0	-15.8	Pass
Overall Test Results					Pass



Technician:

J. Coronel



J. Coronel

Approved By:

J. Hernandez

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.6	Pass
Laboratory Relative Humidity	%	10	70	40	Pass
Impactor Velocity	m/s	4.20	4.40	4.33	Pass
Peak Upper Abdomen Rib Dy	mm	36.0	47.0	41.6	Pass
Peak Lower Abdomen Rib Dy	mm	33.0	44.0	36.9	Pass
Peak Lower Spine T12 Ay	mm	9.0	14.0	11.6	Pass
Peak Impactor Ax	g	-16.0	-12.0	-15.0	Pass
Overall Test Results					Pass



Technician: J. Coronel



Approved By: J. Hernandez

ATD Serial No.: 299

Test Date: 2024-11-08

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.4	Pass
Laboratory Relative Humidity	%	10	70	40	Pass
Impactor Velocity	m/s	6.60	6.80	6.73	Pass
Peak Acetabulum Fy	kN	3.60	4.30	4.05	Pass
Pelvis Ay after 6ms	g	34.0	42.0	34.8	Pass
Peak Impactor Ax	g	-47.0	-38.0	-43.1	Pass
Overall Test Results					Pass

Pelvis Plug S/N: 16513



Technician:

J. Coronel

J. Coronel

Approved By:

J. Hernandez

J. Hernandez

ATD Serial No.: 299

SID-IIs Small Side Impact ATD
Pelvis Acetabulum Impact

Test Date: 2024-11-08

Pelvis Plug S/N: 16513



SID-IIs Pelvis Plug Certification Test

Plug S/N 16513

Test Number 23297

Report Number 23354

Test Date 7/14/2022 1:42:25 PM


	Test Results	Spec Min	Spec Max
Force @ 0.5 mm (N)	256	50	600
Force @ 1.5 mm (N)	1,038	850	1,400
Force @ 2.5 mm (N)	1,355	1,306	1,618
Force @ 3.0 mm (N)	1,423	1,361	1,673

Testing Machine STM-20 5965542
Load Cell S/N (FI360947), Units (LBS) 1000

Crosshead Speed (mm / min) or Rate 12.7
Extension or Position Measured by XHD_100 (XHD100)

Notes:

Force (-N) vs Extension (-mm)



Operator 16513

Part Number 180-4450

Template No 107 14-Jul-22

SACO Research

By: DC

Date: 7/14/22

SACO Research 41735 Elm St, #401 Murrieta, CA 92562 Tel 310-694-2082 FAX



ATD Serial No.: 299

Test Date: 2024-11-10

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.4	Pass
Laboratory Relative Humidity	%	10	70	37	Pass
Impactor Velocity	m/s	4.20	4.40	4.30	Pass
Peak Iliac Fy	kN	4.10	5.10	4.74	Pass
Peak Pelvis Ay	g	28.0	39.0	34.7	Pass
Peak Impactor Ax	g	-45.0	-36.0	-42.1	Pass
Overall Test Results					Pass

Pelvis Plug S/N: 16490 *

* Plug is not impacted and remains certified



Technician:

J. Coronel

J. Coronel

Approved By:

J. Hernandez

J. Hernandez

APPENDIX C
Post-Test ATD Qualification and Performance Verification
SID-IIs Small Side Impact ATD, Left Side Configuration
S/N: 299

ATD Serial No.: 299

Test Date: 2024-12-05


Tested Parameter	Units	Spec Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.9	Pass
Laboratory Relative Humidity	%	10	70	30	Pass
A - Sitting Height	mm	772	788	782	Pass
B - Shoulder Pivot Height	mm	437	453	450	Pass
C - Hpoint Height	mm	79	89	86	Pass
D - H Point From Seatback	mm	141	151	144	Pass
E - Shoulder Pivot From Backline	mm	97	107	104	Pass
F - Thigh Clearance	mm	119	135	128	Pass
G - Head Breadth	mm	140	148	146	Pass
H - Head Back From Backline	mm	40	46	44	Pass
I - Head Depth	mm	178	188	183	Pass
J - Head Circumference	mm	541	551	548	Pass
K - Buttock To Knee Length	mm	514	540	527	Pass
L - Popliteal Height	mm	343	369	357	Pass
K - Knee Pivot To Floor Height	mm	392	409	397	Pass
N - Buttock Popliteal Length	mm	416	442	429	Pass
O - Chest Depth W/O Jacket	mm	195	211	204	Pass
P - Foot Length	mm	216	232	219	Pass
Q - Hip Breadth (W/Pelvic Plugs)	mm	313	323	320	Pass
R - Arm Length	mm	249	259	251	Pass
S - Knee Joint To Seatback	mm	477	493	488	Pass
V - Shoulder Width	mm	341	357	354	Pass
W - Foot Width	mm	78	94	88	Pass
Y - Chest Circumference W/Jacket	mm	851	881	866	Pass
Z - Waist Circumference	mm	761	791	775	Pass
				Overall Test Results	Pass

Technician:





J. Coronel

Approved By:



J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	18.9	25.6	21.4	Pass
Laboratory Relative Humidity	%	10	70	27	Pass
Peak Resultant Acceleration	g	115.0	137.0	123.8	Pass
Peak Head Ax	g	-15.0	15.0	-6.9	Pass
Oscillations After Main Pulse	%	0.0	15.0	2.5	Pass
Is Acceleration Unimodal?	Yes/No	Yes		Yes	Pass
			Overall Test Results	Pass	



Technician:

J. Coronel


J. Coronel

Approved By:

J. Hernandez

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.1	Pass
Laboratory Relative Humidity	%	10	70	43	Pass
Pendulum Velocity	m/s	5.51	5.63	5.58	Pass
Pendulum Decel at 10 ms	m/s	-2.80	-2.20	-2.52	Pass
Pendulum Decel at 15 ms	m/s	-4.10	-3.30	-3.75	Pass
Pendulum Decel at 20 ms	m/s	-5.40	-4.40	-4.93	Pass
Pendulum Decel at 25 ms	m/s	-6.10	-5.40	-5.77	Pass
Pendulum Decel from 25-100 ms	m/s	-6.20	-5.50	-6.01/-5.71	Pass
Peak "D" Plane Rotation	deg	-81.0	-71.0	-75.6	Pass
Time of Peak "D" Plane Rotation	ms	50.0	70.0	59.8	Pass
Peak Occ. Condyle Moment	Nm	36.0	44.0	41.7	Pass
Time of Moment Decay to 0 Nm	ms	102.0	126.0	113.2	Pass
				Overall Test Results	Pass






Technician:

J. Coronel

Approved By:


J. Hernandez



ATD Serial No.: 299

Test Date: 2024-12-05

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.3	Pass
Laboratory Relative Humidity	%	10	70	31	Pass
Impactor Velocity	m/s	4.20	4.40	4.32	Pass
Peak Shoulder Dy	mm	28.0	37.0	31.4	Pass
Peak Upper Spine (T1) Ay	g	17.0	22.0	19.8	Pass
Peak Impactor Ax	g	-18.0	-13.0	-15.5	Pass
Overall Test Results					Pass





Technician:

J. Coronel

Approved By:

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.1	Pass
Laboratory Relative Humidity	%	10	70	31	Pass
Impactor Velocity	m/s	6.60	6.80	6.72	Pass
Peak Shoulder Dy	mm	31.0	40.0	35.5	Pass
Peak Upper Rib Dy	mm	25.0	32.0	28.7	Pass
Peak Middle Rib Dy	mm	30.0	36.0	33.2	Pass
Peak Lower Rib Dy	mm	32.0	38.0	34.7	Pass
Peak Upper Spine (T1) Ay	g	34.0	43.0	37.5	Pass
Peak Lower Spine (T12) Ay	g	29.0	37.0	33.3	Pass
Peak Impactor Ax	g	-36.0	-30.0	-33.7	Pass
Overall Test Results				Pass	Pass





Technician:

J. Coronel

Approved By:

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.6	Pass
Laboratory Relative Humidity	%	10	70	29	Pass
Impactor Velocity	m/s	4.20	4.40	4.32	Pass
Peak Thorax Rib Upper Dy	mm	32.0	40.0	37.6	Pass
Peak Thorax Rib Middle Dy	mm	39.0	45.0	41.2	Pass
Peak Thorax Rib Lower Dy	mm	35.0	43.0	36.5	Pass
Peak Spine Upper T1 Ay	g	13.0	17.0	15.1	Pass
Peak Spine Lower T12 Ay	g	7.0	11.0	8.5	Pass
Peak Impactor Ax	g	-18.0	-14.0	-15.2	Pass
Overall Test Results				Pass	Pass



Technician:

J. Coronel



J. Coronel

Approved By:

J. Hernandez

J. Hernandez

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.7	Pass
Laboratory Relative Humidity	%	10	70	30	Pass
Impactor Velocity	m/s	4.20	4.40	4.29	Pass
Peak Upper Abdomen Rib Dy	mm	36.0	47.0	42.4	Pass
Peak Lower Abdomen Rib Dy	mm	33.0	44.0	36.9	Pass
Peak Lower Spine T12 Ay	mm	9.0	14.0	12.3	Pass
Peak Impactor Ax	g	-16.0	-12.0	-14.9	Pass
Overall Test Results					Pass



Technician:

J. Coronel

J. Coronel

Approved By:

J. Hernandez



J. Hernandez

ATD Serial No.: 299

Test Date: 2024-12-05

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.4	Pass
Laboratory Relative Humidity	%	10	70	30	Pass
Impactor Velocity	m/s	6.60	6.80	6.71	Pass
Peak Acetabulum Fy	kN	3.60	4.30	4.02	Pass
Pelvis Ay after 6ms	g	34.0	42.0	36.8	Pass
Peak Impactor Ax	g	-47.0	-38.0	-43.8	Pass
Overall Test Results					Pass

Pelvis Plug S/N: 17780



Technician:

J. Coronel

J. Coronel

Approved By:

J. Hernandez

J. Hernandez

ATD Serial No.: 299

Test Date: 2024-12-05

Pelvis Plug S/N: 17780



SID-IIs Pelvis Plug Certification Test

Plug S/N 17780

Test Number 25068

Report Number 25125


Test Date 12/11/2022 11:24:40 AM

	Test Results	Spec. Min	Spec. Max
Force @ 0.5 mm (N)	295	50	600
Force @ 1.5 mm (N)	1,199	850	1,400
Force @ 2.5 mm (N)	1,543	1,306	1,618
Force @ 3.0 mm (N)	1,601	1,361	1,673

Testing Machine STM-20 5965542
Load Cell S/N (FI360947), Units (LBS) 1000
Preload Value (-N) 22.24
Crosshead Speed (mm / min) or Rate 12.7
Extension or Position Measured by XHD_100 (XHD100)

Notes:

Force (-N) vs Extension (-mm)



Operator

Part Number 180-4450

Template No 107 11-Dec-22
SACO Research

By: DC Date: 12/11/22

SACO Research 41735 Elm St, #401 Murrieta, CA 92562 Tel 310-694-2082 FAX



ATD Serial No.: 299

Test Date: 2024-12-10

Tested Parameter	Units	Spec. Low	Spec. High	Result	Pass/Fail
Laboratory Temperature	°C	20.6	22.2	21.1	Pass
Laboratory Relative Humidity	%	10	70	28	Pass
Impactor Velocity	m/s	4.20	4.40	4.28	Pass
Peak Iliac Fy	kN	4.10	5.10	4.76	Pass
Peak Pelvis Ay	g	28.0	39.0	34.7	Pass
Peak Impactor Ax	g	-45.0	-36.0	-41.3	Pass
Overall Test Results					Pass

Pelvis Plug S/N: 16490 *

* Plug is not impacted and remains certified



Technician:

J. Coronel

J. Coronel

Approved By:

J. Hernandez

J. Hernandez

APPENDIX D
TEST EQUIPMENT AND INSTRUMENTATION CALIBRATION DATA

Table 1 - Driver ATD Instrumentation

Sensor Location	Sensor S\N	Mfr	Model	Cal Date
Head Acceleration X Primary	P51929	Endevco	7264C-2k	2024-06-05
Head Acceleration Y Primary	P50086	Endevco	7264C-2k	2024-06-05
Head Acceleration Z Primary	P51931	Endevco	7264C-2k	2024-06-05
Head Acceleration X Redundant	P68604	Endevco	7264C-2k	2024-06-05
Head Acceleration Y Redundant	P51934	Endevco	7264C-2k	2024-06-05
Head Acceleration Z Redundant	P58736	Endevco	7264C-2k	2024-06-05
Head Rotation Rate X	ARS7342	DTS	ARS PRO-8k (2kHz)	2024-07-31
Head Rotation Rate Y	ARS7473	DTS	ARS PRO-8k (2kHz)	2024-07-31
Head Rotation Rate Z	ARS7598	DTS	ARS PRO-8k (2kHz)	2024-07-31
Upper Thorax Rib Deflection Y	1143	Servo	08TCI-3725	2024-06-05
Middle Thorax Rib Deflection Y	1075	Servo	08TCI-3725	2024-06-05
Lower Thorax Rib Deflection Y	1213	Servo	08TCI-3725	2024-06-05
Upper Abdomen Rib Deflection Y	1218	Servo	08TCI-3725	2024-06-05
Lower Abdomen Rib Deflection Y	1177	Servo	08TCI-3725	2024-06-05
Lower Spine T12 Acceleration X	P58761	Endevco	7264C-2k	2024-06-06
Lower Spine T12 Acceleration Y	P50077	Endevco	7264C-2k	2024-06-06
Lower Spine T12 Acceleration Z	P58795	Endevco	7264C-2k	2024-06-06
Iliac Wing Impact Side Force Y	278 (Iliac)	R.A. Denton	3228J	2024-05-10
Acetabulum Impact Side Force Y	260 (Acetabulum)	R.A. Denton	3249J	2024-05-10

Table 2 - Vehicle Instrumentation

Sensor Location	Sensor S\N	Mfr	Model	Cal Date
Vehicle CG Ax	M14577	Endevco	758H-2k	2024-08-15
Vehicle CG Ay	M14410	Endevco	758H-2k	2024-08-10
Vehicle CG Az	M14424	Endevco	7264HM6-2k-360	2024-08-10
Left Floor Sill Ay	A254881	MSI	52F-2k	2024-10-02
A-Pillar Sill Ay	M14426	Endevco	7264HM6-2k-360	2024-08-10
A-Pillar Low Ay	M14414	Endevco	7264HM6-2k-360	2024-08-10
A-Pillar Mid Ay	M14425	Endevco	7264HM6-2k-360	2024-08-10
B-Pillar Sill Ay	M11203	Endevco	758H-2k	2024-08-11
B-Pillar Low Ay	M11098	Endevco	758H-2k	2024-08-11
B-Pillar Mid Ay	M11050	Endevco	758H-2k	2024-08-27
Driver Seat Track at H-Point Ay	A356469	MSI	52F-2k	2024-09-24
Engine Top Ax	M13729	Endevco	758H-2k	2024-08-12
Engine Top Ay	M14422	Endevco	7264HM6-2k-360	2024-08-10
Firewall Ay	M11150	Endevco	758H-2k	2024-08-26
Right Roof Ay	M14427	Endevco	758H-2k	2024-08-10
Right Floor Sill Ay	M11130	Endevco	758H-2k	2024-08-28
Rear Floorpan Ax	M14433	Endevco	7264HM6-2k-360	2024-08-10
Rear Floorpan Ay	M14569	Endevco	758H-2k	2024-08-15

Table 3 - Barrier Pole Instrumentation

Sensor Location	Sensor S\N	Mfr	Model	Cal Date
Barrier Pole 01 Fx	46760	Interface	1220FS-50k	2023-11-15
Barrier Pole 02 Fx	132304A	Interface	1220-FS	2023-11-15
Barrier Pole 03 Fx	131211A	Interface	1220-FS	2023-11-15
Barrier Pole 04 Fx	19346	Interface	1220FS-50k	2023-11-15
Barrier Pole 05 Fx	131827A	Interface	1220AF-50k	2023-11-15
Barrier Pole 06 Fx	19322	Interface	1220FS-50k	2023-11-15
Barrier Pole 07 Fx	132302A	Interface	1220-FS	2023-11-15
Barrier Pole 08 Fx	19345	Interface	1220FS-50k	2023-11-15